

Store 1

C04/UPC 22006529/p931

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 C01/P NR/TP RES/OD RES/EVA/INV/MV
 To inspect Vehicle No: _____
 at Workshop No: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S
XXX	

Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SY 88667 Yr Regn: 20/5/15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda C.C. 1497
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 89414 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRHRU1830PP000683
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / SRM / STD A/Rm or
 Tyre Size: F: 215/60R16
 R: 17
 BS / DUN / EXNOVA / GY / FS / LIZA / MG / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 4 mm Rear R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 7/7/22 D.O.I. 8/7/22
 Survey held at Koh Mok
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NR 47, 000
PR-30, 837
NR 16, 163

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.J. (%)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photo

Others

TOTAL

QUOTATION

RAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Highly Marginal: 0000000000
Expressly Not: 0000000000

Services and Study Program

1990 2000 2010 2020 2030

Website: www.honda.com.au

For 24 hours. Residents Assistance: call 0120 461 111

Customer	:	LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 109555
Registration No	:	SCY8866Z
Chassis No	:	MRHRU1830FP000083
Model	:	HRV LX-SIN CVT YM 2015
Owner's Name	:	GOH BWEE CHIEW
Ins Policy No.	:	
Date of Accident	:	7/7/2022

Document No.	: 563122/61939
Date	: 7. Jul 2022
Customer No.	: WZL009
Sys Advisor	: HG SM HAI
Engine No	: L15Z11500087
Date Time	: 7. Jul 2022 1:34:39 PM
Surveyor Name	:
Survey Date	:
Authorisation Date	:



Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BOSUN	SUNDRIES	1	110.00	50	110.00	7.70	117.70
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00	200	250.00	17.50	267.50
BOJSE	SEALANT FOR REAR END PANEL	1	120.00		120.00	8.40	128.40
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	120.00		120.00	8.40	128.40
BOJSE	SEALANT FOR LHR FENDER	1	120.00		120.00	8.40	128.40
BOJSE	SEALANT FOR TAILGATE	1	120.00		120.00	8.40	128.40
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00	200	250.00	17.50	267.50
BMU30A	STRAIGHTEN ALIGN OR RENEW EXHAUST SYSTEM.(N)	1	650.00		650.00	45.50	695.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00	(photo)	650.00	45.50	695.50
BM102D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00	(photo)	650.00	45.50	695.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BM103D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	120.00		120.00	8.40	128.40
BKRP02M	CUT OFF & RENEW RR PANEL.	1	6000.00	5850	6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00	3120	3500.00	245.00	3745.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	580.00	450	580.00	40.60	620.60

Printed on 7/7/2022 1:59:13 PM

Printed on 7/7/2022 1:59:13 PM
This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

GST Amount is calculated from individual line(s).
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.
If the amount is not used at Ksh Motor Co. Sdn. Bhd. it will be refunded.

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation. However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair
Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SCY8866Z
Chassis No : MRHRU1830FP000083
Model : HRV LX-SIN CVT YM 2015
Owner's Name : GOH SWEE CHIEW
Ins Policy No. :
Date of Accident : 7/7/2022

Document No. : SQT22001939 Page 2
Date : 7. Jul 2022
Customer No. : WZL009
Svc Advisor : NG SIN HAI
Engine No : L15Z71000087
Date | Time : 7. Jul 2022 1:34:39 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	650.00		650.00	45.50	695.50
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	520.00		520.00	36.40	556.40
BO-TOW	TOWING SERVICES (MBBS)	1	130.00		130.00	9.10	139.10
BOSUN	REMOVE AND VACUUM SHATTERED GLASSES	1	650.00		650.00	45.50	695.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00		650.00	45.50	695.50
Sum Labor					17790.00	1,245.30	19,035.30
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	1	45.00		45.00	3.15	48.15
39670-T7S-T01	SENSOR UNITPARKING ?	1	291.30	25	218.47	15.29	233.76
39671-T7A-H00	BRACKETPARKING SENSOR UNIT ?	1	4.70	25	3.52	0.25	3.77
39680-TV0-E01ZU	SENSOR ASSY PARKING T99 ?	1	70.90	25	53.17	3.72	56.89
39680-TV0-E01C5	SENSOR ASSYPARKING ?	1	93.70	25	70.27	4.92	75.19
39680-TV0-E11ZN	SENSOR ASSY PARKING T99 ?	1	70.90	25	53.17	3.72	56.89
39680-TV0-E11ZN	SENSOR ASSY PARKING T99 ?	1	70.90	25	53.17	3.72	56.89
39681-T7A-H01ZL	RETAINERPARKING SENSOR ?	2	70.90	25	106.35	7.44	113.79
39683-T0A-Q01ZD	RETAINERPARKING SENSOR ?	2	25.20	25	37.80	2.65	40.45
74940-TR0-003	BUZZER ASSYSMART ?	1	64.10	25	48.07	3.36	51.43
33502-T7A-J01	LAMP UNITR. / OR	1	503.90	25	377.92	26.45	404.37
33552-T7A-J01	LAMP UNITL. / OR	1	503.90	25	377.92	26.45	404.37
34150-T7A-J01	LIGHT ASSY,R.LID / OR	1	287.80	25	215.85	15.11	230.96
34155-T7A-J01	LIGHT ASSYL.LID / OR	1	287.80	25	215.85	15.11	230.96
76700-T7A-003	MOTOR ASSYRR.WINDSHIELD WIPER ?	1	121.30	25	90.97	6.37	97.34
76720-T7A-003	ARM,RR.WIPER / CR	1	45.40	25	34.05	2.38	36.43
76730-T7A-003	BLADEWINDSHIELD WIPER / CR	1	39.70	25	29.77	2.08	31.85
39530-T7M-H01	CAMERA ASSYRR.VIEW ?	1	1110.30	25	832.72	58.29	891.01
68100-T8P-U10ZZ	TAILGATE COMP - OR	1	910.50	25	682.87	47.80	730.67
68210-T5A-023ZZ	HINGE COMP,TAILGATE ✓	2	32.80	25	49.20	3.44	52.64
74440-T7A-003	WEATHERSTRIPTAILGATE / CR1	1	105.20	25	78.90	5.52	84.42
74800-T7A-J01	LOCK ASSYTAILGATE ?	1	90.10	25	67.57	4.73	72.30

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
 300 BEACH ROAD #17-04/07
 THE CONCOURSE
 SINGAPORE 199555
 Registration No : SCY8866Z
 Chassis No : MRHRU1830FP000083
 Model : HRV LX-SIN CVT YM 2015
 Owner's Name : GOH SWEE CHIEW
 Ins Policy No :
 Date of Accident : 7/7/2022

Document No. : SQT22001939
 Date : 7. Jul 2022
 Customer No. : WZL009
 Svc Advisor : NG SIN HAI
 Engine No : L15Z71000087
 Date | Time : 7. Jul 2022 1:34:39 PM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Page 3

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER ?	1	112.30	25	84.22	5.90	90.12
74820-T7J-H01	STAY ASSYR.TAILGATE OPEN X	1	115.50	25	86.62	6.06	92.68
74870-T7J-H01	STAY ASSYL.TAILGATE OPEN X	1	115.50	25	86.62	6.06	92.68
74899-T7A-003	DAMPERTAILGATE DYNAMIC X	1	69.40	25	52.05	3.64	55.69
74900-T8N-Q01ZA	GARNISH ASSYTAILGATE SPOILER X	1	138.40	25	103.80	7.27	111.07
84431-T8N-T01ZA	LINING ASSYTAILGATE LOWER X	1	102.00	25	76.50	5.36	81.86
84433-T8N-T01ZA	LINING ASSYTAILGATE UPPER X	1	26.90	25	20.17	1.41	21.58
84441-S2K-000ZB	POCKETTAILGATE PULL X	1	16.20	25	12.15	0.85	13.00
84485-T8N-T01ZA	LINING ASSYL.TAILGATE SIDE X	1	16.30	25	12.22	0.86	13.08
75722-T7W-A01	EMBLEMRR. / MC	1	15.20	25	11.40	0.80	12.20
75725-T8N-T00	EMBLEM,RR. I-VTEC / MC	1	16.60	25	12.45	0.87	13.32
73211-T8N-T01	GLASS SET,RR.WINDSHIELD / BR	1	739.80	25	554.85	38.84	593.69
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER / MC	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 / MC	1	9.10	25	6.82	0.48	7.30
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER / MC	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT / MC	1	5.20	25	3.90	0.27	4.17
91501-S70-003	FASTENER BW/SHIELD / MC	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B / MC	2	5.50	25	8.25	0.58	8.83
91536-SS0-J01	FASTENER AW/SHIELD / MC	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N) / MC	2	60.00		120.00	8.40	128.40
34100-T5A-003	LIGHT ASSYLICENSE ?	2	33.90	25	50.85	3.56	54.41
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE / BR	1	189.80	25	142.35	9.96	152.31
33505-T7A-J01	REFLECTOR ASSYR.RR. X	1	178.50	25	133.87	9.37	143.24
33555-T7A-J01	REFLECTOR ASSYL.RR. X	1	178.50	25	133.87	9.37	143.24
71501-T8N-T50	FACERR.BUMPER / CR4	1	463.70	25	347.77	24.34	372.11
71502-T7J-H50ZZ	FACER.RR.BUMPER CORNER / CR4	1	95.30	25	71.47	5.00	76.47
71507-T7J-H50ZZ	FACEL.RR.BUMPER CORNER / CR4	1	95.30	25	71.47	5.00	76.47
71593-T7A-000	SPACER,R.RR.BUMPER SIDE / BR	1	18.00	25	13.50	0.95	14.45
71598-T7A-000	SPACER,L.RR.BUMPER SIDE / BR	1	18.00	25	13.50	0.95	14.45

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.


Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE
SINGAPORE 199555
Registration No : SCY8866Z
Chassis No : MRHRU1830FP000083
Model : HRV LX-SIN CVT YM 2015
Owner's Name : GOH SWEE CHIEW
Ins Policy No :
Date of Accident : 7/7/2022

Document No. : SQT22001939
Date : 7. Jul 2022
Customer No. : WZL009
Svc Advisor : NG SIN HAI
Engine No : L15Z71000087
Date | Time : 7. Jul 2022 1:34:39 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 4

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
90107-S9V-A01	BOLTRR.BUMPER STOPPER X	2	4.70	25	7.05	0.49	7.54
91505-TM8-003	CLIP,BUMPER / AC	8	2.30	25	13.80	0.97	14.77
63320-T8N-T00ZZ	GUTTER COMPR.RR. ?	1	163.90	25	122.92	8.60	131.52
63720-T8N-T00ZZ	GUTTER COMPL.RR. ?	1	163.90	25	122.92	8.60	131.52
66100-T8N-T00ZZ	PANEL COMPR. / 00	1	470.20	25	352.65	24.69	377.34
84400-T7A-J01ZA	COVER COMPTONNEAU X CR4 ?	1	140.30	25	105.22	7.37	112.59
84610-T8N-T01ZA	BASE COMPR.TRUNK SIDE LINING X	1	149.70	25	112.27	7.86	120.13
84640-T8N-T01ZA	LINING ASSYRR.PANEL / CRu	1	66.60	25	49.95	3.50	53.45
84660-T8N-T01ZA	BASE COMPL.TRUNK SIDE LINING X	1	149.70	25	112.27	7.86	120.13
04655-T7Y-T00ZZ	PANEL SET RR.FLOOR / 00	1	577.70	25	433.27	30.33	463.60
65513-T7J-H00ZZ	STIFFENERRR.JACK UP X	1	44.50	25	33.37	2.34	35.71
65750-T5B-300ZZ	CROSSMEMBER COMPR.FLOOR X	1	95.50	25	71.62	5.01	76.63
65770-T9A-T00ZZ	CROSSMEMBER COMP,RR.FLOOR RR. X	1	128.30	25	96.22	6.74	102.96
72841-SH3-315	OILSHEET / K	3	43.40	25	97.65	6.84	104.49
84521-T8N-T01ZA	BOARD ASSYTRUNK FLOOR X ?	1	106.00	25	79.50	5.57	85.07
84550-T7W-A00	BOX COMPTRUNK FLOOR ?	1	134.70	25	101.02	7.07	108.09
74410-T7M-H01	PROTECTORR.RR.WHEEL ARCH ?	1	172.10	25	129.07	9.03	138.10
74450-T7M-H01	PROTECTORL.RR.WHEEL ARCH ?	1	172.10	25	129.07	9.03	138.10
74552-T8R-T00	FENDERR.RR INNER X	1	86.60	25	64.95	4.55	69.50
74592-T8R-T00	FENDERL.RR INNER X	1	86.60	25	64.95	4.55	69.50
91501-T2A-003	CLIPINNER FENDER X	6	0.40	25	1.80	0.13	1.93
91501-TR0-003	CLIP,INNER FENDER X	8	2.80	25	16.80	1.18	17.98
Sum Item					8342.13	583.94	8,926.07
BO-V-KOOL-RWS	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN.	1	300.00 / K		300.00	21.00	321.00
Sum Ext. Service					300.00	21.00	321.00

Survey By _____

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

HONDA

QUOTATION

GST Reg No: A299999223
Company Ref No: 85000119923

KAH MOTOR CO. SDN. BHD.
1, LALANG, AT THE CHANGAI FREEWAYS (Bukit)

1, LALANG, AT THE CHANGAI FREEWAYS (Bukit)

1, LALANG, AT THE CHANGAI FREEWAYS (Bukit)

1, LALANG, AT THE CHANGAI FREEWAYS (Bukit)

Website: www.honda.com.sg

1, LALANG, AT THE CHANGAI FREEWAYS (Bukit)

Insurance : LONMAC INSURANCE BHD
NO BEACH ROAD #17-04/07
THE CANNEX@SE
SINGAPORE 100555
Registration No : SCY88882
Chassis No : MHH00118307XXXXX83
Model : HRV LX-SIN CVT YM 2015
Owner's Name : GON SWEE CHEW
Ins Policy No :
Date of Accident : 7/7/2022

Document No. : B0122001939
Date : 7 Jul 2022
Customer No. : WZL009
Sve Adviser : NG SIN HAI
Engine No : L15Z71000087
Date | Time : 7 Jul 2022 1:34:39 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 5

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
Date & Time							
Excess							
Status							
Signature							
Total Amount					26,432.13	1,850.24	28,282.37
Total (Inclusive of GST)							28,282.37

Store (LKK)
8/7/22, 2:00pm

WZL
P/P
L BIL
12 Lys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.