



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|---|---------------------------|--------------------------|-------------|---|
| Customer | : LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 | Document No. | : SQT22001939 | Page | 1 |
| Registration No | : SCY8866Z | Date | : 7. Jul 2022 | | |
| Chassis No | : MRHRU1830FP000083 | Customer No. | : WZL009 | | |
| Model | : HRV LX-SIN CVT YM 2015 | Svc Advisor | : NG SIN HAI | | |
| Owner's Name | : GOH SWEE CHIEW | Engine No | : L15Z71000087 | | |
| Ins Policy No. | : | Date Time | : 7. Jul 2022 1:34:39 PM | | |
| Date of Accident | : 7/7/2022 | Surveyor Name | : | | |
| | | Survey Date | : | | |
| | | Authorisation Date | : | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|----------|--|-----|------------|--------|---------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH: | | | | | | |
| BOSUN | SUNDRIES | 1 | 110.00 | | 110.00 | 7.70 | 117.70 |
| BA02R | REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | 250.00 | | 250.00 | 17.50 | 267.50 |
| BOJSE | SEALANT FOR REAR END PANEL | 1 | 120.00 | | 120.00 | 8.40 | 128.40 |
| BOJSE | SEALANT FOR REAR FLOOR PANEL | 1 | 120.00 | | 120.00 | 8.40 | 128.40 |
| BOJSE | SEALANT FOR LHR FENDER | 1 | 120.00 | | 120.00 | 8.40 | 128.40 |
| BOJSE | SEALANT FOR TAILGATE | 1 | 120.00 | | 120.00 | 8.40 | 128.40 |
| BML02I | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER | 1 | 250.00 | | 250.00 | 17.50 | 267.50 |
| BMU30A | STRAIGHTEN ALIGN OR RENEW EXHAUST SYSTEM.(N) | 1 | 650.00 | | 650.00 | 45.50 | 695.50 |
| BMF00D | RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N) | 1 | 650.00 | | 650.00 | 45.50 | 695.50 |
| BMI02D | REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK | 1 | 650.00 | | 650.00 | 45.50 | 695.50 |
| BKTG02R | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | 1 | 650.00 | | 650.00 | 45.50 | 695.50 |
| BMI03D | REMOVE & INSTALL REAR COMPARTMENT LININGS | 1 | 650.00 | | 650.00 | 45.50 | 695.50 |
| BG02D | REMOVE & INSTALL RR. WINDSCREEN.(N) | 1 | 650.00 | | 650.00 | 45.50 | 695.50 |
| BODAMKIT | WINDSCREEN DAM KIT. | 1 | 120.00 | | 120.00 | 8.40 | 128.40 |
| BKRP02M | CUT OFF & RENEW RR PANEL. | 1 | 6000.00 | | 6000.00 | 420.00 | 6420.00 |
| BP06R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | 1 | 3500.00 | | 3500.00 | 245.00 | 3745.00 |
| BKOT00R | REMOVE & RENEW RR FLOOR INSULATOR.(N) | 1 | 580.00 | | 580.00 | 40.60 | 620.60 |

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|---|---------------------------|--------------------------|-------------|---|
| Customer | : LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 | Document No. | : SQT22001939 | Page | 2 |
| Registration No | : SCY8866Z | Date | : 7. Jul 2022 | | |
| Chassis No | : MRHRU1830FP000083 | Customer No. | : WZL009 | | |
| Model | : HRV LX-SIN CVT YM 2015 | Svc Advisor | : NG SIN HAI | | |
| Owner's Name | : GOH SWEE CHIEW | Engine No | : L15Z71000087 | | |
| Ins Policy No. | : | Date Time | : 7. Jul 2022 1:34:39 PM | | |
| Date of Accident | : 7/7/2022 | Surveyor Name | : | | |
| | | Survey Date | : | | |
| | | Authorisation Date | : | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|---|-----|------------|--------|-----------------|-----------------|------------------|
| BKBU01R | REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA | 1 | 650.00 | | 650.00 | 45.50 | 695.50 |
| BP00R | APPLY BODY UNDERSIDE COATING (N). | 1 | 520.00 | | 520.00 | 36.40 | 556.40 |
| BO-TOW | TOWING SERVICES (MBBS) | 1 | 130.00 | | 130.00 | 9.10 | 139.10 |
| BOSUN | REMOVE AND VACUUM SHATTERED GLASSES | 1 | 650.00 | | 650.00 | 45.50 | 695.50 |
| BC012R | RESET VEHICLE SMART ENTRY SYSTEM | 1 | 650.00 | | 650.00 | 45.50 | 695.50 |
| Sum Labor | | | | | 17790.00 | 1,245.30 | 19,035.30 |
| BO-NUM-COMP-L | NUMBER PLATE WITH CASING-L(N) | 1 | 45.00 | | 45.00 | 3.15 | 48.15 |
| 39670-T7S-T01 | SENSOR UNITPARKING | 1 | 291.30 | 25 | 218.47 | 15.29 | 233.76 |
| 39671-T7A-H00 | BRACKETPARKING SENSOR UNIT | 1 | 4.70 | 25 | 3.52 | 0.25 | 3.77 |
| 39680-TV0-E01ZU | SENSOR ASSY PARKING T99 | 1 | 70.90 | 25 | 53.17 | 3.72 | 56.89 |
| 39680-TV0-E01C5 | SENSOR ASSYPARKING | 1 | 93.70 | 25 | 70.27 | 4.92 | 75.19 |
| 39680-TV0-E11ZN | SENSOR ASSY PARKING T99 | 1 | 70.90 | 25 | 53.17 | 3.72 | 56.89 |
| 39680-TV0-E11ZN | SENSOR ASSY PARKING T99 | 1 | 70.90 | 25 | 53.17 | 3.72 | 56.89 |
| 39681-T7A-H01ZL | RETAINERPARKING SENSOR | 2 | 70.90 | 25 | 106.35 | 7.44 | 113.79 |
| 39683-T0A-Q01ZD | RETAINERPARKING SENSOR | 2 | 25.20 | 25 | 37.80 | 2.65 | 40.45 |
| 74940-TR0-003 | BUZZER ASSYSMART | 1 | 64.10 | 25 | 48.07 | 3.36 | 51.43 |
| 33502-T7A-J01 | LAMP UNITR. | 1 | 503.90 | 25 | 377.92 | 26.45 | 404.37 |
| 33552-T7A-J01 | LAMP UNITL. | 1 | 503.90 | 25 | 377.92 | 26.45 | 404.37 |
| 34150-T7A-J01 | LIGHT ASSY,R.LID | 1 | 287.80 | 25 | 215.85 | 15.11 | 230.96 |
| 34155-T7A-J01 | LIGHT ASSYL.LID | 1 | 287.80 | 25 | 215.85 | 15.11 | 230.96 |
| 76700-T7A-003 | MOTOR ASSYRR.WINDSHIELD WIPER | 1 | 121.30 | 25 | 90.97 | 6.37 | 97.34 |
| 76720-T7A-003 | ARM,RR.WIPER | 1 | 45.40 | 25 | 34.05 | 2.38 | 36.43 |
| 76730-T7A-003 | BLADEWINDSHIELD WIPER | 1 | 39.70 | 25 | 29.77 | 2.08 | 31.85 |
| 39530-T7M-H01 | CAMERA ASSYRR.VIEW | 1 | 1110.30 | 25 | 832.72 | 58.29 | 891.01 |
| 68100-T8P-U10ZZ | TAILGATE COMP | 1 | 910.50 | 25 | 682.87 | 47.80 | 730.67 |
| 68210-T5A-023ZZ | HINGE COMP,TAILGATE | 2 | 32.80 | 25 | 49.20 | 3.44 | 52.64 |
| 74440-T7A-003 | WEATHERSTRIPTAILGATE | 1 | 105.20 | 25 | 78.90 | 5.52 | 84.42 |
| 74800-T7A-J01 | LOCK ASSYTAILGATE | 1 | 90.10 | 25 | 67.57 | 4.73 | 72.30 |

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|---|---------------------------|--------------------------|-------------|---|
| Customer | : LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 | Document No. | : SQT22001939 | Page | 3 |
| Registration No | : SCY8866Z | Date | : 7. Jul 2022 | | |
| Chassis No | : MRHRU1830FP000083 | Customer No. | : WZL009 | | |
| Model | : HRV LX-SIN CVT YM 2015 | Svc Advisor | : NG SIN HAI | | |
| Owner's Name | : GOH SWEE CHIEW | Engine No | : L15Z71000087 | | |
| Ins Policy No. | : | Date Time | : 7. Jul 2022 1:34:39 PM | | |
| Date of Accident | : 7/7/2022 | Surveyor Name | : | | |
| | | Survey Date | : | | |
| | | Authorisation Date | : | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|------------------------------|-----|------------|--------|--------|---------------|------------------|
| 74810-T4N-H01 | SWITCH ASSYTAILGATE OPENER | 1 | 112.30 | 25 | 84.22 | 5.90 | 90.12 |
| 74820-T7J-H01 | STAY ASSYR.TAILGATE OPEN | 1 | 115.50 | 25 | 86.62 | 6.06 | 92.68 |
| 74870-T7J-H01 | STAY ASSYL.TAILGATE OPEN | 1 | 115.50 | 25 | 86.62 | 6.06 | 92.68 |
| 74899-T7A-003 | DAMPERTAILGATE DYNAMIC | 1 | 69.40 | 25 | 52.05 | 3.64 | 55.69 |
| 74900-T8N-Q01ZA | GARNISH ASSYTAILGATE SPOILER | 1 | 138.40 | 25 | 103.80 | 7.27 | 111.07 |
| 84431-T8N-T01ZA | LINING ASSYTAILGATE LOWER | 1 | 102.00 | 25 | 76.50 | 5.36 | 81.86 |
| 84433-T8N-T01ZA | LINING ASSYTAILGATE UPPER | 1 | 26.90 | 25 | 20.17 | 1.41 | 21.58 |
| 84441-S2K-000ZB | POCKETTAILGATE PULL | 1 | 16.20 | 25 | 12.15 | 0.85 | 13.00 |
| 84485-T8N-T01ZA | LINING ASSYL.TAILGATE SIDE | 1 | 16.30 | 25 | 12.22 | 0.86 | 13.08 |
| 75722-T7W-A01 | EMBLEMRR. | 1 | 15.20 | 25 | 11.40 | 0.80 | 12.20 |
| 75725-T8N-T00 | EMBLEM,RR. I-VTEC | 1 | 16.60 | 25 | 12.45 | 0.87 | 13.32 |
| 73211-T8N-T01 | GLASS SET,RR.WINDSHIELD | 1 | 739.80 | 25 | 554.85 | 38.84 | 593.69 |
| 73214-T7J-H01 | RUBBER CR.WINDSHIELD DAMPER | 1 | 19.30 | 25 | 14.47 | 1.01 | 15.48 |
| 73226-SZW-000 | DAMPERSTD 5X5 | 1 | 9.10 | 25 | 6.82 | 0.48 | 7.30 |
| 73254-T7J-H01 | RUBBER CL.WINDSHIELD DAMPER | 1 | 19.30 | 25 | 14.47 | 1.01 | 15.48 |
| 76711-T6A-003 | CAPPIVOT | 1 | 5.20 | 25 | 3.90 | 0.27 | 4.17 |
| 91501-S70-003 | FASTENER BW/SHIELD | 4 | 5.30 | 25 | 15.90 | 1.11 | 17.01 |
| 91502-S70-003 | FASTENER B | 2 | 5.50 | 25 | 8.25 | 0.58 | 8.83 |
| 91536-SS0-J01 | FASTENER AW/SHIELD | 2 | 3.80 | 25 | 5.70 | 0.40 | 6.10 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) | 2 | 60.00 | | 120.00 | 8.40 | 128.40 |
| 34100-T5A-003 | LIGHT ASSYLICENSE | 2 | 33.90 | 25 | 50.85 | 3.56 | 54.41 |
| 74890-T7A-J12ZR | GARNISH ASSYRR.LICENSE | 1 | 189.80 | 25 | 142.35 | 9.96 | 152.31 |
| 33505-T7A-J01 | REFLECTOR ASSYR.RR. | 1 | 178.50 | 25 | 133.87 | 9.37 | 143.24 |
| 33555-T7A-J01 | REFLECTOR ASSYL.RR. | 1 | 178.50 | 25 | 133.87 | 9.37 | 143.24 |
| 71501-T8N-T50 | FACERR.BUMPER | 1 | 463.70 | 25 | 347.77 | 24.34 | 372.11 |
| 71502-T7J-H50ZZ | FACER.RR.BUMPER CORNER | 1 | 95.30 | 25 | 71.47 | 5.00 | 76.47 |
| 71507-T7J-H50ZZ | FACEL.RR.BUMPER CORNER | 1 | 95.30 | 25 | 71.47 | 5.00 | 76.47 |
| 71593-T7A-000 | SPACER,R.RR.BUMPER SIDE | 1 | 18.00 | 25 | 13.50 | 0.95 | 14.45 |
| 71598-T7A-000 | SPACER,L.RR.BUMPER SIDE | 1 | 18.00 | 25 | 13.50 | 0.95 | 14.45 |

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|---|---------------------------|--------------------------|-------------|---|
| Customer | : LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 | Document No. | : SQT22001939 | Page | 4 |
| Registration No | : SCY8866Z | Date | : 7. Jul 2022 | | |
| Chassis No | : MRHRU1830FP000083 | Customer No. | : WZL009 | | |
| Model | : HRV LX-SIN CVT YM 2015 | Svc Advisor | : NG SIN HAI | | |
| Owner's Name | : GOH SWEE CHIEW | Engine No | : L15Z71000087 | | |
| Ins Policy No. | : | Date Time | : 7. Jul 2022 1:34:39 PM | | |
| Date of Accident | : 7/7/2022 | Surveyor Name | : | | |
| | | Survey Date | : | | |
| | | Authorisation Date | : | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|------------------|---|-----|------------|--------|----------------|---------------|------------------|
| 90107-S9V-A01 | BOLTRR.BUMPER STOPPER | 2 | 4.70 | 25 | 7.05 | 0.49 | 7.54 |
| 91505-TM8-003 | CLIP,BUMPER | 8 | 2.30 | 25 | 13.80 | 0.97 | 14.77 |
| 63320-T8N-T00ZZ | GUTTER COMPR.RR. | 1 | 163.90 | 25 | 122.92 | 8.60 | 131.52 |
| 63720-T8N-T00ZZ | GUTTER COMPL.RR. | 1 | 163.90 | 25 | 122.92 | 8.60 | 131.52 |
| 66100-T8N-T00ZZ | PANEL COMPRR. | 1 | 470.20 | 25 | 352.65 | 24.69 | 377.34 |
| 84400-T7A-J01ZA | COVER COMPTONNEAU | 1 | 140.30 | 25 | 105.22 | 7.37 | 112.59 |
| 84610-T8N-T01ZA | BASE COMPR.TRUNK SIDE LINING | 1 | 149.70 | 25 | 112.27 | 7.86 | 120.13 |
| 84640-T8N-T01ZA | LINING ASSYRR.PANEL | 1 | 66.60 | 25 | 49.95 | 3.50 | 53.45 |
| 84660-T8N-T01ZA | BASE COMPL.TRUNK SIDE LINING | 1 | 149.70 | 25 | 112.27 | 7.86 | 120.13 |
| 04655-T7Y-T00ZZ | PANEL SET RR.FLOOR | 1 | 577.70 | 25 | 433.27 | 30.33 | 463.60 |
| 65513-T7J-H00ZZ | STIFFENERRR.JACK UP | 1 | 44.50 | 25 | 33.37 | 2.34 | 35.71 |
| 65750-T5B-300ZZ | CROSSMEMBER COMPRR.FLOOR | 1 | 95.50 | 25 | 71.62 | 5.01 | 76.63 |
| 65770-T9A-T00ZZ | CROSSMEMBER COMP,RR.FLOOR RR. | 1 | 128.30 | 25 | 96.22 | 6.74 | 102.96 |
| 72841-SH3-315 | OILSHEET | 3 | 43.40 | 25 | 97.65 | 6.84 | 104.49 |
| 84521-T8N-T01ZA | BOARD ASSYTRUNK FLOOR | 1 | 106.00 | 25 | 79.50 | 5.57 | 85.07 |
| 84550-T7W-A00 | BOX COMPTRUNK FLOOR | 1 | 134.70 | 25 | 101.02 | 7.07 | 108.09 |
| 74410-T7M-H01 | PROTECTORR.RR.WHEEL ARCH | 1 | 172.10 | 25 | 129.07 | 9.03 | 138.10 |
| 74450-T7M-H01 | PROTECTORL.RR.WHEEL ARCH | 1 | 172.10 | 25 | 129.07 | 9.03 | 138.10 |
| 74552-T8R-T00 | FENDERR.RR.INNER | 1 | 86.60 | 25 | 64.95 | 4.55 | 69.50 |
| 74592-T8R-T00 | FENDERL.RR.INNER | 1 | 86.60 | 25 | 64.95 | 4.55 | 69.50 |
| 91501-T2A-003 | CLIPINNER FENDER | 6 | 0.40 | 25 | 1.80 | 0.13 | 1.93 |
| 91501-TR0-003 | CLIP,INNER FENDER | 8 | 2.80 | 25 | 16.80 | 1.18 | 17.98 |
| Sum Item | | | | | 8342.13 | 583.94 | 8,926.07 |
| BO-V-KOOL-RWS | SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN. | 1 | 300.00 | | 300.00 | 21.00 | 321.00 |
| Sum Ext. Service | | | | | 300.00 | 21.00 | 321.00 |

Survey By

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

| | | | | | |
|-------------------------|---|---------------------------|--------------------------|-------------|---|
| Customer | : LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 | Document No. | : SQT22001939 | Page | 5 |
| Registration No | : SCY8866Z | Date | : 7. Jul 2022 | | |
| Chassis No | : MRHRU1830FP000083 | Customer No. | : WZL009 | | |
| Model | : HRV LX-SIN CVT YM 2015 | Svc Advisor | : NG SIN HAI | | |
| Owner's Name | : GOH SWEE CHIEW | Engine No | : L15Z71000087 | | |
| Ins Policy No. | : | Date Time | : 7. Jul 2022 1:34:39 PM | | |
| Date of Accident | : 7/7/2022 | Surveyor Name | : | | |
| | | Survey Date | : | | |
| | | Authorisation Date | : | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-------------|-------------|-----|------------|--------|--------------------------|---------------|------------------|
| Date & Time | | | | | Total Amount | 26,432.13 | 1,850.24 |
| Excess | | | | | | | 28,282.37 |
| Status | | | | | Total (Inclusive of GST) | | <u>28,282.37</u> |
| Signature | | | | | | | |

Printed on 7/7/2022 1:59:13 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|---|
| Date of Submission | 07/07/2022 14:05 (SGT) |
| Reported by | Driver |
| Date of Accident | 07/07/2022 11:20 (SGT) |
| Exact Location of Accident | Near CTE, Ang Mo Kio North Flyover, Singapore |
| Additional Location Information | - |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------|
| Vehicle Registration Number | SCY8866Z |
|-----------------------------|----------|

INSURED/POLICYHOLDER

| | |
|--------------------------|----------------------|
| Is company? | No |
| Name Of Registered Owner | GOH SWEE CHIEW |
| NRIC No | SXXXX758A |
| Email Address | KYTAN8866@GMAIL.COM |
| Mobile Phone No | (Phone) +65-98259369 |
| Alternative Phone No | - |

VEHICLE PARTICULARS

| | |
|--|---------------------------|
| Manufacturer | Honda |
| Model | Hr-v |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | - |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 1500 |

INSURANCE COMPANY

| | |
|-----------------------------------|--------------------------------------|
| Name of Insurance Company | Tokio Marine Insurance Singapore Ltd |
| Policy Number / Cover Note Number | - |

DRIVER

| | |
|----------------|---------------|
| Name of Driver | TAN KOK YEANG |
| NRIC No | SXXXX265H |
| Date Of Birth | 24/12/1943 |
| Occupation | Indoor |

| | |
|--|-----------------------|
| Date Of Driving Pass | 28/01/1981 |
| Driving experience | 41 YEARS AND 6 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-96381612 |
| Alt. Phone Number | |
| Email Address | KYTAN8866@GMAIL.COM |
| Address | S |
| Address complement | |
| Postcode | |
| Is the driver the policyholder? | No |
| If No, Relationship of the Driver with the Insured | Spouse |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | |
| Insurance Company of Other Vehicle Owned by Driver | |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------|--------------------------|
| Type of Accident | Collision - Head to Rear |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 2 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |
| Translator's name | |
| Translator's ID | |
| Translator's phone number | |
| Translator's email | |
| Original language used in the statement | |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | |

CIRCUMSTANCES OF ACCIDENT

REFER

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------|--------------------|
| Vehicle Registration Number | YP6899D |
| Vehicle Manufacturer | |
| Vehicle Model | |
| Vehicle Variant | |
| Vehicle Colour | |
| Vehicle Category | Commercial vehicle |
| Name of Driver | |
| Contact Number | |

| | | |
|---|--|--|
| Address | | |
| Address complement | | |
| Postcode | | |
| Insurance Company Name | | |
| Nature Of Damage | | |
| Details of property damaged in accident | | |
| No. Of Passenger (Including Driver) | | |

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

I was traveling along CTE towards SLE.

I was going to exit to Hwy 101 Ave 5.
at the slip road

While waiting for the oncoming traffic to clear,
vehicle B hit onto the rear of my vehicle A.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel