

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 08.07.2022

TO : **INDIA** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLW9366Y**
MODEL : **HYUNDAI ELANTRA**
DATE OF ACCIDENT : 07.07.2022
TIME OF ACCIDENT : 18:30HRS

KM HD841CMJ4645461
Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehnd</i>	1	\$ 757.40	\$ 757.40 495
2	REAR BUMPER DIFFUSER <i>Rehnd</i>	1	\$ 996.30	\$ 996.30 305
3	REAR BUMPER REFLECTOR <i>LH amhd</i>	2	\$ 72.50	\$ 145.00 72.50
4	REAR BUMPER RETAINER <i>Re m</i>	2	\$ 57.30	\$ 114.60
5	REAR BUMPER REINFORCEMENT <i>Denthd</i>	1	\$ 494.80	\$ 494.80 329
6	REAR BUMPER BRACKET <i>Best</i>	5	\$ 35.40	\$ 177.00 90
7	REAR BUMPER SIDE INNER GARNISH <i>LH torn</i>	2	\$ 98.60	\$ 197.20 98.60
8	REAR FENDER INNER TRIM <i>3 am</i>	2	\$ 437.50	\$ 875.00
9	REAR FENDER INNER COWLING	1	\$ 146.80	\$ 146.80
10	BOOTLID <i>Buckhd</i>	1	\$ 1,782.10	\$ 1,782.10 ✓
11	BOOTLID LAMP <i>Re m</i>	2	\$ 664.20	\$ 1,328.40
12	BOOTLID LOGO <i>2 am</i>	1	\$ 59.60	\$ 59.60
13	BOOTLID EMBLEM 'ELANTRA'	1	\$ 62.80	\$ 62.80
14	BOOTLID EMBLEM 'GLS'	1	\$ 53.20	\$ 53.20
15	BOOTLID REVERSE CAMERA <i>Re m</i>	1	\$ 875.40	\$ 875.40
16	BOOTLID HINGE <i>2</i>	2	\$ 94.30	\$ 188.60
17	BOOTLID STOPPER <i>Re m</i>	2	\$ 19.20	\$ 38.40
18	BOOTLID INSULATOR	1	\$ 179.80	\$ 179.80
19	BOOTLID TOP LOCK <i>Denthd</i>	1	\$ 166.70	\$ 166.70
20	BOOTLID LOWER LOCK <i>Re m</i>	1	\$ 19.10	\$ 19.10
21	BOOTLID WEATHER STRIP <i>ht</i>	1	\$ 152.60	\$ 152.60
22	TAILLAMP <i>amhd</i>	2	\$ 876.80	\$ 1,753.60 1196
23	REAR END PANEL <i>Denthd</i>	1	\$ 569.40	\$ 569.40
24	REAR END PANEL TOP GARNISH <i>Rehnd</i>	1	\$ 142.30	\$ 142.30

TO : **INDIA** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLW9366Y**
 MODEL : **HYUNDAI ELANTRA**
 DATE OF ACCIDENT : 07.07.2022
 TIME OF ACCIDENT : 18:30HRS

5574.80
 4459.84

TOTAL PRICE	\$	11,276.10
LESS 20%	\$	2,255.22
SUB TOTAL PRICE	\$	9,020.88

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER EXHAUST COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	REAR BUMPER SIDE INNER GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
5	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
6	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
7	BOOT LID INSULATOR CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
8	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
9	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
10	REAR END PANEL SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
11	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 1,020.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	850
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	850
3	TUFF COAT	\$ 250.00	80
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	80
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE	\$ 80.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	X
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	20 ✓
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X

340

TO : **INDIA** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLW9366Y**
MODEL : **HYUNDAI ELANTRA**
DATE OF ACCIDENT : 07.07.2022
TIME OF ACCIDENT : 18:30HRS

11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

TOTAL

4830

2070

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,040.88
TOTAL LABOUR COST : \$ 4,830.00
TOTAL REPAIR COST : \$ 14,870.88

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian L
L/s 08/07/22

06 Days

Total: 686984

n/s: 5.5K

5.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: