

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

07/07/2022

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1

Veh # :- GBD858G

Veh Model :- MITSUBISHI L200 TRITON DOUBL

Estimate# :- CK423601

Claim # :-

ACC. Date :- 06/07/22

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	FRONT BONNET / DD	1	PC	520.00	520.00 /
2.	FRONT SUPPORT PANEL / DD	1	PC	580.00	580.00 /
3.	FRONT HEADLAMP LH / OR	1	PC	670.00	670.00 /
4.	FRONT BUMPER / OR	1	PC	650.00	650.00 /
5.	FRONT BUMPER SIDE RETAINER BRACKET LH / MIS	1	PC	28.00	28.00 /
6.	FRONT BUMPER SIDE SUPPORT PANEL LH / X M	1	PC	165.00	165.00 /
7.	FRONT BUMPER FOG LAMP ASSY LH / DD	1	PC	295.00	295.00 /
8.	FRONT BUMPER FOG LAMP FINISHER COVER LH / MIS	1	PC	110.00	110.00 /
9.	FRONT WIPER TANK / CRU	1	PC	85.00	85.00 /
10.	FRONT FENDER LH / DD	1	PC	275.00	275.00 /
11.	FRONT FENDER LAMP LH / OR	1	PC	38.00	38.00 /
12.	FRONT FENDER INNER LINER LH (FRONT) / MIS	1	PC	65.00	65.00 /
13.	FRONT FENDER LINER LH (REAR) / OR	1	PC	85.00	85.00 /
14.	FRONT TYRE LH / Tn (50%) (SN) BT	1	PC	320.00	320.00 /
15.	FRONT LOWER ARM LH / X M	1	PC	380.00	380.00 /
16.	FRONT UPPER ARM LH / X M	1	PC	360.00	360.00 /
17.	FRONT ABSORBER LH / X M	1	PC	165.00	165.00 /
18.	FRONT KNUCKLE ARM LH / X M	1	PC	520.00	520.00 /
19.	FRONT WHEEL BEARING LH / X M	1	PC	260.00	260.00 /
20.	FRONT STABILIZER BAR / X M	1	PC	295.00	295.00 /
21.	FRONT STABILIZER BAR LINK LH / X M	1	PC	92.00	92.00 /
22.	FRONT DOOR LH / DD	1	PC	780.00	780.00 /
23.	REAR DOOR LH / DD	1	PC	650.00	650.00 /
24.	REAR QUATER PANEL LH - REPAIR / X R	1	PC		
25.	CHASSIS MEMBER LH - REPAIR	1	PC		
26.	FRONT WHEEL HOUSE LH - REPAIR	1	PC		

LIST TOTAL S\$

15% COST PLUS S\$

7,388.00

1,108.20

8,496.20

SPECIAL NET ITEMS :

1.	FRONT GRILLE CLIPS / X M	1	SET	30.00	30.00
2.	FRONT BUMPER CLIPS / X M	1	SET	40.00	40.00
3.	FRONT FENDER LINER CLIPS LH / X M	1	SET	50.00	50.00
4.	FRONT TYRE TUBE VALVE LH / X M	1	PC	12.00	12.00

SPECIAL NET TOTAL S\$

132.00

LABOUR :

TO REMOVE, REPLACE, REPAIR, REFIT FRONT
SUSPENSION ARM LH, FRONT ABSORBER,
FRONT KNUCKLE ARM, FRONT UPPER ARM,
STABILIZER BAR, DRIVE SHAFT & ETC

200.00 /

TO HYDRAULICALLY JUCK & REALIGN CHASIS FRAME
LH & ETC. BACK TO ORIGINAL CONDITION

280.00

TO REMOVE & REPLACE, REFIT FRONT RADIATOR

bigSAFE

Estimate

07/07/2022

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 The Concourse
SINGAPORE 199555.

Attention :- XA025

Page # :- 1 145905
Veh # :- GBD858G
Veh Model :- MITSUBISHI L200 TRITON DOUBL
Estimate# :- CK423601
Claim # :-
ACC. Date :- 06/07/22
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg
Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088664-2

No.	Description	Qty	U.Price	Amounts S\$
	AIRCOND CONDENSOR, AIRCOND COOLING PIPE, AIRCOND LIQUID TUBE & ETC. TO EFFECT REPLACE OF FRONT SUPPORT PANEL ASSY			50 - 120.00
	TO REMOVE & REPLACE, REPAIR, READJUST, CHISEL AT ACCIDENT AREAS SUCH AS FRONT BONNET, BUMPER, SUPPORT PANEL, FRONT WHEEL HOUSE LH, FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, REAR QUATER PANEL LH & ETC			1400 - 1,600.00
	TO CHECK WIRING & ELECTRICAL SYSTEM			30 - 80.00
	TO WHEEL ALIGNMENT & BALANCING			60 - 80.00
	TO REFILL AIRCOND GAS & VACUUM			100.00/
	TO SUPPLY PAINT & FURNISHING MATERIAL AT FRONT BONNET, FRONT FENDER LH, FRONT BUMPER FRONT WHEEL HOUSE LH, CHASEL MEMBER FRONT DOOR LH, REAR DOOR LH, REAR QUATER PANEL LH & ETC			1400 / 1800 1,600.00
	LABOUR TOTAL S\$			3490 4,060.00

= 10,370.40

Store (LKK)
8/7/22, 11.3

E. & O.E
ON-M AL
EYPER 7
L/S

NON-TAX AMOUNT S
AMOUNT S\$ 12,688.20
GST @ 7 % 888.17
AMOUNT DUE S\$ 13,576.37

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultancy hereby certify
the Repairer of the vehicle.
• To survey before repair.
• To display damage report to the customer.
• Parts prices are set by the manufacturer.
• Third party survey is required for insurance claim.
• No illegal modification.
• Supplementary items must be approved by the customer.
• To get final approval from insurance company.

biSAFE

Acknowledged by Repairer

Signature:

Date:

M AL Ly
10 dy 5