



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0536/2022/JT
DATE : 28-Jun-22
WIP : 30652

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 04/07/2022.

YOUR INSURED VEH NO : SMN 2711 R

CHINA TAIPING INSURANCE (S) PTE LTD

105 CECIL STREET

#19-00 THE OCTAGON

SINGAPORE 069534

Attn: Ms Angie - Motor Claims Dept/ Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Hi Adrian
3 days - ok - Johnny Boo
22-Nov-22

OWNER'S NAME : MR. TAN ZE YU
ADDRESS : 55 WEST COAST RD
#12-01
SINGAPORE 127365
TELEPHONE : HP +65 97373092
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210128536
VEHICLE NO : **SJK 1128 H**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 28/10/2021
ENGINE NO : CZD C47062
CHASSIS NO : WAUZZZF38M1147604
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Jun-22
PLACE OF ACCIDENT : ALONG ALEXANDRA ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJK 1128 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$ 800.00
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.	\$	2,000.00	\$ 800.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	4,152.00	\$ 2,152.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJK 1128 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,738.00	
2	REAR BUMPER FIXING PARTS	1	\$ 220.00	
3	REAR BUMPER SPOILER	1	\$ 510.00	\$ 510.00
4	REAR BUMPER TOWING EYE	1	\$ 48.00	
5	REAR BUMPER BRACKET	1	\$ 53.00	
6	BOOT LID CONTROL UNIT	1	\$ 454.00	
7	TAILGATE SENSOR LINE	1	\$ 228.00	
8	AERIAL FOR KESSY	1	\$ 79.00	
9	REAR LIGHT REFLECTOR - LH / RH	2	\$ 92.00	
10	REAR BUMPER REINFORCEMENT BEAM	1	\$ 693.00	
11	REAR BUMPER HOLDING STRAP - CENTER	1	\$ 120.00	
12	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 142.00	
13	REAR PARKING AID SENSOR	2	\$ 530.00	
14	REAR PARKING AID SENSOR SEAL RING	4	\$ 10.00	
15	REAR BUMPER WIRING SET	1	\$ 449.00	
16	REAR WHEEL ARCH COVER - LH / RH	2	\$ 566.00	\$ 565.00
17	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS			\$ 6,282.00	\$ 1,075.00
TOTAL LABOUR CHARGES			\$ 4,152.00	\$ 2,152.00
GRAND TOTAL			\$ 10,434.00	\$ 3,227.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bi-01/11/22



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT