

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
Mr Benjamin Tay Weiren 126 Pending Road #04-298 Singapore 670126 Contact No Mobile: 97860606	<table> <tr> <td>Cust No/Name</td><td>/Mr Benjamin Tay Weiren</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMV7085P / 16/10/202</td></tr> <tr> <td>Date In/Mileage</td><td>04/07/2022/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF1416ML5075803</td></tr> <tr> <td>Engine No</td><td>G4FGKH740336</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A L S116</td></tr> <tr> <td>Colour/Trim</td><td>SWP SNOW WHITE PEAR/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Mr Benjamin Tay Weiren	Reg No/Reg Date	SMV7085P / 16/10/202	Date In/Mileage	04/07/2022/ 0	Chassis No	KNAF1416ML5075803	Engine No	G4FGKH740336	Make/Model	KIA/CERATO 1.6 A L S116	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK
Cust No/Name	/Mr Benjamin Tay Weiren														
Reg No/Reg Date	SMV7085P / 16/10/202														
Date In/Mileage	04/07/2022/ 0														
Chassis No	KNAF1416ML5075803														
Engine No	G4FGKH740336														
Make/Model	KIA/CERATO 1.6 A L S116														
Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	05/07/2022/ 17:07	BLK	282 / Kevin Leong	53827			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1280.00
REPLACE FRT BUMPER, BONNET, FRT WIPER COWLING COVER & AFFECTED AREA								
E PNT98000								1100.00
PAINT WORK ON FRONT BUMPER & BONNET								
E PNT88000								300.00
REPLACE ON FRONT WINDSCREEN GLASS								
M SUNDRY								80.00
TO APPLY FRONT WINDSCREEN GLASS SEALANT								
M SUNDRY								220.00
TO SUPPLY FRONT WINDSCREEN SOLAR FILM								
E PNT88000								320.00
REPAIR ON TOP ROOF PANEL & BOTH TOP ROOF MOULDING								
E PNT98000								550.00
PAINT WORK ON TOP ROOF PANEL								
A 52900099								640.00
REPLACE ON ROOF LINING INCLUDING INNER 'C' PILLAR TRIM								
E PNT88000								1600.00
REPLACE REAR BOOT								
REPAIR ON REAR BUMPER & BODY KIT								
E PNT88000								300.00
REPLACE REAR WINDSCREEN GLASS								
M SUNDRY								80.00
TO APPLY REAR WINDSCREEN SEALANT								
M SUNDRY								220.00
TO SUPPLY REAR WINDSCREEN GLASS SOLAR FILM								
E PNT88000								180.00
TO TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL								
E PNT88000								160.00
TO VACUUM & CLEAN OF DEBRIS								
M SUNDRY								580.00
TO SUPPLY CAM RECORDER SET								
E PNT98000								1375.00
PAINT WORK ON REAR BUMPER, BOOT & BODY KIT								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
Mr Benjamin Tay Weiren 126 Pending Road #04-298 Singapore 670126 Contact No Mobile: 97860606	<table> <tr> <td>Cust No/Name</td><td>/Mr Benjamin Tay Weiren</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMV7085P / 16/10/202</td></tr> <tr> <td>Date In/Mileage</td><td>04/07/2022/ 0</td></tr> <tr> <td>Chassis No</td><td>KNAF1416ML5075803</td></tr> <tr> <td>Engine No</td><td>G4FGKH740336</td></tr> <tr> <td>Make/Model</td><td>KIA/CERATO 1.6 A L S116</td></tr> <tr> <td>Colour/Trim</td><td>SWP SNOW WHITE PEAR/ WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Mr Benjamin Tay Weiren	Reg No/Reg Date	SMV7085P / 16/10/202	Date In/Mileage	04/07/2022/ 0	Chassis No	KNAF1416ML5075803	Engine No	G4FGKH740336	Make/Model	KIA/CERATO 1.6 A L S116	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK
Cust No/Name	/Mr Benjamin Tay Weiren														
Reg No/Reg Date	SMV7085P / 16/10/202														
Date In/Mileage	04/07/2022/ 0														
Chassis No	KNAF1416ML5075803														
Engine No	G4FGKH740336														
Make/Model	KIA/CERATO 1.6 A L S116														
Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	05/07/2022/ 17:07	BLK	282 / Kevin Leong	53827			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2240.00
REPLACE REAR RH FENDER, ALL DOOR MOULDING WITH DOOR GLASS, BOTH WING MIRROR ASSY								
E PNT88000								1600.00
REPAIR ON ALL DOORS, BOTH FRONT FENDER, REAR LH FENDER & TOP LH 'B' PILLAR								
E PNT88000								640.00
REPLACE REAR BOTH QUATER GLASS								
M SUNDRY								80.00
TO APPLY REAR BOTH QUATER GLASS SEALANT								
M SUNDRY								240.00
TO SUPPLY BOTH REAR QUATER GLASS SOLAR FILM								
M SUNDRY								300.00
TO APPLY BODY SEALANT ON AFFECTED AREA								
M SUNDRY								720.00
TO SUPPLY ALL 4 DOORS GLASS SOLAR FILM								
E PNT88000								320.00
REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								
E PNT88000								320.00
REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR								
E PNT88000								120.00
REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR								
M SUNDRY								200.00
PERFORM RUST PREVENTION								
A 54900099								120.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								50.00
TO SUPPLY C & C EMBLEM								
M SUNDRY								50.00
SUNDRIES								
M SUNDRY								250.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Benjamin Tay Weiren	Cust No/Name /Mr Benjamin Tay Weiren
126 Pending Road	Reg No/Reg Date SMV7085P / 16/10/202
#04-298	Date In/Mileage 04/07/2022/ 0
Singapore 670126	Chassis No KNAF1416ML5075803
Contact No Mobile: 97860606	Engine No G4FGKH740336
	Make/Model KIA/CERATO 1.6 A L S116
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	05/07/2022/ 17:07	BLK	282 / Kevin Leong	53827		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
TO PROCEED FULL CAR POLISHING							
E PNT98000							1100.00
PAINT WORK ON BOTH REAR FENDER							
E PNT98000							200.00
PAINT WORK ON BOTH SIDE MIRROR COVERS							
E PNT98000							2200.00
PAINT WORK ON ALL 4 DOORS							
E PNT98000							1100.00
PAINT WORK ON BOTH FRONT FENDER PANEL							
E PNT98000							550.00
PAINT WORK ON LH TOP 'B' PILLAR							
M LAMP ASSY-HEAD,LH				1.00	1078.00	00.00	1078.00
M LAMP ASSY-HEAD,RH				1.00	1078.00	00.00	1078.00
M BLADE ASSY-WIPER,DRIVER				1.00	60.00	00.00	60.00
M BLADE ASSY-WIPER,PASSEGER				1.00	43.00	00.00	43.00
M COVER ASSY-COWL TOP				1.00	247.00	00.00	247.00
M GLASS-WINDSHIELD				1.00	821.00	00.00	821.00
M MOULDING-WINDSHIELD GLASS				1.00	77.00	00.00	77.00
M COVER-AFTER SERIVCE,LH				1.00	11.00	00.00	11.00
M COVER-AFTER SERIVCE,RH				1.00	11.00	00.00	11.00
M MOULDING ASSY-ROOF,RH				1.00	43.00	00.00	43.00
M MOULDING ASSY-ROOF,LH				1.00	43.00	00.00	43.00
M HEADLINING ASSY				1.00	823.00	00.00	823.00
M TRIM ASSY-PACKAGE TRAY				1.00	399.00	00.00	399.00
M TRIM ASSY-RR PILLAR RH				1.00	38.00	00.00	38.00
M TRIM ASSY-RR PILLAR LH				1.00	38.00	00.00	38.00
M GLASS ASSY-REAR WINDOW				1.00	616.00	00.00	616.00
M COVER-RR BUMPER FOG LAMP,LH				1.00	19.00	00.00	19.00
M COVER-RR BUMPER FOG LAMP,RH				1.00	19.00	00.00	19.00
M LAMP ASSY-SIDE T/SIGNAL,LH				1.00	201.00	00.00	201.00
M LAMP ASSY-SIDE T/SIGNAL,RH				1.00	201.00	00.00	201.00
M PANEL ASSY-TRUNK LID				1.00	1491.00	00.00	1491.00
M LAMP ASSY-REAR COMB OUTSIDE,LH				1.00	402.00	00.00	402.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Benjamin Tay Weiren	Cust No/Name /Mr Benjamin Tay Weiren
126 Pending Road	Reg No/Reg Date SMV7085P / 16/10/202
#04-298	Date In/Mileage 04/07/2022/ 0
Singapore 670126	Chassis No KNAF1416ML5075803
Contact No Mobile: 97860606	Engine No G4FGKH740336
	Make/Model KIA/CERATO 1.6 A L S116
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	05/07/2022/ 17:07	BLK	282 / Kevin Leong	53827
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASSY-REAR COMB OUTSIDE,RH		1.00	402.00	00.00	402.00
M LAMP ASSY-REAR COMB INSIDE,LH		1.00	346.00	00.00	346.00
M LAMP ASSY-REAR COMB INSIDE,RH		1.00	346.00	00.00	346.00
M ORNAMENT-KIA NO.115		1.00	38.00	00.00	38.00
M LOGO ASSY-KIA SUB		1.00	32.00	00.00	32.00
M EMBLEM-CERATO		1.00	28.00	00.00	28.00
M PANEL ASSY-QUARTER OUTER,RH		1.00	1861.00	00.00	1861.00
M GLASS & MOULDING ASSY-QUARTER		1.00	252.00	00.00	252.00
M GLASS & MOULDING ASSY-QUARTER		1.00	252.00	00.00	252.00
M MOULDING ASSY-RR DR FRAME,RH		1.00	44.00	00.00	44.00
M MOULDING ASSY-RR DR FRAME,LH		1.00	44.00	00.00	44.00
M W/STRIP ASSY-RR DR BELT O/S LH		1.00	60.00	00.00	60.00
M W/STRIP ASSY-RR DR BELT O/S RH		1.00	60.00	00.00	60.00
M MOULDING ASSY-FRT DR FRAME,LH		1.00	37.00	00.00	37.00
M MOULDING ASSY-FRT DR FRAME,RH		1.00	37.00	00.00	37.00
M W/STRIP ASSY-FR DR BELT O/S LH		1.00	64.00	00.00	64.00
M W/STRIP ASSY-FR DR BELT O/S RH		1.00	64.00	00.00	64.00
M BLACK TAPE-RR DR FRAME RR OTR,		1.00	8.00	00.00	8.00
M BLACK TAPE-RR DR FRAME RR OTR,		1.00	8.00	00.00	8.00
M BLACK TAPE-RR DR FR,LH		1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FR,RH		1.00	13.00	00.00	13.00
M BLACK TAPE-FR DR RR,LH		1.00	13.00	00.00	13.00
M BLACK TAPE-FR DR RR,RH		1.00	13.00	00.00	13.00
M MIRROR ASSY-OUTSIDE RR VIEW,LH		1.00	400.00	00.00	400.00
M MIRROR ASSY-OUTSIDE RR VIEW,RH		1.00	413.00	00.00	413.00
M GLASS ASSY-REAR DOOR,LH		1.00	181.00	00.00	181.00
M GLASS ASSY-REAR DOOR,RH		1.00	181.00	00.00	181.00
M GLASS ASSY-FRONT DOOR,LH		1.00	207.00	00.00	207.00
M GLASS ASSY-FRONT DOOR,RH		1.00	207.00	00.00	207.00

Confirm & accepted by

Nett 35,048.00
 7% GST on 35048.00 2453.36

Total Payable 37,501.36

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.