

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMC 4620P

at Workshop m/s

Specialists

of

Insured:

G3G 8483B

Policy No.

DMPCSNW00138042101

Claims No.

SNM22D004763/02/CSC

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

666k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

1-3.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 348k

Vehicle: IN / OUT

Date:

Person Contacted:

179 24083

Veh No:

SMC 4620P

Yr Regn:

29/06/18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Honda Fit

c.c 1317

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

109981

T/Radio: Insured / Std / NI / NA

Eng/No:

GK31320457

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MOXIS

Front

7

Rear

7

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

7/7/22

D.O.I.

12/7/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 11k.

SD card spoil

No second hand part, workshop went P/P

27/7/22

P/P 11663.04

informed here.

(Red 5608.80, 32%)

29/7/22

P/P 11230.48

reformed here.

(Red 6041.36, 35%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

28/7- typist

Days Of Repair:

8

Resurvey No. of Trip:

3

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format:

Merimen

Lump Sum / I.B.I. (\$

11,663.04

)