

Repair Estimates
Pte Ltd (Co Reg No: 199506045W)
Email: teokeejin@cdge.com.sg

22, 5:19 PM

PAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jul 2022)
Parts: M1-MPV HONDA FREED HYBRID 1.5 G (A) (Catalogue: Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SNC457J/14/07/2022 17:19
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT RH FENDER			
2	1	Chk	*FRT RH FENDER INNER SHIELD	20	0.00	*441.00 F X
3	8		*FRT RH FENDER INNER SHIELD CLIP	20	0.00	*150.00 F X
4	1		*FRT LH FENDER	20	0.00	*31.20 F X
5	1		*FRT LH FENDER INNER SHIELD	20	0.00	*441.00 F
6	8		*FRT LH FENDER INNER SHIELD CLIP	20	0.00	*150.00 F
7	1		*FRT LH FENDER HYBRID BADGE	20	0.00	*31.20 F
8	1	X	*FRT LH QUATER GLASS	20	0.00	*66.00 F
9	1		*FRT LH FENDER LOWER PANEL(OUTER)	20	0.00	*510.00 F X
10	1		*FRT LH FENDER LOWER PANEL(INNER)	20	0.00	*191.00 F
11	1		*FRT LH FENDER LOWER PANELSUPPORT BRACKET	20	0.00	*210.00 F
12	1		*FRT LH RIM 15	20	0.00	*150.00 F
13	1		*FRT LH TYRE9DUNLOP ENASAVE EC300/185/65R15	0	0.00	*401.00 FS
14	1		*FRT LH WHEEL HUB	0	0.00	*250.00 FS
15	1		*FRT LH WHEEL HUB BEARING	20	0.00	*201.00 F
16	1		*FRT LH KUNCKLE ARM	20	0.00	*196.00 F
17	1		*FRT LH LOWER ARM	20	0.00	*351.00 F
18	1		*FRT LH SHOCK ABSORBER	20	0.00	*291.00 F
19	1	X	*FRT LH SHOCK ABSORBER TOP MOUNTING	20	0.00	*350.00 F
20	1	X	*LH STEERING TIE ROD	20	0.00	*48.00 F X
21	1	X	*LH STEERING TIE ROD END	20	0.00	*121.00 F X
22	1		*FRT WINDSCREEN GLASS	20	0.00	*99.00 F X
23	1		*FRT WINDSCREEN GLASS MOULDING	20	0.00	*1,800.00 F
24	1		*SEALANT	20	0.00	*60.00 F
25	1		*INNER SEAL	0	0.00	*40.00 FS
26	1		*ERP BRACKET	0	0.00	*30.00 FS
27	1		*PHV	0	0.00	*26.00 FS
28	1		*AIRBAG CONTROL UNIT	0	0.00	*50.00 FS
29	1		*FRT AIR BAG CRASH SENSOR LH	20	0.00	*854.00 F
30	1		*FRT AIR BAG CRASH SENSOR RH	20	0.00	*104.00 F
31	1		*FRT BUMPER	20	0.00	*104.00 F
32	1		*FRT BUMPER SIDE RETAINER RH	20	0.00	*898.00 F
33	1		*FRT BUMPER SIDE RETAINER LH	20	0.00	*22.00 F
34	10		*FRT BUMPER CLIP	20	0.00	*22.00 F
35	1		*FRT NUMBER PLATE	20	0.00	*38.00 F
36	1		*RADIATOR GRILLE	0	0.00	*45.00 FS
37	1	Chk	*FRT BUMPER UPPER AIRDUCT	20	0.00	*982.00 F
38	1		*FRT BUMPER LOWER CENTER GRILLE	20	0.00	*36.00 F
39	1		*FRT BUMPER RH SIDE COVER	20	0.00	*165.00 F
40	1		*FRT BUMPER LH SIDE COVER	20	0.00	*241.00 F
41	1	X	*FRT BUMPER LOWER GRILLE COVER RH	20	0.00	*241.00 F
42	1		*FRT BUMPER LOWER GRILLE COVER LH	20	0.00	*91.00 F
43	1		*FRT BUMPER INFORCEMENT	20	0.00	*89.00 F
				20	0.00	*332.00 F

Part No.	Particulars	%Disc	%Depr	Amount
1	*RH HEADLAMP	20	0.00	*1,454.00 F
45	*RH HEADLAMP LOWER BRACKET	20	0.00	*36.00 F
46	*LH HEADLAMP	20	0.00	*1,454.00 F
47	X *LH HEADLAMP LOWER BRACKET	20	0.00	*36.00 F
48	*WIPER TANK	20	0.00	*90.00 F
49	X *FRT SUPPORT PANEL TOP	20	0.00	*753.00 F
50	*FRT RH FENDER LOWER PANEL(OUTER)	20	0.00	*191.00 F
51	*FRT RH FENDER LOWER PANEL(INNER)	20	0.00	*210.00 F
52	*FRT RH FENDER LOWER SUPPORT BRACKET	20	0.00	*150.00 F
53	*FRT RH FENDER INNER SHIELD	20	0.00	*120.00 F
54	*STEERING WHEEL AIRBAG	20	0.00	*2,400.00 F
55	*STEERING WHEEL AIRBAG CLOCK SPRING	20	0.00	*283.00 F
56	*FRT LH PASSENGER AIRBAG	20	0.00	*3,201.00 F
57	*FRT DASHBOARD	20	0.00	*750.00 F
58	*FRT RH SEAT BELT	20	0.00	*602.00 F
59	*FRT LH SEAT BELT	20	0.00	*602.00 F
60	*REAR RH FENDER	20	0.00	*912.00 F
61	*REAR BUMPER	20	0.00	*950.00 F
62	*REAR RH BUMPER RETAINER	20	0.00	*25.00 F

Franchise part. S-SpcNett.

Sub Total (S\$) 25,168.40
 - List Item Discount on L Items (S\$) 4,865.28
Total Parts (S\$) 20,303.12

ComfortDelGro Engineering Pte Ltd/SNC457/J/14/07/2022 17:19. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

PM
Estimates on Miscellaneous Items

Qty	Particulars	Amount
1	1 OD/TP Case (Insurer)	11.00
Sub Total (S\$)		11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CUT WELD FRT PANEL,JACK STRAIGHTEN FRT CHASSIS,CUT FENDER LOWER PANEL,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	1000 1,300.00
2	TO PUTTY,RESPRAY ON FRT BONNET,FRT BUMPER,BOTH FENDER,CHASSIS FRAME,FRT LH DOOR AND AFFECTED AREAS	New	1750 1,500.00
3	REMOVE RADIATOR AND CONDENSOR TO ASSIST REPAIR AND REPLACE	New	100 150.00
	TO VACCUM AND RECHARGE AIRCON GAS	New	80 80.00
4	TO REMOVE FRT WINDSCREEN GLASS TO ASSIST REPAIR AND REPLACE	New	120 120.00 ✓
6	REMOVE FRT DASHBOARD TO ASSIST REPAIR AND REPLACE	New	250 250.00 ✓
7	TO REPLACE STEERING AIRBAG ,CLOCK SPRING,PASSENGER AIRBAG AND SRS CONTROL UNIT	New	280 400.00
8	TO REMOVE AND REPLACE BOTH FRT SEAL BELT	New	80 200.00
9	TO RESET AND RE-PROGRAM ECU/AIRBAG SYSTEM	New	280 400.00
10	TO CUT WELD ON REAR RH FENDER AND REPLACEMENT.REPLACE REAR BUMPER AND REALIGN AFFECTED AREAS	New	750 1,000.00
11	TO PUTTY,RESPRAY ON RH REAR FENDER ,RR BUMPER AND AFFECTED AREAS	New	500 800.00
12	TO REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR AND REFIT	New	100 150.00
13	TO DISMANTLE FRT LH SUSPENSION TO ASSIST REPAIR AND REPLACE. (RIM,TYRE,KUNCKLE ARM,LOWER ARM,ABSORBER ETC.)	New	200 300.00
14	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	60 100.00
15	TO TUFF KOTE ON REAR AFFECTED AREAS	New	NI 150.00 X
Gross Labour Cost (S\$)			6,900.00



Alt Gr

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Supplementary 1

Vehicle No : SNC457J Case Owner : 0
Make & Model : HONDA FREED Year Manufacture : 0
Chassis No : GB73132638 Engine No : 0
Sales Order : 0 Supplier : 0
Order By : _____ Type of Claim : 0

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	AIR FILTER RESONATOR						
2	FRT BUMPER UNDER RUBBER		<i>CM</i>	\$ 112.00			☒
3	FRT BUMPER TOW COVER		<i>Return</i>	\$ 75.00			☒
4	LH DRIVESHAFT		<i>NI</i>	\$ 15.40			☒
5	FRT LH ABSORBER BEARING		<i>B</i>	\$ 1,105.00			☒
6	<i>Solar Film</i>		<i>NI</i>	\$ 36.70			☒
7			<i>NI</i>	<i>8300-w</i>			☒
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

DelGro Engineering Pte Ltd
Generate

07/2022 17:19. Not valid without Refers
Merimen e-Claims

20 0.00 *91.00F
20 0.00 *89.00F
20 0.00 *332.00F