

	Part No.	Particulars		%Disc	%Depr	Amount	
	1	*RH HEADLAMP	Cut	20	0.00	*1,454.00 F	✓
45	1	*RH HEADLAMP LOWER BRACKET	Cut	20	0.00	*36.00 F	✓
46	1	*LH HEADLAMP	my cm	20	0.00	*1,454.00 F	✓
47	1	X*LH HEADLAMP LOWER BRACKET		20	0.00	*36.00 F	?
48	1	*WIPER TANK	my cm	20	0.00	*90.00 F	✓
49	1	X*FRT SUPPORT PANEL TOP		20	0.00	*753.00 F	?
50	1	*FRT RH FENDER LOWER PANEL(OUTER)	R	20	0.00	*191.00 F	✓
51	1	*FRT RH FENDER LOWER PANEL(INNER)	R	20	0.00	*210.00 F	X
52	1	*FRT RH FENDER LOWER SUPPORT BRACKET	R	20	0.00	*150.00 F	X
53	1	*FRT RH FENDER INNER SHIELD	Sn	20	0.00	*120.00 F	✓
54	1	*STEERING WHEEL AIRBAG	Burn	20	0.00	*2,400.00 F	✓
55	1	*STEERING WHEEL AIRBAG CLOCK SPRING	Sn	20	0.00	*283.00 F	✓
56	1	*FRT LH PASSENGER AIRBAG	Burn	20	0.00	*3,201.00 F	✓
57	1	*FRT DASHBOARD	Tn	20	0.00	*750.00 F	✓
58	1	*FRT RH SEAT BELT	Tn	20	0.00	*602.00 F	✓
59	1	*FRT LH SEAT BELT	Tn	20	0.00	*602.00 F	✓
60	1	*REAR RH FENDER	R	20	0.00	*912.00 F	✓
61	1	*REAR BUMPER	R	20	0.00	*950.00 F	X
62	1	*REAR RH BUMPER RETAINER	R	20	0.00	*25.00 F	X

franchise part. S=SpcNett.

Sub Total (\$\$) 25,168.40
 - List Item Discount on L Items (\$\$) 4,865.28

Total Parts (\$\$) 20,303.12

ComfortDelGro Engineering Pte Ltd/SNC457J/14/07/2022 17:19. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

TO: Kenneth

Parts = 20555.20
 + Supp = 3168.80
 = 23724.00

-20% 4744.80
 = 18979.20

+ Sn 590.00
 = 19569.20

+ Lebar 4970.00
 = 24539.20

-20% 4907.84
 = 19631.36

L/S = 19500.00

Rushy 20/10/22

11975

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jul 2022)

Parts: M1-MPV HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SNC457J/14/07/2022 17:19

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT RH FENDER	20	0.00	*441.00 F ✓
2	1	CRK -	*FRT RH FENDER INNER SHIELD	20	0.00	*150.00 F ✓
3	8		*FRT RH FENDER INNER SHIELD CLIP	20	0.00	*31.20 F ✓
4	1		*FRT LH FENDER	20	0.00	*441.00 F ✓
5	1		*FRT LH FENDER INNER SHIELD	CM 20	0.00	*150.00 F ✓
6	8		*FRT LH FENDER INNER SHIELD CLIP	CM 20	0.00	*31.20 F ✓
7	1		*FRT LH FENDER HYBRID BADGE	20	0.00	*66.00 F ✓
8	1	X	*FRT LH QUATER GLASS	20	0.00	*510.00 F ?
9	1		*FRT LH FENDER LOWER PANEL(OUTER)	R 20	0.00	*191.00 F ✓
10	1		*FRT LH FENDER LOWER PANEL(INNER)	R 20	0.00	*210.00 F ✓
11	1		*FRT LH FENDER LOWER PANELSUPPORT BRACKET	R 20	0.00	*150.00 F ✓
12	1		*FRT LH RIM 15	CM 0	0.00	*401.00 FS ✓
13	1		*FRT LH TYRE9DUNLOP ENASAVE EC300/185/65R15	Follow Pn 0	0.00	*250.00 FS
14	1		*FRT LH WHEEL HUB	R 20	0.00	*201.00 F ✓
15	1		*FRT LH WHEEL HUB BEARING	CM 20	0.00	*196.00 F ✓
16	1		*FRT LH KUNCKLE ARM	R 20	0.00	*351.00 F ✓
17	1		*FRT LH LOWER ARM	R 20	0.00	*291.00 F ✓
18	1		*FRT LH SHOCK ABSORBER	R 20	0.00	*350.00 F ✓
19	1	X	*FRT LH SHOCK ABSORBER TOP MOUNTING	20	0.00	*48.00 F ?
20	1	X	*LH STEERING TIE ROD	20	0.00	*121.00 F ?
21	1	X	*LH STEERING TIE ROD END	20	0.00	*99.00 F ?
22	1		*FRT WINDSCREEN GLASS	CM 20	0.00	*1,800.00 F ✓
23	1		*FRT WINDSCREEN GLASS MOULDING	CM 20	0.00	*60.00 F ✓
24	1		*SEALANT	CM 0	0.00	*40.00 FS ✓
25	1		*INNER SEAL	CM 0	0.00	*30.00 FS ✓
26	1		*ERP BRACKET	CM 0	0.00	*26.00 FS ✓
27	1		*PHV	CM 0	0.00	*50.00 FS ✓
28	1		*AIRBAG CONTROL UNIT	CM 20	0.00	*854.00 F ✓
29	1		*FRT AIR BAG CRASH SENSOR LH	CM 20	0.00	*104.00 F ✓
30	1		*FRT AIR BAG CRASH SENSOR RH	CM 20	0.00	*104.00 F ✓
31	1		*FRT BUMPER	CM 20	0.00	*898.00 F ✓
32	1		*FRT BUMPER SIDE RETAINER RH	CM 20	0.00	*22.00 F ✓
33	1		*FRT BUMPER SIDE RETAINER LH	CM 20	0.00	*22.00 F ✓
34	10		*FRT BUMPER CLIP	CM 20	0.00	*38.00 F ✓
35	1		*FRT NUMBER PLATE	CM 0	0.00	*45.00 FS ✓
36	1		*RADIATOR GRILLE	CM 20	0.00	*982.00 F ✓
37	1	CRK -	*FRT BUMPER UPPER AIRDUCT	20	0.00	*36.00 F ?
38	1		*FRT BUMPER LOWER CENTER GRILLE	CM 20	0.00	*165.00 F ✓
39	1		*FRT BUMPER RH SIDE COVER	CM 20	0.00	*241.00 F ✓
40	1		*FRT BUMPER LH SIDE COVER	CM 20	0.00	*241.00 F ✓
41	1	X	*FRT BUMPER LOWER GRILLE COVER RH	20	0.00	*91.00 F ?
42	1		*FRT BUMPER LOWER GRILLE COVER LH	CM 20	0.00	*89.00 F ✓
43	1		*FRT BUMPER INFORCEMENT	R 20	0.00	*332.00 F ✓

Estimates on Miscellaneous Items

Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO CUT WELD FRT PANEL,JACK STRAIGHTEN FRT CHASSIS,CUT FENDER LOWER PANEL,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	1000	1,300.00
2	TO PUTTY,RESPRAY ON FRT BONNET,FRT BUMPER,BOTH FENDER,CHASSIS FRAME,FRT LH DOOR AND AFFECTED AREAS	New	1250	1,500.00
3	REMOVE RADIATOR AND CONDENSOR TO ASSIST REPAIR AND REPLACE TO VACCUM AND RECHARGE AIRCON GAS	New	100	150.00
		New		80.00
1	TO REMOVE FRT WINDSCREEN GLASS TO ASSIST REPAIR AND REPLACE	New		120.00 ✓
6	REMOVE FRT DASHBOARD TO ASSIST REPAIR AND REPLACE	New		250.00 ✓
7	TO REPLACE STEERING AIRBAG ,CLOCK SPRING,PASSENGER AIRBAG AND SRS CONTROL UNIT	New	280	400.00
8	TO REMOVE AND REPLACE BOTH FRT SEAL BELT	New	80	200.00
9	TO RESET AND RE-PROGRAM ECU/AIRBAG SYSTEM	New	280	400.00
10	TO CUT WELD ON REAR RH FENDER AND REPLACEMENT.REPLACE REAR BUMPER AND REALIGN AFFECTED AREAS	New	750	1,000.00
11	TO PUTTY,RESPRAY ON RH REAR FENDER ,RR BUMPER AND AFFECTED AREAS	New	500	800.00
12	TO REMOVE INTERIOR UPHOLSTERY TO ASSIST REPAIR AND REFIT	New	100	150.00
13	TO DISMANTLE FRT LH SUSPENSION TO ASSIST REPAIR AND REPLACE. (RIM,TYRE,KUNCKLE ARM,LOWER ARM,ABSORBER ETC.)	New	200	300.00
14	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	60	100.00
15	TO TUFF KOTE ON REAR AFFECTED AREAS	New	25	150.00 X

Gross Labour Cost (\$\$)

6,900.00

1 ComfortDelGro Engineering Pte Ltd/SNC457J/14/07/2022 17:19. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 29 Aug 2022)**Parts:** M1-MPV HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SNC457J/29/08/2022 12:13**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR FILTER RESONATOR	20	0.00	*112.00 F
2	1		*FRT BUMPER UNDER RUBBER	20	0.00	*75.00 F
3	1		*FRT BUMPER TOW COVER	20	0.00	*15.40 F
4	1		*LH DRIVESHAFT	20	0.00	*1,105.00 F
5	1		*FRT WINDSCREEN SOLAR FILM	0	0.00	*300.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 1,607.40

- List Item Discount on L Items (\$\$) 261.48

Total Parts (\$\$) 1,345.92

ComfortDelGro Engineering Pte Ltd/SNC457J/29/08/2022 12:13. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Sep 2022)**Parts:** M1-MPV HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SNC457J/27/09/2022 11:17**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*AIR INTAKE RESONATOR	0.00	0.00	*112.00 F
2	1		*ENGINE UNDERCOVER	0.00	0.00	*75.00 F
3	1		*FRT BUMPER TOW COVER	0.00	0.00	*15.40 F
4	1		*REAR BUMPER CLIPS	0.00	0.00	*38.00 F
5	1		*LHF DRIVE SHAFT	0.00	0.00	*1,105.00 F
6	1		*STRG RING PIECE 2 OF 2	0.00	0.00	*216.00 F

F=Franchise part.

Total Parts (S\$) **1,561.40**

ComfortDelGro Engineering Pte Ltd/SNC457J/27/09/2022 11:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS