## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three

#04-01 Suntec Tower Three Singapore 038988 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 11 Jul 2022

# **Preliminary Advice**

Vehicle No: SLK8558EAccident Date: 29/06/2022Make: MERCEDES-BENZ C180Policy No.: DMPG22004766

Assignment Date : 08/07/2022 Excess : \$\\$0.00 Date of Inspection : 8/7/2022 Est. Duration of Repair : 28

Inspection At : CYCLE & CARRIAGE INDUSTRIES PL

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	95,793.38
Revised Amount	:S\$	60,295.25
Check Items (Estimated)	:S\$	31,281.09
Total	:S\$	91,576.34

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old value :5\$	New for Old	d Value	:S\$
------------------------	-------------	---------	------

 Pre-Accident Value
 :S\$ 188,000.00

 COE / PARF Rebate
 :S\$ 72,816.00

Salvage Value :S\$

Margin for Repair :S\$ 115,184.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let
	us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .