



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. M8 4500111-X

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 58121
Reg No/Reg Date SLK8558E / 22/04/2021
Date In/Mileage / 0
Chassis No W1K2050762R623067X
Engine No 26491580103478
Make/Model MB/C 180
Colour/Trim 028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator				
WN000512	Credit	07/07/2022/ 17:41	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : DMPG22004766 // 29/06/2022								
DRIVE IN/EXCESS : TOW IN 06/07/2022 // TBA								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
S BPNSUB								580.00
1 PC RIGHT FRONT TYRE - 70 (80%)								7650 8640.00
A BPILAB								
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH 960 X 8								4200 4800.00
A BPIRES								
RESPRAY BONNET, FRONT BUMPER, RIGHT FRONT FENDER, RIGHT FRONT CHASSIS, RIGHT FRONT DOOR. 8 X 6 5								0.10 380.00
A BPILAB								
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT								120.00
A BPILAB								
CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT								0.07 1000.00
A BPILAB								
PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMENT. NETT (photo)								? 2400.00
A BPILAB								
REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS								? 2400.00
A BPILAB								
REMOVE AND RE-INSTALL ENGINE ASSY, TRANSMISSION ASSY AND ELECTRONICS TO ASSIST WORKLOAD								0.07 500.00
A BPILAB								
REMOVE / RENEW / REFIT RADIATOR AND CONDENSER, CHECK COOLING SYSTEM AND AIR-CON SYSTEM WITH RE-GAS. NETT								540.00
A BPILAB								

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chunhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111 X

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 58121
Reg No/Reg Date SLK8558E / 22/04/2021
Date In/Mileage / 0
Chassis No W1K2050762R623067X
Engine No 26491580103478
Make/Model MB/C 180
Colour/Trim 028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WN000512	Credit	07/07/2022/ 17:41	YK	395 / Yik Chan Hoe					
					INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT			0.07	560.00 ✓
					A BPILAB RENEW FRONT W/SCREEN				2880 3840.00
					A BPILAB REMOVE & INSTALL INSTRUMENT PANEL				2880.00 ✓
					A BPILAB REMOVE AND REPLACE DRIVER'S AND PASSENGERS' SEAT BELTS AND AIR-BAGS, REPLACE CONTROL UNITS AND RESET 'SRS' SYSTEM				960 1200.00
					A BPILAB REPLACE STEERING WHEEL AND STEERING COLUMN				? 480.00
					A BPILAB TRANSFER MECHANICAL & ELECTRICAL COMPONENTS OVER TO NEW DOOR. NETT				1970 2400.00
					A BPILAB REMOVE AND REFIT ABR PUMP, TO BLEED AND RESET SYSTEM.				
					A BPILAB REMOVE AND REFIT PIPINGS AND WIRINGS TO ASSIST WORKLOAD. (photo)				
					A BPILAB TO APPLY SEAL SEAM ON PANEL JOINTS				120.00 ✓
					A BPILAB APPLY CAVITY WAX ON AFFECTED AREAS				180.00 ✓
					A BPILAB APPLY SEAL SEAM ON THE INNER PART OF FENDER (W205)				120.00 ✓
					S BPNSUB INSTALL SOLAR FILM ON FRONT W/SCREEN				300.00 ✓
					M BPNSUN 1 PC IU BRACKET				26.00 ✓
					M RIGHT FRONT FENDER / 00	1.00	977.57	00.00	977.57
					M RIGHT FRONT FENDER LINER RR - BR	1.00	145.10	00.00	145.10
					M RIGHT FRONT FENDER LINER FF - BR	1.00	134.11	00.00	134.11
					M FRONT BUMPER - BR	1.00	1674.18	00.00	1674.18
					M FRONT BUMPER LOWER TRIM STRIP - BR	1.00	207.58	00.00	207.58
					M FRONT BASIC CARRIER FOR BUMPER - ?	1.00	207.71	00.00	207.71
					M FRONT BASIC CARRIER FOR BUMPER - ?	1.00	105.08	00.00	105.08
					M FRONT TOP BASIC MOUNTING FOR BUMPER - ?	1.00	106.65	00.00	106.65

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chunhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Page 2 of 5



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 58121
Reg No/Reg Date SLK8558E / 22/04/2021
Date In/Mileage / 0
Chassis No W1K2050762R623067X
Engine No 26491580103478
Make/Model MB/C 180
Colour/Trim 028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WN000512	Credit	07/07/2022/ 17:41	YK	395 / Yik Chan Hoe					
					M FRONT IMPACT ABSORBER - OR	1.00	173.25	00.00	173.25
					M RIGHT FRONT BASIC CARRIER FOR BUMPER - OR	1.00	105.65	00.00	105.65
					M RIGHT FRONT BUMPER GRILLE - CR	1.00	70.49	00.00	70.49
					M FRONT BUMPER COVER, TOWING EYE - MIS	1.00	66.66	00.00	66.66
					M FRONT CPA RADAR SENSOR ?	1.00	1233.72	00.00	1233.72
					M FRONT BUMPER ELECTRICAL WIRING HARNESS ?	1.00	172.34	00.00	172.34
					M RIGHT FRONT DISTANCE SENSOR - OR	1.00	195.43	00.00	195.43
					M FRONT DISTANCE SENSOR ?	2.00	195.43	00.00	390.86
					M PTS SPACER RING - MC	6.00	7.10	00.00	42.60
					M FRONT SRS PRESSURE SENSOR ?	1.00	127.20	00.00	127.20
					M RIGHT FRONT BUMPER MOUNTING RAIL ?	1.00	15.52	00.00	15.52
					M BONNET - OR	1.00	2215.00	00.00	2215.00
					M BONNET MB EMBLEM - MC	1.00	80.58	00.00	80.58
					M RIGHT BONNET HINGE ?	1.00	200.36	00.00	200.36
					M RADIATOR GRILLE AIR DUCT ?	1.00	157.54	00.00	157.54
					M RADIATOR GRILLE ?	1.00	143.15	00.00	143.15
					M LAMP UNIT ?	1.00	3443.48	00.00	3443.48
					M RIGHT HEADLAMP UNIT - OR	1.00	3443.48	00.00	3443.48
					M FRONT SUPPORT PANEL - CR	1.00	851.45	00.00	851.45
					M U-SHAPED STRIKER ?	1.00	104.58	00.00	104.58
					M FRONT SUPPORT PANEL CONSOLE ?	1.00	257.72	00.00	257.72
					M RIGHT FRONT ANGLE BRACKET - MIS	1.00	64.59	00.00	64.59
					M FRONT CROSS MEMBER ?	1.00	473.91	00.00	473.91
					M RIGHT FRONT CROSSMEMBER ABSORBER - OR	1.00	220.02	00.00	220.02
					M RIGHT FRONT BOTTOM ABSORBER ?	1.00	119.28	00.00	119.28
					M RIGHT FRONT STRUT TOWER - OR	1.00	1745.52	00.00	1745.52
					M RIGHT FRONT TOP LONGITUDINAL MEMBER - OR	1.00	515.54	00.00	515.54
					M RIGHT FRONT LONGITUDINAL MEMBER - OR	1.00	375.71	00.00	375.71
					M RIGHT FRONT STRUT TOWER REINFORCEMENT - OR	1.00	170.17	00.00	170.17
					M RIGHT FRONT FENDER BRACKET - OR	1.00	63.52	00.00	63.52
					M RIGHT RUNNING BOARD - CR4	1.00	588.60	00.00	588.60
					M RIGHT RUNNING TRIM MOULDING FF - OR	1.00	127.42	00.00	127.42
					M RIGHT RUNNING TRIM MOULDING RR - MC	1.00	83.12	00.00	83.12

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chunhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 194400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 58121
Reg No/Reg Date SLK8558E / 22/04/2021
Date In/Mileage / 0
Chassis No W1K2050762R623067X
Engine No 26491580103478
Make/Model MB/C 180
Colour/Trim 028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator	
WN000512	Credit	07/07/2022/ 17:41	YK	395 / Yik Chan Hoe	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M COVER, ENGINE COMP. LOWER	BR	1.00	205.89	00.00	205.89
M RIGHT FRONT SHOCK-ABSORBER STRUT	BR	1.00	773.51	00.00	773.51
M FRONT TUBULAR TORSION BAR	BR	1.00	683.41	00.00	683.41
M RIGHT FRONT TORSION BAR LINKAGE	BR	1.00	96.53	00.00	96.53
M RIGHT FRONT STEERING KNUCKLE	BR	1.00	1439.20	00.00	1439.20
M RIGHT FRONT WHEEL BEARING	BR	1.00	575.41	00.00	575.41
M RIGHT FRONT CONTROL ARM	BR	1.00	864.36	00.00	864.36
M RIGHT FRONT SPRING LINK ARM	BR	1.00	645.97	00.00	645.97
M RIGHT FRONT STRUT ARM	BR	1.00	649.20	00.00	649.20
M INTEGRAL CARRIER	BR	1.00	2547.52	00.00	2547.52
M STEERING GEAR	BR	1.00	7694.86	00.00	7694.86
M STEERING COLUMN	BR	1.00	3367.46	00.00	3367.46
M STEERING WHEEL	BR	1.00	1511.42	00.00	1511.42
M DRIVER'S AIRBAG	BR	1.00	1826.94	00.00	1826.94
M INSTRUMENT PANEL	BR	1.00	4689.48	00.00	4689.48
M PASSENGER AIRBAG	BR	1.00	1945.22	00.00	1945.22
M SRS CONTROL UNIT, COMPLETE	BR	1.00	1121.48	00.00	1121.48
M SRS ACCELERATION SENSOR	BR	2.00	146.45	00.00	292.90
M RIGHT KNEE AIRBAG	BR	1.00	1080.46	00.00	1080.46
M RIGHT FOOTWELL UNDER COVER	BR	1.00	183.05	00.00	183.05
M LEFT FRONT SEAT BELT	BR	1.00	731.35	00.00	731.35
M RIGHT FRONT SEAT BELT	BR	1.00	731.35	00.00	731.35
M LEFT REAR SEAT BELT	BR	1.00	438.92	00.00	438.92
M RIGHT REAR SEAT BELT	BR	1.00	438.92	00.00	438.92
M LEFT DISK WHEEL	BR	1.00	661.04	00.00	661.04
M RIGHT FRONT DISK WHEEL	BR	1.00	661.04	00.00	661.04
M FRONT WINDSHIELD	BR	1.00	910.02	00.00	910.02
M FRONT W/SCREEN SEALING STRIP	BR	4.00	2.70	00.00	10.80
M ONE-COMPONENT ADHESIVE	BR	2.00	179.31	00.00	358.62
M RIGHT FRONT BRAKE ROTOR	BR	1.00	289.55	00.00	289.55
M RIGHT FRONT BRAKE CALIPER BRACKET	BR	1.00	306.32	00.00	306.32
M RIGHT FRONT BRAKE CALIPER	BR	1.00	1158.53	00.00	1158.53
M BRAKE WEAR SENSOR	BR	1.00	17.62	00.00	17.62

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chenhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information
WIP No 58121
Reg No/Reg Date SLK8558E / 22/04/2021
Date In/Mileage / 0
Chassis No W1K2050762R623067X
Engine No 26491580103478
Make/Model MB/C 180
Colour/Trim 028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator			
WN000512	Credit	07/07/2022/ 17:41	YK	395 / Yik Chan Hoe			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	TS TWO-COMPONENT ADHESIVE			1.00	858.76	00.00	858.76
M	UNDERBODY PROTECTION WAX			1.00	116.04	00.00	116.04
M	SEAM SEAL (FENDER)			1.00	70.68	00.00	70.68
M	SEAM SEAL			1.00	116.07	00.00	116.07

LEFT FRONT AND REAR UNDER CARRIAGE REQUIRES FURTHER CHECK TO CONFIRM,
VEHICLE MOUNTED ROAD KERB ON THE LEFT.

ESTIMATE

Store (LKK)
8/7/22, 4:30p

2D-16L AL
EXTRIS-?
P/P
by PL
28 days

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5169 Fax: 6872 1272
Email: chandee@cyclecarriage.com.sg

Confirmed & accepted by: LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
Authorized signatory and company stamp

7% GST on Net 95,793.38 95,793.38 8705.54
Total Payable 102,498.92

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG