



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 58121
Reg No/Reg Date SLK8558E / 22/04/2021
Date In/Mileage / 0
Chassis No W1K2050762R623067X
Engine No 26491580103478
Make/Model MB/C 180
Colour/Trim 028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WN000512	Credit	07/07/2022/ 17:41	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : DMPG22004766 // 29/06/2022								
DRIVE IN/EXCESS : TOW IN 06/07/2022 // TBA								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
S BPNSUB								
1 PC RIGHT FRONT TYRE - 70 (80%)								464 / 580.00
A BPILAB								
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH 960 x 8								7680 / 8640.00
A BPIRES								
RESPRAY BONNET, FRONT BUMPER, RIGHT FRONT FENDER, RIGHT FRONT CHASSIS, RIGHT FRONT DOOR. 8 x 65								4200 / 4800.00
A BPILAB								
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT					0.10			380.00
A BPILAB								
CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT					0.07			120.00
A BPILAB								
PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMENT. NETT (photo)								1920 / 2400.00
A BPILAB								
REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS								1920 / 2400.00
A BPILAB								
REMOVE AND RE-INSTALL ENGINE ASSY, TRANSMISSION ASSY AND ELECTRONICS TO ASSIST WORKLOAD					0.07			500.00
A BPILAB								
REMOVE / RENEW / REFIT RADIATOR AND CONDENSER, CHECK COOLING SYSTEM AND AIR-CON SYSTEM WITH RE-GAS. NETT								540.00
A BPILAB								

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6372 1272
Email: chunhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

58121
SLK8558E / 22/04/2021
/ 0
W1K2050762R623067X
26491580103478
MB/C 180
028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WN000512	Credit	07/07/2022/ 17:41	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT					0.07			550.00 ✓
A BPILAB RENEW FRONT W/SCREEN								2880.00 ✓
A BPILAB REMOVE & INSTALL INSTRUMENT PANEL								2880.00 ✓
A BPILAB REMOVE AND REPLACE DRIVER'S AND PASSENGERS' SEAT BELTS AND AIR-BAGS. REPLACE CONTROL UNITS AND RESET 'SRS' SYSTEM								960.00 ✓
A BPILAB REPLACE STEERING WHEEL AND STEERING COLUMN								480.00 ✓
A BPILAB TRANSFER MECHANICAL & ELECTRICAL COMPONENTS OVER TO NEW DOOR. NETT								1920.00 ✓
A BPILAB REMOVE AND REFIT ABR PUMP, TO BLEED AND RESET SYSTEM. REMOVE AND REFIT PIPINGS AND WIRINGS TO ASSIST WORKLOAD. (photo)								120.00 ✓
A BPILAB TO APPLY SEAL SEAM ON PANEL JOINTS								180.00 ✓
A BPILAB APPLY CAVITY WAX ON AFFECTED AREAS.								120.00 ✓
A BPILAB APPLY SEAL SEAM ON THE INNER PART OF FENDER (W205)								300.00 ✓
S BPNSUB INSTALL SOLAR FILM ON FRONT W/SCREEN								nec 26.00 ✓
M BPNSUN 1 PC IU BRACKET					1.00	977.57	00.00	977.57 ✓
M RIGHT FRONT FENDER / 00					1.00	145.10	00.00	145.10 ✓
M RIGHT FRONT FENDER LINER RR - BR					1.00	134.11	00.00	134.11 ✓
M RIGHT FRONT FENDER LINER FF - BR					1.00	1674.18	00.00	1674.18 ✓
M FRONT BUMPER - BR					1.00	207.58	00.00	207.58 ✓
M FRONT BUMPER LOWER TRIM STRIP - MC					1.00	207.71	00.00	207.71 ✓
M FRONT BASIC CARRIER FOR BUMPER - BR					1.00	105.08	00.00	105.08 ✓
M FRONT BASIC CARRIER FOR BUMPER - BR					1.00	106.65	00.00	106.65 ✓
M FRONT TOP BASIC MOUNTING FOR BUMPER - X nn								

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6372 1272
Email: chunhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

WIP No
Reg No/Reg Date
Date In/Mileage
Chassis No
Engine No
Make/Model
Colour/Trim

Vehicle & Document Information

58121
SLK8558E / 22/04/2021
/ 0
W1K2050762R623067X
26491580103478
MB/C 180
028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WN000512	Credit	07/07/2022/ 17:41	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M FRONT IMPACT ABSORBER	OR				1.00	173.25	00.00	173.25
M RIGHT FRONT BASIC CARRIER FOR BUMPER	OR				1.00	105.65	00.00	105.65
M RIGHT FRONT BUMPER GRILLE	CVT				1.00	70.49	00.00	70.49
M FRONT BUMPER COVER, TOWING EYE	MIS				1.00	66.66	00.00	66.66
M FRONT CPA RADAR SENSOR	? X NN				1.00	1233.72	00.00	1233.72
M FRONT BUMPER ELECTRICAL WIRING HARNESS	? / TN				1.00	172.34	00.00	172.34
M RIGHT FRONT DISTANCE SENSOR	OR				1.00	195.43	00.00	195.43
M FRONT DISTANCE SENSOR	? X NN				2.00	195.43	00.00	390.86
M PTS SPACER RING	MC				6.00	7.10	00.00	42.60
M FRONT SRS PRESSURE SENSOR	? MIS				1.00	127.20	00.00	127.20
M RIGHT FRONT BUMPER MOUNTING RAIL	? X NN				1.00	15.52	00.00	15.52
M BONNET	DO				1.00	2215.00	00.00	2215.00
M BONNET MB EMBLEM	MC				1.00	80.58	00.00	80.58
M RIGHT BONNET HINGE	? X NN				1.00	200.36	00.00	200.36
M RADIATOR GRILLE AIR DUCT	? X NN				1.00	157.54	00.00	157.54
M RADIATOR GRILLE	? X NN				1.00	143.15	00.00	143.15
M LAMP UNIT	? X NN				1.00	3443.48	00.00	3443.48
M RIGHT HEADLAMP UNIT	OR				1.00	3443.48	00.00	3443.48
M FRONT SUPPORT PANEL	BT				1.00	851.45	00.00	851.45
M U-SHAPED STRIKER	? X NN				1.00	104.58	00.00	104.58
M FRONT SUPPORT PANEL CONSOLE	? BR				1.00	257.72	00.00	257.72
M RIGHT FRONT ANGLE BRACKET	MIS				1.00	64.59	00.00	64.59
M FRONT CROSS MEMBER	? X NN				1.00	473.91	00.00	473.91
M RIGHT FRONT CROSSMEMBER ABSORBER	OR				1.00	220.02	00.00	220.02
M RIGHT FRONT BOTTOM ABSORBER	? X NN				1.00	119.28	00.00	119.28
M RIGHT FRONT STRUT TOWER	DO				1.00	1745.52	00.00	1745.52
M RIGHT FRONT TOP LONGITUDINAL MEMBER	DO				1.00	515.54	00.00	515.54
M RIGHT FRONT LONGITUDINAL MEMBER	DO				1.00	375.71	00.00	375.71
M RIGHT FRONT STRUT TOWER REINFORCEMENT	DO				1.00	170.17	00.00	170.17
M RIGHT FRONT FENDER BRACKET	DO				1.00	63.52	00.00	63.52
M RIGHT RUNNING BOARD	CR4				1.00	588.60	00.00	588.60
M RIGHT RUNNING TRIM MOULDING FF	OR				1.00	127.42	00.00	127.42
M RIGHT RUNNING TRIM MOULDING RR	MC				1.00	83.12	00.00	83.12

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6372 1272
Email: chunhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Page 3 of 5



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 58121
Reg No/Reg Date SLK8558E / 22/04/2021
Date In/Mileage / 0
Chassis No W1K2050762R623067X
Engine No 26491580103478
Make/Model MB/C 180
Colour/Trim 028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator				
WN000512	Credit	07/07/2022/ 17:41	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M COVER, ENGINE COMP. LOWER					1.00	205.89	00.00	205.89
M RIGHT FRONT SHOCK-ABSORBER STRUT					1.00	773.51	00.00	773.51
M FRONT TUBULAR TORSION BAR					1.00	683.41	00.00	683.41
M RIGHT FRONT TORSION BAR LINKAGE					1.00	96.53	00.00	96.53
M RIGHT FRONT STEERING KNUCKLE					1.00	1439.20	00.00	1439.20
M RIGHT FRONT WHEEL BEARING					1.00	575.41	00.00	575.41
M RIGHT FRONT CONTROL ARM					1.00	864.36	00.00	864.36
M RIGHT FRONT SPRING LINK ARM					1.00	645.97	00.00	645.97
M RIGHT FRONT STRUT ARM					1.00	649.20	00.00	649.20
M INTEGRAL CARRIER					1.00	2547.52	00.00	2547.52
M STEERING GEAR					1.00	7694.86	00.00	7694.86
M STEERING COLUMN					1.00	3367.46	00.00	3367.46
M STEERING WHEEL					1.00	1511.42	00.00	1511.42
M DRIVER'S AIRBAG					1.00	1826.94	00.00	1826.94
M INSTRUMENT PANEL					1.00	4689.48	00.00	4689.48
M PASSENGER AIRBAG					1.00	1945.22	00.00	1945.22
M SRS CONTROL UNIT, COMPLETE					1.00	1121.48	00.00	1121.48
M SRS ACCELERATION SENSOR					2.00	146.45	00.00	292.90
M RIGHT KNEE AIRBAG					1.00	1080.46	00.00	1080.46
M RIGHT FOOTWELL UNDER COVER					1.00	183.05	00.00	183.05
M LEFT FRONT SEAT BELT					1.00	731.35	00.00	731.35
M RIGHT FRONT SEAT BELT					1.00	731.35	00.00	731.35
M LEFT REAR SEAT BELT					1.00	438.92	00.00	438.92
M RIGHT REAR SEAT BELT					1.00	438.92	00.00	438.92
M LEFT DISK WHEEL					1.00	661.04	00.00	661.04
M RIGHT FRONT DISK WHEEL					1.00	661.04	00.00	661.04
M FRONT WINDSHIELD					1.00	910.02	00.00	910.02
M FRONT W/SCREEN SEALING STRIP					4.00	2.70	00.00	10.80
M ONE-COMPONENT ADHESIVE					2.00	179.31	00.00	358.62
M RIGHT FRONT BRAKE ROTOR					1.00	289.55	00.00	289.55
M RIGHT FRONT BRAKE CALIPER BRACKET					1.00	306.32	00.00	306.32
M RIGHT FRONT BRAKE CALIPER					1.00	1158.53	00.00	1158.53
M BRAKE WEAR SENSOR					1.00	17.62	00.00	17.62

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chunhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Page 4 of 5



Mercedes-Benz

ESTIMATE FOR SLK8558E

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 58121
Reg No/Reg Date SLK8558E / 22/04/2021
Date In/Mileage / 0
Chassis No W1K2050762R623067X
Engine No 26491580103478
Make/Model MB/C 180
Colour/Trim 028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator
WN000512	Credit	07/07/2022/ 17:41	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M TS TWO-COMPONENT ADHESIVE	1.00	858.76	00.00	858.76
M UNDERBODY PROTECTION WAX	1.00	116.04	00.00	116.04
M SEAM SEAL (FENDER)	1.00	70.68	00.00	70.68
M SEAM SEAL	1.00	116.07	00.00	116.07
M BPNSUN				

LEFT FRONT AND REAR UNDER CARRIAGE REQUIRES FURTHER CHECK TO CONFIRM,
VEHICLE MOUNTED ROAD KERB ON THE LEFT.

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chunhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

Third party survey is on a "Without Prejudice" basis
and no conclusion(s) is allowed

Nett 95,793.38
7% GST on 95793.38 6705.54
Total Payable 102,498.92

Validity of this estimate is 14 days from date of quote. This is a computer-generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG