



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

SUPPLEMENTARY

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 58121
Reg No/Reg Date SLK8558E / 22/04/2021
Date In/Mileage 13/07/2022/ 34615
Chassis No W1K2050762R623067X
Engine No 26491580103478
Make/Model MB/C 180
Colour/Trim 028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WN000512	Credit	07/09/2022/ 18:47	YK	395 / Yik Chan Hoe					
A BPILAB					REMOVE AND REFIT 'ABR' PUMP, PIPINGS, WIRING HARNESS TO ASSIT WORKLOAD TO BLEED SYSTEM AND RESET 'ESP' SYSTEM.				1440.00 ✓
A BPILAB					REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS (REAR)				1920.00 ✓
A BPILAB					ADDITIONAL LABOUR TO REMOVE AND REFIT REAR BUMPER FOR PAINTING.				960.00 ✓
A BPIRES					ADDITIONAL LABOUR TO RESPRAY REAR BUMPER			0.05	800.00 ✓
A BPILAB					INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT (2ND INSPECTION) (rear LH portion)				540.00 ✓
X					HEXALOBULAR BOLT	4.00	1.23	00.00	NEC 4.92 ✓
X					LOCK NUT	2.00	6.06	00.00	NEC 12.12 ✓
X					SCREW	1.00	15.99	00.00	NEC 15.99 ✓
X					RIGHT FRONT W/HOUSE LOWER STRUT PANEL	1.00	276.13	00.00	DD 276.13 ✓
X					SCREW	3.00	4.18	00.00	NEC 12.54 ✓
X					STUD BOLT	2.00	3.08	00.00	NEC 6.16 ✓
X					NUT	2.00	4.05	00.00	NEC 8.10 ✓
X					RIGHT FRONT FENDER END COVERING	1.00	28.56	00.00	NEC 28.56 ✓
X					HOLE PLUG	3.00	3.80	00.00	NEC 11.40 ✓
X					EXPANSION RIVET	2.00	1.19	00.00	NEC 2.38 ✓
X					RIVET	4.00	6.09	00.00	NEC 24.36 ✓
X					LEFT FRONT CROSSMEMBER BRACKET	1.00	88.24	00.00	NEC 88.24 ✓
X					RIGHT FRONT SUPPORT ANGLE BRACKET	1.00	49.29	00.00	NEC 49.29 ✓
X					HEXALOBULAR BOLT	2.00	40.05	00.00	NEC 80.10 ✓
X					HEXAGON HEAD BOLT	2.00	18.63	00.00	NEC 37.26 ✓
X					NUT-A-WASHER ASSEMBLY	2.00	15.99	00.00	NEC 31.98 ✓
X					NUT W FLANGE, BINDING	1.00	9.99	00.00	NEC 9.99 ✓
X					SCREW W RND. HEXAL. HEAD	2.00	17.21	00.00	NEC 34.42 ✓
X					SCREW W RND. HEXAL. HEAD	2.00	23.78	00.00	NEC 47.56 ✓
X					RIGHT FRONT WATER DRAINAGE PIPE	1.00	53.44	00.00	TN 53.44 ✓

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarrage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No 58121
Reg No/Reg Date SLK8558E / 22/04/2021
Date In/Mileage 13/07/2022/ 34615
Chassis No W1K2050762R623067X
Engine No 26491580103478
Make/Model MB/C 180
Colour/Trim 028 831 Graphite Gr/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
WN000512	Credit	07/09/2022/ 18:47	YK	395 / Yik Chan Hoe						
X					RIGHT FRONT BRAKE ROTOR COVER PLATE	1.00	54.50	00.00	BT	54.50 ✓
X					SCREW	4.00	3.08	00.00	NEC	12.32 ✓
X					COVER F ENGINE COMP. BM	1.00	202.93	00.00	MIS	202.93 ✓
X					COMBINATION NUT	2.00	14.92	00.00	NEC	29.84 ✓
X					HEXAGON HEAD BOLT	1.00	18.09	00.00	NEC	18.09 ✓
X					HEXAGON NUT	1.00	4.71	00.00	NEC	4.71 ✓
X					THREAD ROLLING SCREW	2.00	8.98	00.00	NEC	17.96 ✓
X					SCREW	2.00	34.43	00.00	NEC	68.86 ✓
X					RIGHT FRONT PILLAR LOWER REINFORCEMENT	1.00	144.25	00.00	DD	144.25 ✓
X					RIVET	26.00	6.09	00.00	NEC	158.34 ✓
X					RIVET	50.00	2.73	00.00	NEC	136.50 ✓
X					RIVET	2.00	4.24	00.00	NEC	8.48 ✓
X					BLIND RIVET	20.00	1.70	00.00	NEC	34.00 ✓
X					SEAM SEAL	1.00	116.07	00.00	MIS	116.07 ✓
X					RETAINING SPRING	1.00	3.05	00.00	NEC	3.05 ✓
X					RADIATOR ANTIFREEZE	3.00	34.86	00.00	NEC	104.58 ✓
X					BRAKE FLUID	2.00	57.59	00.00	NEC	115.18 ✓
X					RIVET	8.00	6.09	00.00	NEC	48.72 ✓
X					PLUG	1.00	2.10	00.00	NEC	2.10 ✓
X					TIRE PRESSURE SENSOR	1.00	201.74	00.00	NEC	201.74 ✓
X					TIRE VALVE	1.00	96.08	00.00	NEC	96.08 ✓
X					MOLDING CLIP	2.00	6.44	00.00	NEC	12.88 ✓
X					MOUNTING CLIP	1.00	5.75	00.00	NEC	5.75 ✓
X					MOUNTING CLIP	1.00	5.91	00.00	NEC	5.91 ✓
X					MOUNTING CLIP	3.00	7.16	00.00	NEC	21.48 ✓
X					LEFT A-PILLAR TRIM	1.00	243.68	00.00	DEF	243.68 ✓
X					*MSP 12V/70AH BATTERY	1.00	349.00	00.00	Shorted	349.00 ✓
X					LEFT REAR SPRING LINK ARM	1.00	302.52	00.00	BT	302.52 ✓
X					LEFT REAR WHEEL CARRIER	1.00	1745.55	00.00	BT	1745.55 ✓
X					COLLAR NUT	1.00	25.54	00.00	BT	25.54 ✓
X					LEFT REAR CAMBER ARM	1.00	247.92	00.00	BT	247.92 ✓
X					LEFT REAR TIE ROD	1.00	226.80	00.00	BT	226.80 ✓
X					LEFT REAR PUSHING STRUT ARM	1.00	113.78	00.00	BT	113.78 ✓

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

SUPPLEMENTARY

ESTIMATE FOR SLK8558E

ERGO INSURANCE PTE LTD

MOTOR CLAIM DEPARTMENT
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985
68299199

Vehicle & Document Information

WIP No **58121**
Reg No/Reg Date **SLK8558E / 22/04/2021**
Date In/Mileage **13/07/2022/ 34615**
Chassis No **W1K2050762R623067X**
Engine No **26491580103478**
Make/Model **MB/C 180**
Colour/Trim **028 831 Graphite Gr/ 041 101 ARTICO Leat**

Account No	Terms	Date/Time Printed	CSE	Operator			
WN000512	Credit	07/09/2022/ 18:47	YK	395 / Yik Chan Hoe			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X LEFT REAR WHEEL FLANGE				1.00	539.00	00.00	BT 539.00 ✓
X FLUTED SOCKET SCREW				1.00	30.63	00.00	NEC 30.63 ✓

ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 11,943.68
7% GST on 11943.68 836.06
Total Payable 12,779.74

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG