



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 997M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Price (\$)	Our Adjusted (\$)
	<b>LABOUR</b>				
	TO SUPPLY AND REPLACE DAMAGED EXTERNAL LOCK FOR DOOR.		520.00	-	520.00
	TO SUPPLY LABOUR AND MATERIAL TO REPAIR DAMAGED AREA OF THE REF BOX WITH FIBERGLASS.		400.00	-	180.00
	TO PROVIDE GRAPHICS REINSTATEMENT ON 25FT FREEZER TRUCK:		1,500.00	-	1,500.00
	- GRAPHIC WRAP ON LEFT SIDE OF THE BOX				
	LABOUR (25FT REFRIGERATED TRUCK)		1,800.00	-	1,800.00
	NOTE :				
	- 2DAYS FOR ARTWORK				
	- 2DAYS FOR REPAIR AND REPLACEMENT				
			4,220.00	-	4,000.00
	<b>GRAND TOTAL</b>		<b>4,220.00</b>	-	<b>4,000.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>					<b>4,000.00</b>

Report Ref No. CS/SPS22006546/Gqy3m4

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.