

**COMFORT TRANSPORTATION PTE LTD**

**REPAIR ESTIMATE**

Vehicle No. : SHD7162D

Date: 28/06/2022

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 553.00
1	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER SIDE BRACKET RH			\$ 35.60
1	REAR BUMPER REFLECTOR LAMP RH			\$ 32.00
1	REAR BUMPER LOWER COVER			\$ 228.00
1	REAR BUMPER REINFORCEMENT			\$ 428.40
1	RR BUMPER REINFORCEMENT BRACKET RH			\$ 160.60
	<b>SUB TOTAL</b>		575	\$ 1,459.60
	<b>LESS 20%</b>			\$ 291.92
	<b>DISCOUNTED TOTAL</b>		460	\$ 1,167.68
	<b>Labour Charge</b>			
	PANEL BEATING			\$ 320.00
	SPRAY PAINTING CHARGE			\$ 300.00
	REMOVE/ REFIX EXHAUST PIPE		560	\$ 150.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 60.00
	<b>TOTAL LABOUR</b>		1020	\$ 830.00
	<b>ESTIMATE TOTAL</b>		460 + 1020 = 1480	\$ 1,997.68

de  
ner  
X  
X  
X  
X  
X

Nett

280  
250  
X 114  
30

2 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495249  
WP 28/6/22 @ 430pm  
2 days  
Lb's ready after repair  
Tanpin LKK auto car

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: