



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6659U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	TO REPAIR SEE LABOUR	459.40	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,768.30	-
1	REAR BUMPER SIDE BRACKET RH	NOT NECESSARY	55.80	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	2,147.90	-
	LESS 20% DISCOUNT		-890.68	-4.40
			3,562.72	17.60
<u>SPECIAL NETT ITEMS</u>				
1	REAR DOOR COMFORTDELGRO APP STICKER RH (SN)	NECESSARY	80.00	80.00
			80.00	80.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER COVER, REAR FENDER RH AND REAR DOOR RH.		1,050.00	525.00
	SPRAY PAINTING CHARGE.		800.00	750.00
	TRANSFER OF DOOR.	NOT NECESSARY	120.00	-
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/ REFIX UPHOLSTERY & CUSHION RR.	NOT NECESSARY	120.00	-
			2,150.00	1,275.00
GRAND TOTAL			5,792.72	1,372.60
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,372.60

Report Ref No. NS/INC22006548/Tvcm4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.