

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD3017S

Make : HYUNDAI

Model : I-40

Date: 06/24/22

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$ 1,052.20
10	FRONT BUMPER CLIPS		\$ 2.20	\$ 22.00
1	FRT BUMPER GRILLE LH			\$ 187.20
1	RADIATOR GRILLE			\$ 1,480.00
1	RADIATOR GRILLE H EMBLEM			\$ 129.50
1	BONNET			\$ 2,508.80
1	FRT BUMPER REINFORCEMENT			\$ 588.40
1	FRT BUMPER CENTRE GRILLE			\$ 178.60
1	FRT BUMPER SIDE BRACKET LH			\$ 24.60
1	HEADLAMP LH			\$ 1,388.00
1	AIRCON CONDENSER			\$ 947.80
1	RADIATOR			\$ 1,637.20
	SUB TOTAL			\$ 10,144.30
	LESS 20%			\$ 2,028.86
	DISCOUNTED TOTAL			\$ 8,115.44
	FRT NUMBER PLATE WITH TRIM COVER	-10.00%		\$ 55.00
				\$ 55.00
	Labour Charge			
	PANEL BEATING			\$ 900.00
	SPRAY PAINTING CHARGE			\$ 600.00
	CHECK ALL LIGHTING			\$ 60.00
	WIRING CHARGE			\$ 60.00
	TOTAL LABOUR			\$ 1,620.00
	ESTIMATE TOTAL			\$ 9,790.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97445749
 up 24/6/22 & Repair 3 pm
 L/S Resurvey after repair
 Tanpin C Consultants
 3 days

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: