

ASS. REC. BY:

Tough

REF:

INC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

MS/John

Veh No:

SHC 3782X

Yr Regn:

249, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Comiq

c.c.

1580

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

413/88

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH 85 / CV 24 / 88159

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: ☒ NI / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

1 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wet Hake

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

21/6/22

Survey held at

Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop: or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report  
☐ : Final Report
1) \_\_\_\_\_  
Date/Time, File Return to?

2) \_\_\_\_\_

Rep. Format: \_\_\_\_\_

Lump Sum / L.B.L. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

## COMFORT TRANSPORTATION PTE LTD

**REPAIR ESTIMATE**

Vehicle No. : SHC3782X

Make : HYUNDAI

Model : IONIQ(G3)

Date: 21.06.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH RH		138.1	\$276.20
1	REAR BUMPER FOG LAMP			\$201.50
1	REAR BUMPER LICENCE LAMP			\$85.30
1	ANTENNA ASSY SMARTKEY			\$40.50
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	\$111.60
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	REAR BUMPER TOWING COVER			\$98.80
1	REAR BUMPER CENTER UNDER COVER			\$225.00
SUB TOTAL				\$2,576.95
LESS 20%				\$515.39
DISCOUNTED TOTAL				\$2,061.56
	REAR NUMBER PLATE WITH TRIM COVER		-10%	\$55.00
	BOOTLID COMFORT TEL NO STICKER		-10%	\$40.00
	BOOTLID COMFORT LOGO STICKER		-10%	\$30.00
	BOOTLID COMFORT APP STICKER		-10%	\$30.00
	REAR BUMPER REVERSE SENSOR		-10%	\$180.00
				\$335.00
Labour Charge				
	PANEL BEATING			\$750.00
	SPRAY PAINTING CHARGE			\$600.00
	CHK ALL LIGHTING			\$60.00
	TUFF KOTE			\$60.00
	REMOVE/REFIX REVERSE SENSOR			\$80.00
TOTAL LABOUR				\$1,550.00
ESTIMATE TOTAL				\$3,946.56

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer as follows:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jia 4748544  
 21/6/22 2:50pm  
 ~ 2 days  
 1/3 Ready after repair  
 tanjia@lkk.com



Date/Time: 21.06.2022 10:58

Page : 1

Team: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4298715

JC NO 305520312


CUSTOMER		REGN NO:	MILEAGE
COMFORT TRANSPORTATION PTE LTD		SHC3782X	
IR/MS	7010045	MAKE:	FUEL
CUSTOMER NO.		HYUNDAI	E.....1/2.....F
ADDRESS	383 SIN MING DRIVE	MODEL	DATE/TIME IN
	Singapore SINGAPORE 575717	IONIQ(G3)	20.06.2022 19:55
EL. (R)	65508755	YR OF MANU.	TARGET DATE
(P)	(O)	06.11.2019	
DISCOUNT CARD NO.		CHASSIS CODE	COMPLETION DATE/TIME:
		KMHC851CVLU188159	

JOB DESCRIPTION

Accident Date: 20.06.2022

NATURE: 3P 20.06.2022

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------



CHECKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHC3782X YY

Vehicle No.: SHC3782X

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard