

ASS. REC. BY: Taughm

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 2787P

Yr Regn: 209, oct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai

c.c. 1580

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 336414

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: UMHC851CVL4187607

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Watsake

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 22/4/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.I. /

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2787P

16.06.2022

MAKE REG 30.10.2019

CHIANG/NTUC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
2	REAR BUMPER SIDE BRACKET LH/RH		\$55.80
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	TOW COVER		\$98.80
2	NUMBER PLATE LAMP LH/RH		\$85.30
1	REAR FOG LAMP		\$210.50
1	REAR SMART ANTENNA		\$40.50
10	REAR BUMPER CLIPS		\$2.20
	SUB TOTAL		\$1,959.45
	20.00%		\$391.89
	DISCOUNTED TOTAL		\$1,567.56
2	REAR FENDER ADVERTISEMENT		\$200.00
1	REAR NUMBER PLATE W/HOLDER		\$55.00
1	REAR REVERSE SENSOR		\$180.00
			\$411.50
	Labour Charge		
	Panel Beating		350 \$600.00
	Spray Painting Charge		250 \$300.00
	Check Lighting and Wiring		x \$60.00
	Tuff Coating		x \$60.00
	Remove/refix Reverse sensor		30 \$60.00
	TOTAL LABOUR		\$1,080.00
	ESTIMATE TOTAL		\$3,059.06
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanf/lu 97495749
 WP 22/6/22 0430
 4/5 Body after repair
 2 days
 Tanf/lu 97495749

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 22.06.2022 10:58

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4298867

JC NO 305520680

OMER

COMFORT TRANSPORTATION PTE LTD

7010045

OMER NO.

ESS

383 SIN MING DRIVE
Singapore SINGAPORE 575717

65508755

(O)

(R)

(P)

UNT CARD NO.

REGN NO:

SHC2787P

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN
22.06.2022 09:40

YR OF MANU.

30.10.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU187607

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 16.06.2022

ATURE: 3P 16.06.2022

NO

LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

No.:

SHC2787P

CHIANG

Vehicle No.:

SHC2787P

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard