

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2223A

21.06.2022

MAKE/REG 06.12.2018

CHIANG/NTUC

MODEL TOYOTA PRIUS G4

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER		\$551.89
1	REAR UNDER COVER		\$654.96
1	REAR REINFORCEMENT		\$378.32
2	REAR BUMPER SIDE RETAINER RH/LH	\$112.70	\$225.40
1	REAR TRUNK GRANISH SUB ASSY		\$1,054.70
1	TRUNK PRIUS EMBLEM		\$62.14
1	TRUNK HYBRID EMBLEM		\$62.14
10	REAR BUMPER CLIPS	\$2.20	\$22.00
1	LH TAIL UPPER LAMP		\$557.90
1	LH TAIL LOWER LAMP		\$570.00
1	TOW COVER		\$82.70
1	LH FENDER		\$992.04
1	LH FEDER SHIELD		\$134.20
	SUB TOTAL		\$5,348.39
	25.00%		\$1,337.09
	DISCOUNTED TOTAL		\$4,011.29
1	REAR BUMPER ADVERTISEMENT		\$50.00
1	PETROL SICKER		\$20.00
1	COMFOERT LOGO APP		\$40.00
1	COMFORT / TEL NUMBER STICKER		\$60.00
1	REVERSE SENSOR		\$135.70
			\$280.13
	Labour Charge		
	Panel Beating		\$1,050.00
	Spray Painting Charge		\$800.00
	Tuff Kote		\$60.00
	Remove and Rear upholstery		\$90.00
	Check Lighting		\$60.00
	Remove and Refix Reverse Sensor		\$60.00
	TOTAL LABOUR		\$2,120.00
	ESTIMATE TOTAL		\$6,411.42
A	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495779

up 22/6/22 0430

1/3 Resurvey after repair

2 days

Taufik C. Chantawan

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508989
383 Sin Ming Drive Singapore 575717

Date/Time: 22.06.2022 10:59

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4298870

JC NO305520681

STOMER

REGN NO.:

SHC2223A

MILEAGE

/MS

COMFORT TRANSPORTATION PTE LTD

MAKE :

TOYOTA

FUEL

E.....1/2.....F

STOMER NO.

7010045

MODEL

PRIUS HYBRID(G4)22.06.2022 08:20

DATE/TIME IN

DRESS

383 SIN MING DRIVE

Singapore SINGAPORE 575717

YR OF MANU.

06.12.2018

TARGET DATE

(R)

65508755

(O)

(P)

CHASSIS CODE

JTDKB3FU803077678

COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION


Accident Date: 21.06.2022

NATURE: 3P 21.06.2022

3/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

Vehicle No.:

SHC2223A

CHIANG

Vehicle No.:

SHC2223A

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard