

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB3283A

Make : HYUNDAI

Model : I-40

Date: 21/06/2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER			\$ 553.00	de
1	REAR BUMPER CLIPS			\$ 22.00	de
2	REAR BUMPER BRACKET LH RH		\$ 35.60	\$ 71.20	Run
1	REAR BUMPER REINFORCEMENT			\$ 428.40	de
1	RR BUMPER REINFORCEMENT BRACKET LH RH		\$ 160.60	\$ 321.20	Run.
1	REAR BUMPER UNDER COVER			\$ 228.00	de
1	BOOTLID			\$ 2,174.90	de
1	BOOTLID 'H' EMBLEM			\$ 63.10	de
1	BOOTLID CRDI PLATE			\$ 52.40	de
1	BOOTLID MOULDING			\$ 85.00	de
1	BOOTLID I40 EMBLEM			\$ 67.90	de
1	REAR PANEL			\$ 526.70	XR
1	REAR PANEL GARNISH			\$ 57.70	Run
2	TAIL LAMP LH RH <i>LH - old damage area</i>		\$ 697.80	\$ 1,395.60	Run.
	SUB TOTAL			\$ 6,992.70	3674-70
	LESS 20%			\$ 1,398.54	2939.76
	DISCOUNTED TOTAL			\$ 5,594.16	
1	REAR BUMPER REVERSE SENSOR			\$ 135.70	Nett am
	Labour Charge			\$ 135.70	Nett 135.70
	PANEL BEATING			\$ 900.00	10% 122.13
	SPRAY PAINTING CHARGE			\$ 600.00	560
	TUFF KOTE			\$ 80.00	50
	CHECK ALL LIGHTING			\$ 60.00	30
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00	30
	TOTAL LABOUR			\$ 1,700.00	1250
	ESTIMATE TOTAL			\$ 7,429.86	4311.89

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Tanphm 9749 5749
 WP' 21/6/22 @ 5pm
 03 days
 L/P Resurvey after repair
 Tanphm C (Kuantan)
 Page 1

4311.89
 4311.89
 3 days