

INC

TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB3283A

Date: 21/06/2022

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 553.00
1	REAR BUMPER CLIPS			\$ 22.00
2	REAR BUMPER BRACKET LH RH		\$ 35.60	\$ 71.20
1	REAR BUMPER REINFORCEMENT			\$ 428.40
1	RR BUMPER REINFORCEMENT BRACKET LH RH		\$ 160.60	\$ 321.20
1	REAR BUMPER UNDER COVER			\$ 228.00
1	BOOTLID			\$ 2,174.90
1	BOOTLID 'H' EMBLEM			\$ 63.10
1	BOOTLID CRDI PLATE			\$ 52.40
1	BOOTLID MOULDING			\$ 85.00
1	BOOTLID I40 EMBLEM			\$ 67.90
1	REAR PANEL			\$ 526.70
1	REAR PANEL GARNISH			\$ 57.70
2	TAIL LAMP LH RH <i>LH - old damage</i>		\$ 697.80	\$ 1,395.60
SUB TOTAL				\$ 6,992.70
LESS 20%				\$ 1,398.54
DISCOUNTED TOTAL				\$ 5,594.16
1	REAR BUMPER REVERSE SENSOR			\$ 135.70
Labour Charge				
PANEL BEATING				\$ 900.00
SPRAY PAINTING CHARGE				\$ 600.00
TUFF KOTE				\$ 80.00
CHECK ALL LIGHTING				\$ 60.00
REMOVE/REFIX REVERSE SENSOR				\$ 60.00
TOTAL LABOUR				\$ 1,700.00
ESTIMATE TOTAL				\$ 7,429.86

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 92495749
 up 21/6/22 @ 5pm
 03 days
 c/p Resurvey after repair
 Tanpin C (Mantson)
 Page 1

Date/Time: 21.06.2022 14:32

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4298748

JC NO305520316

STOMER

REGN NO:

SHB3283A

MILEAGE

V/MS CITYCAB PTE LTD
STOMER NO 7010070
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188 (R) (P) (O)

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

21.06.2022 13:40

YR OF MANU.

08.12.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMHU097215

COMPLETION DATE/TIME:


SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 21.06.2022

NATURE: 3P 21.06.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.: SHB3283A

YY

Vehicle No.:

SHB3283A

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard