

TOTAL

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2993R

22.06.2022

MAKE REG 06.08.2019

CHIANG/NTUC

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
2	REAR BUMPER SIDE BRACKET LH/RH		\$55.80
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER CENTRE LOWER MOULDING		\$155.00
1	TOW COVER		\$98.80
2	NUMBER PLATE LAMP LH/RH		\$85.30
1	REAR FOG LAMP		\$210.50
1	REAR SMART ANTENNA		\$40.50
10	REAR BUMPER CLIPS		\$2.20
	SUB TOTAL		\$2,114.45
	20.00%		\$422.89
	DISCOUNTED TOTAL		\$1,691.56
1	REAR NUMBER PLATE W/HOLDER		\$55.00
1	REAR REVERSE SENSOR		\$180.00
			\$211.50
	Labour Charge		
	Panel Beating		\$600.00
	Spray Painting Charge		\$300.00
	Check Lighting and Wiring		\$60.00
	Tuff Coating		\$60.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$1,080.00
	ESTIMATE TOTAL		\$3,194.56
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanghik 97495749

WR 22/6/22 0440

US Rising after repair

02 days

Tanghik @ 11:40 AM

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4298905

JC NO305520710

STOMER

V/MS CITYCAB PTE LTD
STOMER NO. 7010070
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188 (R) (O)
(P)

SCOUNT CARD NO.

REGN NO.

SHB2993R

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

22.06.2022 11:10

DATE/TIME IN

YR OF MANU.

06.08.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU165087

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 22.06.2022

NATURE: 3P 22.06.2022

S/NO

LABOR CODE

DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

:

:

le No.: SHB2993R

CHIANG

Vehicle No.:

SHB2993R

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard