



## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHD4254S

29.06.2022

MAKE 24.07.2019 REG DATE

CHIANG/NTUC

MODEL IONIQ G 2

| Qty  | Parts Description/ Labour   | Type                 | Amount                       |
|--|-----------------------------|----------------------|------------------------------|
| 1  | REAR BUMPER                 |                      | <i>M</i> \$459.40            |
| 1  | REAR BUMPER CENTRE MOULDING |                      | <i>cur</i> \$451.25          |
| 1  | REAR BUMPER REINFORCEMENT   |                      | <i>?</i> \$394.80            |
| 1  | REAR BUMPER UNDER MOULDING  |                      | <i>X</i> \$155.00            |
| 1  | REAR BUMPER BRACKET LH / RH | <i>LHX</i>           | \$55.80 <i>Hand</i> \$111.60 |
| 10   | REAR BUMPER COVER CLIPS     |                      | \$2.20 <i>cur</i> \$22.00    |
| 1  | REAR FOG LAMP               |                      | <i>X</i> \$201.50            |
| 1  | TAIL LAMP LH                |                      | <i>cur</i> \$935.40          |
| 1  | REAR NUMBER PLATE LAMP      |                      | \$85.30 <i>X</i> \$170.60    |
| 1  | REAR BUMPER REFLECTOR LH    |                      | <i>X</i> \$41.45             |
|  | <b>SUB TOTAL</b>            |                      | <b>\$2,943.00</b>            |
|  | <b>20.00%</b>               |                      | <b>\$588.60</b>              |
|  | <b>DISCOUNTED TOTAL</b>     |                      | <b>\$2,354.40</b>            |
| 1  | REAR NUMBER PLATE W/HOLDER  | <i>WC old damage</i> | <i>X</i> \$55.00             |
| 1  | REAR REVERSE SENSOR         |                      | <i>X</i> \$180.00            |
|  |                             |                      | <b>\$211.50</b>              |
|  | <b>Labour Charge</b>        |                      |                              |
|  | Panel Beating               |                      | <i>350</i> \$550.00          |
|  | Spray Painting Charge       |                      | <i>250</i> \$300.00          |
|  | Tuff Kote                   |                      | <i>X</i> \$90.00             |
|  | Remove/refix Reverse sensor |                      | <i>30</i> \$60.00            |
|  | <b>TOTAL LABOUR</b>         |                      | <b>\$1,000.00</b>            |
|  | <b>ESTIMATE TOTAL</b>       |                      | <b>\$3,565.90</b>            |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. |                             |                      |                              |

Tanpin 97475749  
 WP 30/6/22 @ 330 pm  
 L/S Resurvey after repair  
 Tanpin @ 11hamban  
 2 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Date/Time: 30.06.2022 11:30

Page : 1

Team: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4344753

JC NO 305521609


|   |  |  |                                  |
|---|--|--|----------------------------------|
| CUSTOMER  |  | REGN NO.:<br><b>SHD4254S</b>             | MILEAGE                          |
| VMS<br>COMFORT TRANSPORTATION PTE LTD                       |  | MAKE:<br><b>HYUNDAI</b>                  | FUEL                             |
| CUSTOMER NO.<br>7010045                                     |  | MODEL<br><b>IONIQ(G2)</b>                | DATE/TIME IN<br>30.06.2022 09:40 |
| ADDRESS<br>383 SIN MING DRIVE<br>Singapore SINGAPORE 575717 |  | YR OF MANU.<br>24.07.2019                | TARGET DATE                      |
| ... (R) 65508755 (O)  |  | CHASSIS CODE<br><b>KMHC851CVKU164886</b> | COMPLETION DATE/TIME:            |
| COUNT CARD NO.  |  |  |                                  |

### JOB DESCRIPTION

Accident Date: 29.06.2022

NATURE: 3P 29.06.2022

| S/NO | LABOR CODE | DESCRIPTION |
|------|------------|-------------|
|------|------------|-------------|



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHD4254S**

**CHIANG**

Vehicle No.: **SHD4254S**

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard