MFORT TRANSPORTATION PTE LTD

EPAIR ESTIMATE

/ehicle No. : SHA6980G

: HYUNDAI Make

: IONIQ(G2)

Date: 24.06.2022

Insurance: NTUC

MVA: MS. LOKE YY

Model :	IONIQ(G2)				
Ein eine Lieben	Parts Description / Labour	Туре	Unit Price	Amount	
10	REAR BUMPER COVER REAR BUMPER CLIPS REAR BUMPER CENTRE MOULDING ASSY REAR BUMPER REINFORCEMENT REAR BUMPER REINFORCEMENT BRACKET LH REAR BUMPER TOWING COVER SUB TO LESS: DISCOUNTED TO REAR BUMPER RUBBER MAT REAR BUMPER REVERSE SENSOR	20%	473.25 378-60	\$459.40 \$22.00 \$451.25 \$394.80 \$138.10 \$98.80 \$1,564.35 \$312.87 \$1,251.48 \$50.00 \$180.00 \$230.00	
	Labour Charge PANEL BEATING SPRAY PAINTING CHARGE REMOVE/REFIX REVERSE SENSOR TOTAL LASS ESTIMATE TO		650 1008.60 45\$800 02eleys	\$50 \$400.00 250 \$300.00 30 \$80.00 \$780.00 \$2,261.48	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfkri 17495749

wp' 21/0/12 e 3pm

2 dens

c/5 Resur Orffer repoir

tenflin c/hh ant LKK Auto C

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: