

ASS. REC. BY: Taught

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
☒	

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Chiang

Veh No: SHD4517J Yr Regn: 249 / Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai lraig c.c. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 408540 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH851CVL4189762

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 7 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wan Hake

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/6/22

Survey held at Comfort Agency

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) _____
Date/Time, File Return to?

2) _____

Rep. Format: _____

Lump Sum / L.B.I. (?) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4517J

30.06.2022

MAKE REG. 14.11.2019

MODEL IONIQ G3

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER STAY LH /RH		\$138.10	\$276.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER LOWER MOULDING			\$155.00
1	REAR BUMPER UNDER CENTRE COVER			\$225.00
1	REAR SPOILER			\$665.40
1	REAR THIRD BRAKE LAMP			\$385.60
1	BOOTLID COVER			\$2,549.70
1	BOOTLID COVER TRIM BOARD			\$259.70
1	TAIL LAMP LH			\$935.40
1	BOOTLID LOCK UPPER			\$224.00
2	BOOTLID LAMP LH/RH	RHx	\$822.00	\$1,644.00
1	BOOTLID H EMBLEM			\$38.00
1	BOOTLID EMBLEM IONID			\$31.80
1	BOOTLID EMBLEM HYBRID			\$24.30
1	BUMPER FOG LAMP			\$201.50
2	BUMPER NUMBER LAMP LH/RH		\$85.30	\$170.60
1	BUMPER HOOK COVER			\$94.60
1	REAR ANTENNA - SMART KEY			\$40.50
1	REAR END PANEL			\$532.00
2	REAR BUMPER BRACKET LH /RH		\$55.80	\$111.60
				\$9,892.35
				20.00%
				\$1,978.47
				DISCOUNTED TOTAL
				\$7,913.88
1	BOOTLID COMFORT APP STICKER			\$40.00
2	BOOTLID COMFORT /TEL NUMBER STICKER		\$30.00	\$60.00
1	BOOTLID ADVERTISEMENT			\$100.00
2	REAR FENDER ADVERTISEMENT LH/RH		\$100.00	\$200.00
1	REAR BUMPER MAT			\$50.00
2	SEALANT WSCREEN		\$23.00	\$46.00
1	REAR NUMBER PALTE W/HOLDER			\$55.00
1	REAR REVERSE SENSOR			\$180.00
				\$697.50
	Labour Charge			
	Panel Beating		700	\$1,050.00
	Spray Painting Charge			\$600.00
	Remove/Refix rear windscreen UPP/LOW		180	\$200.00
	Check wiring and lighting		30	\$60.00
	Tuff Kote		30	\$60.00
	Remove/Refix reverse sensor		30	\$60.00

	TOTAL LABOUR		\$2,030.00
	+		
	ESTIMATE TOTAL		\$10,641.38
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tauphu 97495749
 up 30/6/27 @ 4pm
 L/S Resurvey after repair
 Tauphu @ Lhantow
 3-4 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4344832 JC NO.305521716


CUSTOMER
VMS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
L (R) 65508755 (O)
(P)
COUNT CARD NO.

REGN NO.: SHD4517J	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 30.06.2022 10:40
YR OF MANU. 14.11.2019	TARGET DATE
CHASSIS CODE KMHC851CVLU189762	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 30.06.2022
NATURE: 3P 30.06.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHD4517J CHIANG

Vehicle No.: SHD4517J

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard