

Tauphi

INC

ASSIGNMENT

Veh No: SMA 8182F Yr Regn: 2019 REC

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading 307797. T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDRZF4 30908761

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: (Nil) / S/Rim / STD A/Rim or

	
N/S	O/S
	

Tyre Size: F: 195/65R15

R: 25

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm

L/Bal. 6 mm

DOA _____ D.O.I. 24/6/72

Survey held at Compt. Courcy.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐ : Prelim. Report
☐ : Final Report

Resurvey No. of Trip:

2)

Lump Sum / E.B.: 05

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Transportation:

$$S + RS \rightarrow SI$$

Photos

Others

TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHA8182E

Date: 24.06.2022

Make : Toyota

Insurance: NTUC

Model : Prius

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$ 503.04
10	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER SIDE BRACKET RH			\$ 55.80
1	REAR BUMPER LOWER COVER			\$ 654.96
1	REAR BUMPER TOWING COVER			\$ 82.70
1	TAIL LAMP RH LOWER			\$ 570.00
1	REAR BUMPER SIDE RETAINER RH			\$ 94.80
1	REAR BUMPER REINFORCEMENT			\$ 378.32
1	BACK DOOR GARNISH SUB ASSY			\$ 1,054.71
1	REAR BUMPER REFLECTOR RH			\$ 55.00
1	REAR TRUNK LID LOGO (PRIUS)			\$ 62.14
1	REAR TRUNK LID LOGO (HYBRID)			\$ 62.14
1	REAR TRUNK LID LOGO (TOYOTA STAR)			\$ 81.43
1	REAR WINDSCREEN GLASS WITH MOULDING			\$ 1,884.32
1	REAR TRUNK LID COVER			\$ 1,303.29
1	REAR TRUNK LID GLASS			\$ 1,569.70
	SUB TOTAL			\$ 8,434.35
	LESS 25%			\$ 2,108.59
	DISCOUNTED TOTAL			\$ 6,325.76
	REAR BUMPER RUBBER MAT			\$ 50.00
	REAR TRUNK LID COMFORT & TEL NO. STICKER			\$ 60.00
	REAR TRUNK LID APPS STICKER			\$ 40.00
	REAR BUMPER REVERSE SENSOR			\$ 135.70
				\$ 285.70
	Labour Charge			
	PANEL BEATING			\$ 800.00
	SPRAY PAINTING CHARGE			\$ 800.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 60.00
	CHECK ALL LIGHTING			\$ 80.00
	TUFF KOTE			\$ 50.00
	TOTAL LABOUR			\$ 1,790.00
	ESTIMATE TOTAL			\$ 8,401.46

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Toyota 97495747
 up 24/6/22 5pm
 Lb Resurvey after repair
 LKK Auto Consultants
 2-3 days

Date/Time: 24.06.2022 08:28

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD

Sales Order: 4299126

JC NO305520759

STOMER

MS CITYCAB PTE LTD
STOMER NO. 7010070
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65551188 (O)
(P)


COUNT CARD NO.

REGN NO: SHA8182E	MILEAGE
MAKE: TOYOTA	FUEL E.....1/2.....F
MODEL PRIUS HYBRID(G4A23.06.2022 15:40	DATE/TIME IN
YR OF MANU. 05.12.2019	TARGET DATE
CHASSIS CODE JTDKB3FU303089611	COMPLETION DATE/TIME:

Accident Date: 23.06.2022
NATURE: 3P 23.06.2022

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

No.: **SHA8182E** YY

Vehicle No.: **SHA8182E**

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard