

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

attached.

REPAIR ESTIMATE

DATE: 28.06.2022

MODEL: Hyundai i40

VEHICLE NO.: SH 8948X

LKK -

INSURANCE: NTUC (LHS)

MVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper	1		\$ 1,052.20
	Front Bumper Clips	10	\$ 2.20	\$ 22.00
	Front Bumper Side Bracket RH	1		\$ 22.40
	Front Fender RH	1		\$ 663.00
	Front Fender Shield RH	1		\$ 174.90
	HeadLamp RH	1		\$ 1,388.00
	SUB TOTAL			\$ 3,322.50
	LESS 20% DISCOUNTED TOTAL			\$ 664.50
				\$ 2,658.00
	Labour Charge			
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 300.00
	Check Lightings			\$ 40.00
	Tuff Kote			\$ 40.00
	TOTAL LABOUR			\$ 680.00
	ESTIMATE TOTAL			\$ 3,338.00

de
na
nn
nn
nn
nn
3125.20
2500.16

280
250
30
30
590

3090.16
450 2450
2days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495747
Wps 28/6/22 @ 4:30pm
1/2 Resury after repair
2days
Tanpin @ Kluang

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: