

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH9733S

Make : HYUNDAI

Model : IONIQ(G3)

Date: 23.06.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER REINFORCEMENT BRACKET RH			\$138.10
1	REAR BUMPER FOG LAMP			\$201.50
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	\$111.60
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	BOOTLID			\$2,549.70
1	BOOTLID HYUNDAI PLATE			\$24.30
			988.25	
			790.60	
	SUB TOTAL			\$4,563.25
	LESS 20%			\$912.65
	DISCOUNTED TOTAL			\$3,650.60
	REAR BUMPER RUBBER MAT			\$50.00
	BOOTLID COMFORT TEL NO STICKER		-10%	\$40.00
	BOOTLID COMFORT LOGO STICKER		-10%	\$30.00
	BOOTLID COMFORT APP STICKER		-10%	\$30.00
	REAR BUMPER REVERSE SENSOR		-10%	\$180.00
			280,	
			10% = 252	
			\$N - 50	
			302	
	Labour Charge			350
	PANEL BEATING			\$750.00
	SPRAY PAINTING CHARGE		500	\$600.00
	TUFF KOTE			\$60.00
	REMOVE/REFIX REVERSE SENSOR		880	\$80.00
	TOTAL LABOUR			\$1,490.00
	ESTIMATE TOTAL			\$5,470.60
			\$1972.60	
			2 days	
			*	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfah 97495747
 inv 23/6/22 @ 430pm
 p/p Resurvey kept paint
 tanfah @ 11hantoon
 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: