



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9733S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	DEFORMED	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR BUMPER REINFORCEMENT BRACKET RH	NOT NECESSARY	138.10	-
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
2	REAR BUMPER SIDE BRACKET LH / RH @\$55.80	NOT NECESSARY	111.60	-
1	REAR BUMPER LOWER CTR MOULDING	NOT NECESSARY	155.00	-
1	EMBLEM HYBRID	NECESSARY	24.30	24.30
1	EMBLEM - IONIQ	NECESSARY	31.30	31.30
1	BOOTLID	TO REPAIR SEE LABOUR	2,549.70	-
1	BOOTLID HYUNDAI PLATE	NOT NECESSARY	24.30	-
	LESS 20% DISCOUNT		-912.65	-197.65
			3,650.60	790.60
<u>NETT ITEMS</u>				
1	BOOTLID COMFORT TEL NO STICKER (N)	NECESSARY	40.00	40.00
1	BOOTLID COMFORT LOGO STICKER (N)	NECESSARY	30.00	30.00
1	BOOTLID COMFORT APP STICKER (N)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (N)	NECESSARY	180.00	180.00
	LESS 10% DISCOUNT		-	-28.00
			280.00	252.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
			50.00	50.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOTLID.		750.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00

Report Ref No. NS/INC22006565/Tce2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE. REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	60.00 80.00 1,490.00	- 30.00 880.00
GRAND TOTAL			5,470.60	1,972.60
RECOMMENDED COST OF REPAIRS (CONFIRMED)				1,972.60

Report Ref No. NS/INC22006565/Tce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.