

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH9733S

Make : HYUNDAI

Model : IONIQ(G3)

Date: 23.06.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$459.40
10	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER REINFORCEMENT BRACKET RH			\$138.10
1	REAR BUMPER FOG LAMP			\$201.50
2	REAR BUMPER SIDE BRACKET LH RH		\$55.80	\$111.60
1	REAR BUMPER LOWER CTR MOULDING			\$155.00
1	EMBLEM HYBRID			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	BOOTLID			\$2,549.70
1	BOOTLID HYUNDAI PLATE			\$24.30
	SUB TOTAL			\$4,563.25
	LESS 20%			\$912.65
	DISCOUNTED TOTAL			\$3,650.60
	REAR BUMPER RUBBER MAT			\$50.00
	BOOTLID COMFORT TEL NO STICKER	-10%		\$40.00
	BOOTLID COMFORT LOGO STICKER	-10%		\$30.00
	BOOTLID COMFORT APP STICKER	-10%		\$30.00
	REAR BUMPER REVERSE SENSOR	-10%		\$180.00
				\$330.00
	Labour Charge			
	PANEL BEATING			350 \$750.00
	SPRAY PAINTING CHARGE			250 \$600.00
	TUFF KOTE			\$60.00
	REMOVE/REFIX REVERSE SENSOR			30 \$80.00
	TOTAL LABOUR			\$1,490.00
	ESTIMATE TOTAL			\$5,470.60

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taufik 97495747
 inv 23/6/22 @ 430pm
 p/p Resurvey before paint
 Taufik @ Khanthawon
 02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 23.06.2022 10:47

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4299007

JC NO 305520717

CUSTOMER
COMFORT TRANSPORTATION PTE LTD
7010045
CUSTOMER NO.
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL. (R) 65508755 (O)
(P)


REGN NO. SH 9733S	MILEAGE
MAKE HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 22.06.2022 23:15
YR OF MANU. 31.03.2022	TARGET DATE
CHASSIS CODE KMHC851CVLU194740	COMPLETION DATE/TIME:

DISCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 22.06.2022
NATURE: 3P 22.06.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

ame:
C No.:
ehicle No.: SH 9733S YY

Vehicle No.: SH 9733S

ame of Service Advisor

Signature/Date

Name of Service Advisor

Date

to be returned to Service Reception upon collection

To be kept by Security Guard