

ASS. REG. BY: Taufikh

REF:

INC NS/INC22006566/Tqc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: Lim TS Vehicle: IN / OUT

Veh No: SHA2551M Yr Regn: 2019, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Lang CC 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 523483 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHC851CVICU141828

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Oil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Workshop

Front R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at Langkat Langkat

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rt N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh finalised LS \$2700, 2 days. (Red \$2261.40, 46%)

Date/Time, File Pass to? : Preli. Report : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
S + RS, \$	
Photos	
Others	
TOTAL	

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Report Format: TP

Lump Sum / ~~Est. Cost~~ 2700

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 30.06.2022

MODEL: Hyundai Ioniq

VEHICLE NO.: SHA2551M

INSURANCE: NTUC (LKS)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Frt Fender LH	1		\$ 588.80 <i>Ry</i>
	Frt Fender Shield LH	1		\$ 164.70 <i>X</i>
	Frt Fender Blue-Drive LH	1		\$ 26.60 <i>ndc</i>
	Frt Wheel Cap LH	1		\$ 346.40 <i>cut</i>
	Headlamp LH	1		\$ 1,993.65 <i>cut</i>
	Frt Bumper	1		\$ 481.10 <i>de</i>
	Frt Bumper Upper Moulding	1		\$ 368.50 <i>Ry</i>
	Frt Bumper Side Bracket LH	1		\$ 35.00 <i>T</i>
	Frt Bumper Clips	10	\$ 2.20	\$ 22.00 <i>wr</i>
	SUB TOTAL			\$ 4,026.75
	LESS 20%			\$ 805.35
	DISCOUNTED TOTAL			\$ 3,221.40
	Frt Fender Adv.Sticker LH	1		\$ 100.00 NETT <i>ml</i>
	Labour Charge			
	Panel Beating			\$ 800.00 <i>350</i>
	Spray Painting Charge			\$ 600.00 <i>500</i>
	Check Lightings			\$ 60.00 <i>30</i>
	Tuff Kote			\$ 60.00 <i>X</i>
	Wheel Alignment			\$ 120.00 <i>BD</i>
	TOTAL LABOUR			\$ 1,640.00
	ESTIMATE TOTAL			\$ 4,961.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanji 9749 5749
wr 30/6/22 @ 330pm
2 delays
43 Henry after repair
Tanji & Ikhana for work

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4344817

JC NO305521713

CUSTOMER NAME: COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) COUNT CARD NO.	REGN NO.: SHA2551M	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: IONIQ(G2)	DATE/TIME IN 30.06.2022 11:40
	YR OF MANU. 18.04.2019	TARGET DATE
	CHASSIS CODE KMHC851CVKU141828	COMPLETION DATE/TIME:

Accident Date: 30.06.2022
NATURE: 3P 30.06.2022/C

C


JOB DESCRIPTION

45
NTUC

PD
9595E

S/NO LABOR CODE
00010 PB

DESCRIPTION
PANEL BEATING-SHA2551M-TP



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

Vehicle No.: **SHA2551M**

LIMITS

Vehicle No.:

SHA2551M

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard