

**REPAIR ESTIMATE**

Effective Date: 1 Nov 2020

DATE: 30.06.2022  
 MODEL: Hyundai Ioniq  
 VEHICLE NO.: SHA2551M

LKK -  
 INSURANCE: NTUC (LIS)  
 MVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Frt Fender LH	1		\$ 588.80 <i>Ry</i>
	Frt Fender Shield LH	1		\$ 164.70 <i>Xny</i>
	Frt Fender Blue-Drive LH	1		\$ 26.60 <i>ndc</i>
	Frt Wheel Cap LH	1		\$ 346.40 <i>cut</i>
	Headlamp LH	1		\$ 1,993.65 <i>cut</i>
	Frt Bumper	1		\$ 481.10 <i>de</i>
	Frt Bumper Upper Moulding	1		\$ 368.50 <i>Ry</i>
	Frt Bumper Side Bracket LH	1		\$ 35.00 <i>Xny</i>
	Frt Bumper Clips	10	\$ 2.20	\$ 22.00 <i>net</i>
	<b>SUB TOTAL</b>			\$ 4,026.75 <i>2869.75</i>
	<b>LESS 20% DISCOUNTED TOTAL</b>			\$ 805.35 <i>2295.80</i>
				<b>\$ 3,221.40</b>
	Frt Fender Adv.Sticker LH	1		\$ 100.00 <b>NETT</b> <i>nt</i>
	<b>Labour Charge</b>			
	Panel Beating			\$ 800.00 <i>350</i>
	Spray Painting Charge			\$ 600.00 <i>500</i>
	Check Lightings			\$ 60.00 <i>80</i>
	Tuff Kote			\$ 60.00 <i>Xny</i>
	Wheel Alignment			\$ 120.00 <i>BD</i>
	<b>TOTAL LABOUR</b>			\$ 1,640.00 <i>960</i>
	<b>ESTIMATE TOTAL</b>			\$ 4,961.40 <i>3355.80</i>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Tanji 9749 5749*  
*up 30/6/22 @ 330 pm*  
*2 days*  
*43 Mary at the repair*  
*Tanji & Mhanfo. wh*

*2 days*  
*4592700*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: