



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205756

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 19/09/2022
Reference CC6/CTI22006569/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SMZ 6435Z
Insured Veh. GBA 1161H
Claim No. SNM22D204885/C02
Policy No. DMCVSNA00012982200
Accident Date 10/07/2022
Inspection Date 12/07/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22006569/Upa3q2 Date: 19/09/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 1161H	Veh. Inspected	SMZ 6435Z	
Policy No.	DMCVSNA00012982200	Coverage (\$)	0.00	
Claim No.	SNM22D204885/C02	Excess (\$)	0.00	
Assign From		Assign Date	12/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	MINI COOPER S (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	WMWSV32040T151539	Colour	BLUE	
Odometer	76234 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/45 R17	MICHELIN	6 mm	
L/H Front Tyre	205/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	205/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	205/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/07/2022	Inspection Date	12/07/2022	
Survey held at	LC AUTOMOTIVE BLOCK 10 SIN MING IND.ESTATE , SECTOR C #01-20 SINGAPORE 575645			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 6435Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID INNER TRIM BOARD	NOT NECESSARY	688.00	-
1	BOOT LID	BADLY DENTED	1,655.00	1,466.20
1	BOOT LID BODY STICKER	NECESSARY	400.00	245.00
1	BOOT LID INNER RUBBER	NOT NECESSARY	228.00	-
1	REAR BOOT LID COOPER LOGO	NECESSARY	55.00	55.00
1	REAR BOOT LID S LOGO	NECESSARY	35.00	35.00
1	REAR BOOT LID LOGO	NECESSARY	95.00	58.00
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BUMPER	DISTORTED	1,485.00	945.00
1	REAR BUMPER LOWER GRILLE	TORN	388.00	355.00
1	REAR BUMPER LOWER GARNISH /COVER	TORN	412.00	412.00
2	REAR BUMPER SIDE BRACKET @\$215.00	BENT	430.00	230.00
2	REAR BUMPER LOWER SIDE LAMP @\$412.00	CRACKED	824.00	824.00
2	REAR BUMPER LOWER SIDE LAMP COVER GARNISH @ \$285.00	TWISTED	570.00	570.00
1	SET REAR BUMPER CLIPS	NECESSARY	65.00	50.00
4	REAR BUMPER REVERSE SENSOR @\$190.00	SHORTED (2 PCS ONLY)	760.00	380.00
1	REAR BUMPER REINFORCEMENT	BENT	770.00	595.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	112.00	-
2	REAR TAIL LAMP @\$788.00	NOT NECESSARY	1,576.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	780.00	-
1	REAR BUMPER TOP GARNISH	NOT NECESSARY	560.00	-
1	REAR END PANEL INNER LOCK	TWISTED	358.00	285.00
2	REAR EXHAUST CHROME PIPE @\$325.00	SERVICEABLE	650.00	-
1	REAR EXHAUST HEATSHIELD	BENT	112.00	112.00
	LESS 10% DISCOUNT		-	-661.72
			13,058.00	5,955.48

Report Ref No. CC6/CTI22006569/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
			50.00	40.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX CUSHION GARNISH .		120.00	80.00
	TO REMOVE & REFIX REAR WINDSCREEN .		120.00	120.00
	TO REMOVE & REPLACED REVERSE SENSOR .		120.00	50.00
	TO CHECK WIRING SYSTEM.		80.00	20.00
	TO REMOVE & REFIX REAR EXHAUST CHROME PIPE .		120.00	60.00
	TO REMOVE & REFIX REAR BODY STRIKER .	NOT NECESSARY	180.00	-
	TUFF KOTE.		120.00	40.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,000.00	600.00
	SPRAY PAINTING.		1,000.00	800.00
			2,860.00	1,770.00
GRAND TOTAL			15,968.00	7,765.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,200.00

Report Ref No. CC6/CTI22006569/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 6435Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 6435Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMZ 6435Z

RE-INSPECTION

