

MSIAUTOM

LC AUTOMOTIVE

25 KAKI BUKIT ROAD 4 #05-26 Synergy @ KB Singapore 417800

YONG WEE LOON
25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

not authorized
11/7/22
1/5 \$6200
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No third modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

11th JULY 2022
Acknowledged by Repairer
Signature:
Date:

Accident date: 10th JULY 2022

Estimated repair cost for vehicle no: SMZ6435Z MINI COOPER

S/n	Qty	Items	U/price	Amount	
1	1	boot lid inner trim board		\$688.00	X
2	1	boot lid	1466.20	\$1,655.00	✓
3	1	boot lid body sticker	245.00	\$400.00	✓
4	1	boot lid inner rubber		\$228.00	X
5	1	Rear boot lid Cooper logo		\$55.00	✓
6	1	Rear boot lid S logo		\$35.00	✓
7	1	Rear boot lid emblem logo	58	\$95.00	✓
8	1	Rear boot lid number plate		\$50.00	X
9	1	Rear bumper	945	\$1,485.00	✓
10	1	rear bumper lower grille	355	\$388.00	✓
11	1	Rear bumper lower garnish/ cover		\$412.00	✓
12	2	Rear bumper side bracket	115x2-230	\$215.00	✓
13	2	Rear Bumper lower side lamp		\$412.00	✓
14	2	Rear Bumper lower side lamp cover / chrome garnish		\$285.00	✓
15	1	Rear bumper clips	50	\$6.50	✓
16	4	Rear bumper reverse sensor		\$190.00	2pc
17	1	Rear bumper reinforcement	595	\$770.00	✓
18	1	Rear Bumper towing cover		\$112.00	X
19	2	Rear tail lamp		\$788.00	X
20	1	Rear end panel		\$780.00	X
21	1	Rear end panel top garnish		\$560.00	X
22	1	Rear End Panel inner lock	285	\$358.00	✓
23	2	rear exhaust chrome pipe		\$325.00	X
24	1	rear exhaust heatshield		\$650.00	X
Subtotal :-				\$12,946.00	

Labour charges

To remove & re-fix cushion garnish	\$120.00	80
To remove & re-fix rear windscreen	\$120.00	✓
Remove Rear windscreen sealant replaced	\$50.00	40 s/n
To remove & re-fix reverse sensor	\$120.00	50
To check wiring system	\$80.00	20
to remove & Refix rear exhaust chrome pipe	\$120.00	60
To Remove & Refix rear body striker	\$180.00	X
Tuff kote	\$120.00	40
Panel beating	\$1,000.00	600
Spray painting	\$1,000.00	800

Subtotal :- \$2,910.00
Total:- \$15,856.00

p-6617-2
102
5-955-48