

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

HSiao Tony

Not Authorized
LKH
12/7/22
1/5 \$5700
4 days

VEHICLE No: SKZ 8286Y

1PC	FRONT BUMPER	se/torn	762.40	\$985.20	✓
1PC	FRONT BUMPER LOWER	11		\$650.00	X
1PC	FRONT BUMPER SIDE RETAINER O/S	one		\$66.50	✓
1SET	FRONT BUMPER CLIPS	new		\$50.00	✓
1PC	HEADLAMP O/S	one	1929.10	\$1,959.20	✓
1PC	FRONT FENDER O/S	Bent	545.20	\$788.10	✓
1PC	FRONT FENDER OUTER PROTECTOR O/S	Dis	280.40	\$388.50	✓
1PC	FRONT FENDER INNER SHIELD O/S	torn	192.50	\$315.10	✓
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	new		\$50.00	✓
1PC	FRONT DOOR O/S	R		\$1,109.20	X
1PC	FRONT DOOR MIRROR ASSY O/S	11		\$850.00	X
1PC	FRONT SHOCK ABSORBER O/S	Bent	398.20	\$655.10	✓
1PC	FRONT KNUCKLE ARM O/S	Bent	544.30	\$599.20	✓
1PC	FRONT KNUCKLE ARM BEARING O/S	new	266.20	\$350.00	✓
1PC	FRONT LOWER ARM O/S	Bent		\$588.20	✓
1PC	BONNET	R		\$1,280.30	X
1PC	FRONT SPORT RIM O/S	waged		\$1,100.00	600 S/N
1PC	ROCKER PANEL GARNISH O/S	torn		\$750.00	✓
			(20% 550)	\$12,534.60	

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$80.00	30
TO CONDUCT WHEEL ALIGNMENT	\$120.00	80
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$200.00	120
TO RESET & REPROGRAMME SYSTEM	11 \$120.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$600.00	500
TO PUTTY & SPRAY PAINTING	\$900.00	800
TOTAL	\$14,604.60	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

6223
202
4978.40
600
1550
7128.40
202
5702