

AUTOWERKS

ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

14 July 2022

REG NO.: SKP 8836 M
MAKE/MODEL: TOYOTA COROLLA ALTIS

not authorized
17/7/22
2/5 @ 8700/
12 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding	\$ 156.80
1	Rear boot lid	\$ 985.70
2	Rear boot hinges	\$ 171.40 X
1	Rear boot inner trim	\$ 188.50 X
1	Rear boot inner trim clip (1 set)	\$ 50.00 X
2	Rear boot lamps	\$ 577.40
1	Rear boot lock	\$ 100.80
1	Rear boot lock catch	\$ 60.30 X
1	Rear boot logo	\$ 89.70
1	Rear boot rubber	\$ 145.70
1	Rear boot "COROLLA" emblem	\$ 80.30
1	Rear boot "ALTIS" emblem	\$ 75.70
1	Rear boot outer chrome moulding	\$ 288.50
2	Rear taillamps	\$ 760.20
2	Rear taillamp panels	\$ 775.40 X
1	Rear end panel	\$ 777.40
1	Rear end panel inner garnish	\$ 200.30
1	Rear keyless sensor	\$ 185.20
1	Rear bumper	\$ 688.70
2	Rear bumper top brackets	\$ 181.80
2	Rear bumper side brackets	\$ 97.00
2	Rear bumper reflectors	\$ 120.20 X
1	Rear bumper reinforcement	\$ 344.70
2	Rear bumper reinforcement stays	\$ 161.00
2	Rear bumper side retainers	\$ 130.00
2	Rear bumper PDC sensors	\$ 390.00
2	Rear number plate lamps	\$ 96.00 X
1	Rear spare tyre board	\$ 363.50
1	Rear spare tyre panel	\$ 1,100.70
1	Rear exhaust silencer	\$ 881.70 X
2	Rear exhaust mountings	\$ 97.20 X
2	Rear fenders	\$ 2,241.40 lpc
1	Rear fender air gate	\$ 87.50 X
2	Rear fender inner shields	\$ 249.20 lpc
2	Rear fender inner trims	\$ 670.80 lpc
		\$ 13,570.70
Less 25%		\$ 3,392.68
		\$ 10,178.03

SPECIAL NETT ITEMS

- | | |
|---|--------------------------------------|
| 1 | Rear windscreen sealant |
| 1 | Rear bumper clip (1 set) |
| 1 | Rear number plate with holder |
| 2 | Rear fender inner trim clips (2 set) |

\$	RM	80.00	40
\$	RM	50.00	/
\$	Bent	50.00	40
\$	RM	90.00	X
\$		270.00	

S/N

LABOUR CHARGES

- | | |
|----|--|
| 1 | To remove, replaced damaged lamps and check up rear wiring. |
| 2 | To remove and refit inner garnishes. |
| 3 | To remove and refit rear reverse sensor. |
| 4 | To transfer boot lid mechanism and wiring assembly. |
| 5 | To remove and refit fuel tank assembly with all attachments. |
| 6 | To remove and refit rear windscreen glass. |
| 7 | To remove, refit and replace exhaust silencer and mountings. |
| 8 | To apply undercoating. |
| 9 | Panel beating. |
| 10 | To re-spray painting on the affected areas. |

\$	80.00	30
\$	150.00	80
\$	150.00	50
\$	120.00	60
\$	150.00	60
\$	180.00	120
\$	150.00	60
\$	200.00	120
\$	2,400.00	2000
\$	2,200.00	1200
\$	5,780.00	

GRAND TOTAL :

\$	16,228.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9308.2
25%
6981.15
130
3780
10891.15