

C

Келлет

ASSIGNMENT

Veh No: SHC 8490E Yr Regn: 11/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai i40 C.C. 1685

Colour 1. Blue A/C: Insured / Std / NI / NA

Sp. Reading **666 P36** T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHUB 41UMG 4080563

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/80R16
R: _____

	N/S	O/S	

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 7/7/22 D.O.I. 12/7/2022

Survey held at

Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1	GIA & EH not regy. Awest for BV.
13/2	L1 Rm @ 3550h
27/3	L1 Rm @ 540d Conhr

☐: Prel. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) $S - RS$ SI

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$

: Site Insp (\$

: Interview (\$

Tech Invs (\$

Weekend (\$)

2. Others

1992

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

Not Notation

11/10/87

Permy After Sales

Required Book Value

7 days

DATE: 12-Jul-22

INSURANCE:

MODEL: HYUNDAI I40

VEHICLE NO.: SHC 8490 E

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR FENDER (LH)	1	\$ 2,171.40	\$2,171.40
REAR DOOR (LH)	1	\$2,707.70	\$2,707.70
REAR DOOR RUBBER (LH)	1	\$ 280.50	\$280.50
REAR DOOR REGULATOR (LH)	1	\$ 660.90	\$660.90
REAR DOOR POWER WINDOW MOTOR	1	\$ 386.20	\$386.20
REAR DOOR LOCK ASSY	1	\$ 468.20	\$468.20
REAR DOOR HINGE UPPER (LH)	1	\$ 114.50	\$114.50
REAR DOOR HINGE LOWER (LH)	1	\$ 123.50	\$123.50
REAR DOOR CHECK (LH)	1	\$ 92.90	\$92.90
REAR DOOR OUTER MOULDING (LH)	1	\$ 176.80	\$176.80
ROCKER PANEL OUTER GARNISH (LH)	1	\$ 732.80	\$732.80
FRONT BUMPER COVER	1	\$ 1,052.20	\$1,052.20
FRONT BUMPER GRILLE (LH)	1	\$ 149.20	\$149.20
FRONT BUMPER BRACKET TOP (LH)	1	\$ 44.80	\$44.80
FRONT BUMPER BRACKET (LH)	1	\$ 49.20	\$49.20
FRONT BUMPER RETAINER MOUNTING LH	1	\$ 76.20	\$76.20
FRONT BUMPER GRILLE AIR DUCT (LH)	1	\$ 126.20	\$126.20
HEADLAMP SUPPORT PANEL ASSY	1	\$ 907.40	\$907.40
HEADLAMP (LH)	1	\$ 2,776.00	\$2,776.00
HEADLAMP SUPPORT TOP COVER	1	\$ 222.60	\$222.60
FRONT FENDER (LH)	1	\$ 663.00	\$663.00
FRONT FENDER APRON PANEL (LH)	1	\$ 637.00	\$637.00
FRONT FENDER SHIELD (LH)	1	\$ 174.90	\$174.90
FRONT DOOR MIRROR ASSY (LH)	1	\$ 893.50	\$893.50
FRONT DOOR (LH)	1	\$2,707.70	\$2,707.70
FRONT DOOR RUBBER	1	\$ 290.50	\$290.50
FRONT DOOR GEAR/REGULATOR (LH)	1	\$ 776.80	\$776.80
FRONT DOOR POWER MOTOR (LH)	1	\$ 172.70	\$172.70
FRONT DOOR POWER MOTOR (RH)	1	\$ 296.40	\$296.40
FRONT DOOR HINGE UPPER (LH)	1	\$ 113.60	\$113.60
FRONT DOOR HINGE LOWER (LH)	1	\$ 125.70	\$125.70
FRONT DOOR CHECK (LH)	1	\$ 91.80	\$91.80
FRONT DOOR INNER LOCK (LH)	1	\$ 490.80	\$490.80
FRONT DOOR OUTER MOULDING (LH)	1	\$ 153.10	\$153.10
FRONT WHEEL RIM (LH)	1	\$ 650.60	\$650.60
FRONT WHEEL HUB CAP (LH)	1	\$ 214.20	\$214.20
KNUCKLE ARM (LH)	1	\$ 1,104.00	\$1,104.00
FRONT WHEEL BEARING AND HUB (LH)	1	\$ 863.80	\$863.80
FRONT SUSPENSION LOWER ARM (LH)	1	\$ 595.90	\$595.90
FRONT SHOCK ABSORBER ASSY (LH)	1	\$ 684.40	\$684.40
FRONT SHOCK ABSORBER MOUNTING (LH)	1	\$ 217.60	\$217.60
STG TIE ROD (LH)	1	\$ 186.40	\$186.40
STG TIE END (LH)	1	\$ 125.20	\$125.20

STABILIZER BAR ASSY	1	\$ 463.70	\$463.70
STABILIZER BAR LINK (LH)	1	\$ 85.90	\$85.90
FRONT DRIVE SHAFT (LH)	1	\$ 2,061.60	\$2,061.60
RACK & PINION ASSY	1	\$ 1,820.00	\$1,820.00
SUB TOTAL			\$29,980.00
LESS 20%			\$5,996.00
DISCOUNTED TOTAL			\$23,984.00
Rear Door Comfortdelgro & Apps Sticker(LH)	1	\$ 80.00	\$ 80.00
FRONT DOOR COMFORT LOGO (LH)	1	\$ 75.00	\$75.00
FRONT TYRE (LH)	1	\$ 216.00	\$216.00
SUB TOTAL			\$ 371.00
Labour Charge			
Panel Beating	1	\$ 2,200.00	\$2,200.00
Spray Painting Charge	1	\$ 1,800.00	\$1,800.00
Wiring Charge	1	\$ 100.00	\$100.00
Tuff Kote	1	\$ 100.00	\$100.00
Towing Charge	1	\$ 80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear	1	\$ 150.00	\$150.00
Remove/Refix Fuel Tank	1	\$ 150.00	\$150.00
Transfer of Door Mechanism FRONT	1	\$ 80.00	\$80.00
Re-set Frt Power Window System	1	\$ 200.00	\$200.00
Transfer of Door Mechanism REAR	1	\$ 80.00	\$80.00
Re-set Rear Power Window System	1	\$ 200.00	\$200.00
Four Wheel Alignment	1	\$ 120.00	\$120.00
Remove/Refix Undercarriage (Frt)	1	\$ 400.00	\$400.00
Remove/Refix Radiator	1	\$ 90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$ 130.00	\$130.00
Diagnostic & Resetting To Erase Fault Code	1	\$ 550.00	\$550.00
TOTAL LABOUR			\$6,430.00
ESTIMATE TOTAL			\$ 30,785.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: