



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22006584/Gvy3m4	
			Date: 15/09/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SBS 3441S	Veh. Inspected	SMU 9008E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D22002085MFBP	Excess (\$)	0.00	
Assign From	JOANNE TAN JO ANN	Assign Date	12/07/2022	
2. Vehicle Particulars & Condition				
Make & Model	MINI COOPER CLUBMAN 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WMWML32070TM97180	Colour	WHITE	
Odometer	178254 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R16	PIRELLI	6 mm	
L/H Front Tyre	195/55 R16	PIRELLI	6 mm	
R/H Rear Tyre	195/55 R16	PIRELLI	6 mm	
L/H Rear Tyre	195/55 R16	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/07/2022	Inspection Date	20/07/2022	
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	