

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO.201006949C

M/S : MS FIRST CAPITAL INSURANCE LIMITED

6 Raffles Quay

#21-00

Singapore 048580

TEL: 62222311

ATTN: Motor Claim Department

Your Ref No:

TP 0722-6889

Claim Type:

Third Party

Accident Date:

07/07/2022

TP Veh Reg No:

SBS34418

Estimate No: **EST1508359**

Date: 08 Jul 2022

Policy No: 2070010315-02

Veh Reg No: **SMU9008E**

Make/Model: MINI COOPER

CLUBMAN 1.6 AT ABS

D/AB 2WD 5DR

Chassis No: **WMWML32070TM97180**

Engine No: A2461320

Reg. Date: 04/02/2010

LKK Auto Care 62223547
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modifications is allowed
 • Supplementary part(s) must be resurveyed and
 is subject to final approval from Insurance Company
 I acknowledge by Repairer
 Signature:
 Date:

Estimate Repair Cost to Vehicle No :SMU9008E

Description	U/Price	Quantity	Price S\$	Amount S\$
Spare Parts				
1 SIDE MIRROR ASSY- LH <i>crk</i>	585.0000	1 PC	585.00	
2 FRONT DOOR -LH <i>Buc</i>	680.0000	1 PC	680.00	
3 FRONT DOOR RUBBER - LH	900.0000	1 PC	900.00	
4 FRONT DOOR OUTER HANDLE - LH <i>cat</i>	100.0000	1 PC	100.00	
5 FRONT DOOR LOCK - LH <i>?</i>	320.0000	1 PC	320.00	
6 FRONT DOOR REGULATOR GEAR - LH <i>?</i>	520.0000	1 PC	520.00	
7 FRONT DOOR REGULATOR GEAR MOTOR - LH <i>?</i>	220.0000	1 PC	220.00	
8 FRONT DOOR OUTER CHANNEL CHROME -LH <i>X nn</i>	95.0000	1 PC	95.00	
9 REAR FENDER - LH <i>Repair X</i>	1,150.0000	1 PC	1,150.00	
10 REAR FENDER OUTER CHANNEL CHROME -LH <i>X nn</i>	95.0000	1 PC	95.00	
11 REAR FENDER OUTER WHEEL ARCH GARNISH -LH <i>sur</i>	155.0000	1 PC	155.00	
12 ROCKER PANEL SIDE GARNISH -LH <i>X nn</i>	260.0000	1 PC	260.00	
			5,080.00	
	Less 10%		508.00	4,572.00
Labour				
13 TO KNOCK OUT DENTS, LH B PILLAR, REAR FENDER LH, REMOVE, REPLACE ACCIDENT PARTS	980.0000	1 JOB	980.00	<i>500</i>
14 TO RESPRAY PAINT ON ACCIDENT PORTIONS. PEARL	600.0000	1 JOB	600.00	<i>400 450</i>
15 PAINT MATERIALS	38.0000	1 JOB	38.00	<i>X</i>
16 TO TUFF-KOTE	30.0000	1 JOB	30.00	<i>/</i>
17 TO RESET CHECK LIGHT	70.0000	1 JOB	70.00	<i>X</i>
18 TO 4 WHEEL ALIGNMENT	75.0000	1 JOB	75.00	<i>60</i>
			1,793.00	1,793.00
			Total	S\$ 6,365.00
			Add GST @ 7%	445.55
			Total Amount Payable	S\$ 6,810.55

TOTAL: SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED TEN AND CENTS FIFTY FIVE ONLY

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

*5 Days. p/p before paint photo.
 After repair photo.
 Gino Ricop
 2017/22*

[Signature]