

ASS. REC. BY:

REF:

AIG/ 22006585/1K

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

1.B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNB 69720

Yr Regn:

09, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pionts

c.c

1497

Colour:

M. Brown

Sp. Reading:

89663

A/C: Insured / Std / NI / NA

Eng/No:

T/Radio: Insured / Std / NI / NA

C/No:

JTD 88914320L 000807

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Wanli

Front

Rear

R/Bal.

2

mm

R/Bal.

3

mm

L/Bal.

2

mm

L/Bal.

3

mm

D.O.A.

7/7/22

D.O.I.

8/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got BZ

15/7 83718.53 Celine

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

: Fuel

: Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Not Withstand  
Preserving B4 paint

LAD2207-

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SNB6972D**

83718.53

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

08 JUL 2022

**SNB6972D**

JTDZZ9H320L000807

201603575K

TOYOTA

SIENTA

07/07/2022

**SJS6665Z/AIG**

08/09/2021

| PART                                           | LIST          |
|------------------------------------------------|---------------|
| 1 COVER, REAR BUMPER                           | \$ 321.20 ✓   |
| 1 EXTENSION, RR BUMPER                         | \$ 191.80 ✓   |
| 1 EXTENSION, REAR BUMPER SIDE, LH              | \$ 130.30 X   |
| 1 EXTENSION, REAR BUMPER SIDE, RH              | \$ 130.30 ✓   |
| 1 RETAINER, REAR BUMPER SIDE, LH               | \$ 71.10 X    |
| 1 RETAINER, REAR BUMPER SIDE, RH               | \$ 71.10 X    |
| 1 CUSHION, REAR BUMPER                         | \$ 26.40 X    |
| 1 SEAL, REAR BUMPER SIDE, LH                   | \$ 61.60 X    |
| 1 SEAL, REAR BUMPER SIDE, RH                   | \$ 61.60 X    |
| 1 PANEL, BODY LOWER BACK, OUTER                | \$ 438.20 ✓   |
| 1 PANEL SUB-ASSY, BODY LOWER BACK              | \$ 702.90 X   |
| 1 COVER, LUGGAGE COMPARTMENT TRIM BOX          | \$ 407.30 X   |
| 1 RAIL SUB-ASSY, SLIDE DOOR, CENTER LH         | \$ 303.50 X   |
| 1 PANEL SUB-ASSY, BACK DOOR                    | \$ 1,142.50 ✓ |
| 1 BOARD SUB-ASSY, DECK                         | \$ 704.50 X   |
| 1 EMBLEM, BACK DOOR, NO.1 LOGO                 | \$ 68.20 ✓    |
| 1 EMBLEM, BACK DOOR 'HYBRID SYNERGY DRIVE'     | \$ 52.50 ✓    |
| 1 BOARD, REAR FLOOR, NO.1                      | \$ 671.00 X   |
| 1 BOARD ASSY, REAR FLOOR, NO.2                 | \$ 282.70 X   |
| 1 BOX, DECK FLOOR, REAR                        | \$ 674.80 X   |
| 1 COVER, DECK TRIM, REAR                       | \$ 183.40 X   |
| 1 BOARD ASSY, BACK DOOR TRIM                   | \$ 139.20 X   |
| 1 STAY ASSY, BACK DOOR, RH                     | \$ 244.90 X   |
| 1 STAY ASSY, BACK DOOR, LH                     | \$ 244.90 X   |
| 1 HINGE ASSY, BACK DOOR, UPPER                 | \$ 61.60 X    |
| 1 PAD, BACK DOOR HINGE, NO.1                   | \$ 4.60 X     |
| 1 LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH | \$ 472.40 X   |

**Trans-cab Auto Services Pte Ltd****LAD2207-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SNB6972D**

|                                        |           |                  |   |
|----------------------------------------|-----------|------------------|---|
| 1 STRIKER ASSY, BACK DOOR LOCK         | \$        | <i>na</i> 26.10  | X |
| 1 FRAME ASSY, RR                       | \$        | <i>na</i> 212.00 | X |
| 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE | \$        | <i>na</i> 210.30 | X |
| <b>TOTAL</b>                           | <b>\$</b> | <b>8,312.90</b>  |   |
| <b>25%</b>                             | <b>\$</b> | <b>2,078.23</b>  |   |
|                                        | <b>\$</b> | <b>6,234.68</b>  |   |

**Special Nett**

|                                   |           |                   |             |
|-----------------------------------|-----------|-------------------|-------------|
| 1SET PARKING AID                  | \$        | <i>na</i> 700.00  | X           |
| 1SET REAR BUMPER CLIP             | \$        | <i>na</i> 95.00   | <i>60na</i> |
| 2 WINDSCREEN SEALANT              | \$        | <i>na</i> 150.00  | <i>40na</i> |
| 1 WINDSCREEN MOULDING             | \$        | <i>na</i> 200.00  | ✓           |
| 1 WINDSCREEN INNER SPONGE SEAL    | \$        | <i>na</i> 130.00  | <i>30na</i> |
| 1 REAR BUMPER PROTECTOR           | \$        | <i>nsp</i> 180.00 | X           |
| 1SET REAR BUMPER RETAINER CLIP    | \$        | <i>na</i> 85.00   | X           |
| 1 END PANEL TRIM CLIP             | \$        | <i>na</i> 65.00   | X           |
| 1 REAR NUMBER PLATE WITH MOULDING | \$        | <i>na</i> 200.00  | X           |
| <b>TOTAL</b>                      | <b>\$</b> | <b>1,805.00</b>   |             |
| <b>TOTAL PARTS</b>                | <b>\$</b> | <b>8,039.68</b>   |             |

**LABOUR**

|                                                                                                                           |    |                  |             |
|---------------------------------------------------------------------------------------------------------------------------|----|------------------|-------------|
| To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.                                                    | \$ | 300.00           | <i>120l</i> |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | 380.00           | <i>60l</i>  |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 2,200.00         | <i>600l</i> |
| To transfer of rear end panel fittings, attachment and perform water seepage test.                                        | \$ | <i>na</i> 380.00 | X           |
| To transfer of Tailgate fittings, attachments and perform water seepage test.                                             | \$ | 180.00           | <i>60l</i>  |
| To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.                   | \$ | 480.00           | <i>20l</i>  |

**Trans-cab Auto Services Pte Ltd**

LAD2207-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SNB6972D

|                                                                                                       |    |               |          |             |
|-------------------------------------------------------------------------------------------------------|----|---------------|----------|-------------|
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                       | \$ | <i>nn</i>     | 380.00   | <i>X</i>    |
| To check steering geometry and computer wheel alignment                                               | \$ | <i>nn</i>     | 220.00   | <i>X</i>    |
| To Rust-Proofing and apply undercoat Of The Affected Areas.                                           | \$ |               | 250.00   | <i>60%</i>  |
| Putty And Spray Painting Of The Affected Portion.                                                     | \$ |               | 2,200.00 | <i>660%</i> |
| To reinstall rear bumper parking sensor.                                                              | \$ |               | 170.00   | <i>50%</i>  |
| To Check Electrical Lighting Concerned.                                                               | \$ | <i>Repair</i> | 170.00   | <i>X</i>    |
| To transfer of luggage floor panel fittings, attachment and perform water seepage test.               | \$ | <i>nn</i>     | 380.00   | <i>X</i>    |
| To transfer of tire, rim and on wheel balancing.                                                      | \$ | <i>nn</i>     | 220.00   | <i>X</i>    |
| To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators. | \$ | <i>nn</i>     | 380.00   | <i>X</i>    |

**TOTAL \$ 8,290.00****Over All Total \$ 16,329.68****(PART-BY-PART) Repair Days****~~25~~ DAYS***5 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: