



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2203666

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 14/06/2022
Reference CS3/GRB22005470/Gty3e2
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SLB 3503T

Bill cancel refer to new invoice No. AC2204995 15/08/2022 \$261.00

Insured Veh. SMJ 4061R

Claim No.

Policy No.

Accident Date 04/06/2022

Inspection Date 08/06/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 08.06.2022 04.30pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2204995

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 15/08/2022
Reference CS3/GRB22005470/Gcy3e2-
'
Code GRB

PROFESSIONAL SERVICE FEE

Vehicle No. SLB 3503T
Insured Veh. SMJ 4061R
Claim No. MFL2022D0002944
Policy No. D21MFL0000447_01
Accident Date 04/06/2022
Inspection Date 08/06/2022

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
Merimen Fee	11.00
Note: Pls discard Inv.AC2203666 dated 14/06/2022 \$140.17	
Subtotal	261.00
GST (7%)	18.27
Grand Total	279.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM