

TOTAL

Veh No: SNF 8886K Yr Regn: 27/12/10
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA/
Make: MINI Cooper SHB C.C 1598
Colour: white / Black A/C: Insured / Std / NI / NA
Sp. Reading 144070 T/Radio: Insured / Std / NI / NA
Eng/No: WMWSV 32070TY 82269
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or affected
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 215/45R17
R:
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 6 Rear 6
R/Bal. mm R/Bal. mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 09/07/22 D.O.I. 13/7/22
Survey held at
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S frt
The U/C / Chassis frame / Body Structure affected due to collision.

Not Authorised

15 July 2022

13/7/22
2/5 \$3200 /
H days

REG NO.: SNF 8886 K
MAKE/MODEL: MINI COOPER S

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front bonnet	\$ 1,150.00 X
1	Front bonnet logo	\$ 90.00 X
1	Front fender -RH	\$ 535.00
1	Front fender inner shield	\$ 165.00
1	Front fender wheel arch garnish	\$ 220.00
1	Front wheel hub	\$ 245.00
1	Front wheel bearing	\$ 225.00
1	Front shock absorber	\$ 385.00
1	Front knuckle arm	\$ 498.00
1	Front lower arm	\$ 431.00 X
1	Front door	\$ 930.90 X
1	Front door rubber	\$ 145.00 X
		\$ 5,019.90
	Less 10%	\$ 501.99
		\$ 4,517.91

<u>SPECIAL NETT ITEMS</u>		
1	Front tyre	\$ 500.00 X
1	Front wheel rim	\$ 1,200.00 600
1	Front fender inner shield clip (1 set)	\$ 50.00 40
		\$ 1,750.00

S/N	LABOUR CHARGES	
1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	To remove and refit front undercarriage.	\$ 250.00 120
3	To conduct wheel alignment.	\$ 150.00 80
4	To apply undercoating.	\$ 150.00 30
5	Panel beating.	\$ 1,500.00 500
6	To re-spray painting on the affected areas.	\$ 1,400.00 600
		\$ 3,530.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1 of 1

\$ 9,797.91

2273
102
20457
640
1350
40357

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996

Fax : (65) 6384 1996

Hotline : (65) 9691 0887

Email: techneatcarcare@yahoo.com.sg

Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SNF 8886 K
Date: 13.7.22 17:37

MINI : R58 Coupe (2011 - 2015) : Series/Sport Suspension/JCW Series : with 17" Wheel

Front : Left

Actual	Before	Specified Range
-0°40'		-1°00' 0°00'
3°11'		
0°30'		0°00' 0°12'
10°40'		
9°59'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-4°20'		-1°00' 0°00'
3°11'		
-0°10'		0°00' 0°12'
16°47'		
12°27'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
3°40'		-0°20' 0°20'
0°00'		-0°30' 0°30'
-6°07'		
0°21'		0°00' 0°24'

Rear : Left

Actual	Before	Specified Range
-1°21'		-2°10' -1°20'
-1°05'		0°06' 0°18'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°31'		-2°10' -1°20'
1°08'		0°06' 0°18'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°10'		-0°30' 0°30'
0°03'		0°12' 0°36'
-1°06'		-0°12' 0°12'

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996

Fax : (65) 6384 1996

Hotline : (65) 9691 0887

Email: techneatcarcare@yahoo.com.sg

Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SNF 8886K
Date: 18.7.22 16:49

MINI : R58 Coupe (2011 - 2015) : Series/Sport Suspension/JCW Series : with 17" Wheel

Front : Left

Actual	Before	Specified Range
-0°51'	-1°02'	-1°00' 0°00'
3°05'	3°05'	
0°09'	-0°02'	0°00' 0°12'
10°01'	10°12'	
9°10'	9°10'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°04'	-0°05'	-1°00' 0°00'
3°14'	3°14'	
0°05'	0°11'	0°00' 0°12'
11°42'	11°43'	
11°39'	11°39'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°47'	-0°57'	-0°20' 0°20'
-0°09'	-0°09'	-0°30' 0°30'
-1°41'	-1°31'	
0°14'	0°09'	0°00' 0°24'

Rear : Left

Actual	Before	Specified Range
-1°24'	-1°35'	-2°10' -1°20'
-0°47'	-0°49'	0°06' 0°18'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°29'	-1°34'	-2°10' -1°20'
1°04'	1°05'	0°06' 0°18'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°05'	-0°01'	-0°30' 0°30'
0°17'	0°16'	0°12' 0°36'
-0°55'	-0°57'	-0°12' 0°12'