

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : XD7917D

Accident Date : 7/7/22

Location : AYE (TUAS) NEAR JURONG PORT ROAD

Model:

5 HINO FS1
29/10/2013-28/10/2023

3P:

YL58318 (ERGO)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	2pcs	Rear o/s & n/s tail lamp bracket / BT	160.40		
2	2pcs	Rear o/s & n/s tail lamp / OR	920.40		
3	2pcs	Rear o/s & n/s tail lamp reflector (white) / OR		300.00	
4	1 pc	Rear reg. no. plate / BT		45.00	
5	1 pc	Rear reg. no. plate bracket / BT		100.00	
6	2pcs	Rear reg. no. plate lamp X	240.20		
7	1 pc	Rear tail gate (chengal) / OR		2,800.00	
8	5 pcs	Rear tail gate hinges / BT		300.00	
9	1 pc	Rear LTA guard (Re Airp) / DD		2,200.00	
10	2pcs	Rear LTA guard bracket X		300.00	
11	1 pc	Rear LTA guard reflective sticker / NPL		100.00	
12	1 pc	Rear guard step / OR		600.00	
13	2pcs	Rear tail gate 60 KMPH emblem / NPL		30.00	
14	1 pc	Rear becareful of swinging sticker / NPL		50.00	
15	1 pc	Rear reverse camera X		500.00	
16	1 pc	Rear end panel X		1,500.00	
17	1 pc	Rear end panel reflective sticker / NPL		100.00	
18	1 pc	Rear o/s chassis frame X			
		Braking light (RH) / OR			
		Sub Total:	1,321.00	8,925.00	0.00
			10%	0%	0%
		After Less %:	1,188.90	8,925.00	0.00
		Labour			
1		To repair rear portion, straighten, welding rear damage parts & realign rear carriage	1,600.00	900	
2		To paint rear portion	800.00	500	
3		To remove and replace rear reverse camera	50.00	30	
4		To check for fault code and restting	280.00	30	
5		To check wiring	100.00	X	
6		To re seal anti rust	60.00	30	
		Sub Total:	2,890.00		
		Total:	13,003.90		
		After Less 20%:	10,403.12		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party liability is on a "Without Prejudice" basis
- No illegal trading, AAE M(M), MSAE(Aust)
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:



8778 1999
24 hr accident call



XD7917D ESTIMATEPg1