

ASS. REC. BY:

REF:

1051

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMV 8182T

Yr Regn:

01 / 16

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Voxel

c.c.

1496

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

109194

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RU3 1110853

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

8/7/22

D.O.I.

12/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

P. 15

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Date: 09/07/2022

Vehicle No: SMV8162T

Model: HONDA VEZEL HYBRID 1.5X

Chassis: RU31110853-2015

Reg. Year: 2016

Third Party Insurer: ECICS

Third Party Veh No: SMP5609Z

Date of Accident: 08/07/2022

Estimator: TING AN

Surveyor:

*Not with in
1/1 Day
Resurvey After Paint 6 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>By</i> \$635.00
2	REAR TAILGATE "VEZEL" EMBLEM	1		<i>Am</i> \$38.00
3	REAR TAILGATE "HYBRID" EMBLEM	1		<i>Am</i> \$38.00
4	REAR TAILGATE "HONDA" EMBLEM	1		<i>Am</i> \$18.00
5	REAR TAILGATE INNER TRIM BOARD	1		\$120.00
6	REAR TAILGATE INNER LOCK	1		<i>Am</i> \$65.00
7	REAR TAILGATE WEATHERSTRIP	1		<i>Am</i> \$50.00
8	REAR WINDSCREEN MOULDING	1		<i>Am</i> \$65.00
9	REAR TAILGATE LAMP LH	1		<i>Am</i> \$275.00
10	REAR TAILGATE LAMP RH	1		<i>Am</i> \$275.00
11	REAR TAIL LAMP LH	1		<i>Am</i> \$300.00
12	REAR TAIL LAMP RH	1		<i>Am</i> \$300.00
13	REAR BUMPER	1		<i>By</i> \$200.00
14	REAR SIDE BUMPER LH	1		<i>Am</i> \$80.00
15	REAR SIDE BUMPER RH	1		\$80.00
16	REAR BUMPER SIDE BRACKET LH	1		<i>Am</i> \$13.00
17	REAR BUMPER SIDE BRACKET RH	1		\$13.00
18	REAR BUMPER REFLECTOR LH	1		<i>Am</i> \$40.00
19	REAR BUMPER REFLECTOR RH	1		\$40.00
20	REAR BUMPER SMART BUZZER	1		\$50.00
21	REAR END PANEL	1		\$290.00
22	REAR END PANEL UPPER COVER	1		<i>CM</i> \$50.00
23	REAR FLOOR PANEL TOOLBOX TRAY	1		\$120.00
24	REAR FLOOR PANEL TOOLBOX TRAY UPPER BOARD	1		\$275.00
25	REAR FENDER WHEEL ARCH COVER LH	1		<i>Am</i> \$55.00
26	REAR FENDER WHEEL ARCH COVER RH	1		<i>Am</i> \$55.00

SUB TOTAL	\$3,540.00
COST +10%	\$354.00
PARTS TOTAL	\$3,894.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 150143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Authorized by Repairer

6A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Date:

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 09/07/2022
Vehicle No: SMV8162T
Model: HONDA VEZEL HYBRID 1.5X
Chassis: RU31110853-2015
Reg.Year: 2016

Third Party Insurer: ECICS
Third Party Veh No: SMP5609Z
Date of Accident:
Estimator: TING AN
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		na \$80.00
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		na \$50.00
3	REAR BUMPER CLIPS	1		na \$50.00
4	REAR BUMPER REVERSE SENSOR	1		na \$300.00
5	REAR BUMPER LOWER LIP	1		CR \$150.00
6	REAR END PANEL JOINT SEALANT	1		\$100.00
7	REAR END PANEL UPPER COVER CLIPS	1		na \$40.00
8	REAR EXHAUST TIP	1		\$250.00
9	REAR FENDER WHEEL ARCH CLIPS LH	1		na \$30.00
10	REAR FENDER WHEEL ARCH CLIPS RH	1		na \$30.00
S/N TOTAL				\$1,080.00

405a
X
2005a
7
7
X
✓

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

\$1,200.00 7

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR SIDE BUMPER LH, REAR SIDE BUMPER RH, REAR END PANEL & ETC.

\$1,200.00 800

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.

\$150.00 120

LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$120.00 60

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$100.00 50

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$120.00 7

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 09/07/2022
Vehicle No: SMV8162T
Model: HONDA VEZEL HYBRID 1.5X
Chassis: RU31110853-2015
Reg.Year: 2016

Third Party Insurer: ECICS
Third Party Veh No: SMP5609Z
Date of Accident:
Estimator: TING AN
Surveyor:

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$120.00 ?

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 20%

LABOUR TOTAL \$3,090.00

TING AN

TOTAL

\$8,064.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9819 | Fax: (+65) 6481 1093

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	09/07/2022 11:53 (SGT)
Reported by	Both
Date of Accident	08/07/2022 17:40 (SGT)
Exact Location of Accident	TPE, Singapore
Additional Location Information	TPE TOWARDS PUNGGOL
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMV8162T

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	MARK TEO WEI-JERN
NRIC No	SXXXX722Z
Email Address	mtwj.777@gmail.com
Mobile Phone No	(Phone) +65-97669717
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Vezel
Variant	VEZEL 1.5X HYBRID A
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496


INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10497875R00

DRIVER

Name of Driver	MARK TEO WEI-JERN
NRIC No	SXXXX722Z
Date Of Birth	07/08/1974
Occupation	Indoor

Date of accident: 8/7/2022 Time: 5:40PM Location: TPE towards Ponggol
My Vehicle A: SMV8162T Vehicle B: SMP5609Z Vehicle C: _____
SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

CAR B rear-ended into my car A on the right most lane of TPE on 8 July 2022 at around 5:40PM travelling in the direction of Ponggol.

While travelling at around 80km/h, I (CARA) saw the car in front of me braking and came to a stop, I followed by braking and stopping and was thus rear-ended by CAR B.

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :

Email address :

& myself :

Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

COMPLETED