



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22006592/Eqy3e2	
			Date: 14/07/2022	
			Code: SMR	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
Insured Veh.	SHB 1137C	Veh. Inspected	FBQ 7711Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	D22001961MFSH	Excess (\$)	0.00	
Assign From	Ashlene Lee	Assign Date	12/07/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA FS150F	c.c	149	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	PMKKC27A0KB212603	Colour	ORANGE	
Odometer	67048 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	70/80-19	DUNLOP	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90-19	DUNLOP	4 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.				
<b>5. General Information</b>				
Accident Date	23/06/2022	Inspection Date	12/07/2022	
Survey held at	RIGHT CLICK AUTOWORKS PTE LTD 7 SOON LEE STREET, #01-27, ISPACE, SINGAPORE 627608			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$8,000.00				