



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF22006598/Gqy3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1		Date:	16/08/2022
HEMMANT ROAD SINGAPORE 438675			
ATTN: HAFIZUL		Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SMJ 9857D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	HAFIZUL	Assign Date	12/07/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E250	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WDD2130452A591081	Colour	SILVER
Odometer	29605 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/40 R18	MICHELIN	6 mm
L/H Front Tyre	275/40 R18	MICHELIN	6 mm
R/H Rear Tyre	275/40 R18	MICHELIN	6 mm
L/H Rear Tyre	275/40 R18	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, N/S BODY AND ROOFTOP. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/07/2022	Inspection Date	20/07/2022
Survey held at	5 WIMBORNE ROAD 436631		
Repairer	JOO HAK KEE AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	