



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22006598/Gqy3e2
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)			Date:	16/08/2022
POLICE LOGISTICS BASE (PLB)				
1 HEMMANT ROAD SINGAPORE 438675			Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SMJ 9857D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	HAFIZUL	Assign Date	12/07/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/40 R18	MICHELIN	6 mm	
L/H Front Tyre	275/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	275/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	275/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION, N/S BODY AND ROOFTOP. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/07/2022	Inspection Date	20/07/2022	
Survey held at	5 WIMBORNE ROAD 436631			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				