



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22006599/Rqy3m4	
			Date: 20/10/2022	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YQ 5035G	Veh. Inspected	SLT 3986M
	Policy No.		Coverage (\$)	0.00
	Claim No.	M12D18622206	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	12/07/2022
2. Vehicle Particulars & Condition				
	Make & Model	B.M.W 216I GT LED	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WBA2D920405E91562	Colour	BLUE
	Odometer	89345 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R17	PIRELLI	6 mm
	L/H Front Tyre	205/55 R17	PIRELLI	6 mm
	R/H Rear Tyre	205/55 R17	PIRELLI	6 mm
	L/H Rear Tyre	205/55 R17	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/06/2022	Inspection Date	12/07/2022
	Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	