

(08/11/20) W91

ASS. REC. BY

REF:

CS/NOI 2200 6599/Rqy3

4562

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 3986M

at Workshop m/s AUTO INSURE

of 6, MARILYN LANE

Insured: NOI

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 96k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

REPORT LIMIT - 49k

Rasul finalised LS \$2500, 5 days. (Red \$5895.55, 70%)

Veh No: SLT 3986M Yr Regn: 2017 / OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 216GT LED C.C 1491

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 89345 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBA25920405691562

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R17  
R: \_\_\_\_\_BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 04/06/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 12/01/22

AUTO INSURE

Date/Time, File Pass to?

☐ : Prell. Report

1) 18/10 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format : TP

Lump Sum / H.B.I: (\$ 2500 )





**Auto Insure Pte. Ltd.**  
6 Marsiling Lane  
Singapore (739145)  
E: claims01@autoinsure.com.sg  
W: www.autoinsure.com.sg  
T: 3157 2626 F: 6368 0081  
**GST No.: 201437380M**

**Page No.1**

**AUTOMOBILE ASSESSMENT REPORT**

Our Ref: **SLT3986M (MARVYN)**

Your Ref: **YQ5035G**

Date: **12-Jul-22**

BY EMAIL ONLY  
(claims01@autoinsure.com.sg)

**ATTENTION: MOTOR CLAIMS DEPT**

**United Overseas Insurance Limited**

146 Robinson Road  
#02-01 UOI Building  
Singapore 068909

**Assessed Vehicle No** : **SLT3986M**  
**Car Make and Model** : **B.M.W. 216I GT LED**  
**Date of Accident** : **04-Jun-22**  
**Date of Assessment** : **12-Jul-22**

We have carried out a physical assessment of SLT3986M at our workshop Auto Insure Pte Ltd sustained damages to the RH REAR portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the RH REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : L/S  
Adjusted Amount : \$ **8,983.23**  
Est. Repair Days : **6**



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.  
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

**AUTO INSURE PTE. LTD.** For any reliance on this report by any third party.

Our Ref: SLT3986M

Your Ref: YQ5035G

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<b><u>PARTS REPLACEMENT - LIST ITEMS</u></b>				
1	1	REAR BUMPER <i>repair</i>		\$ 1,260.66
2	1	REAR BUMPER SIDE RETAINER RH <i>X</i>		\$ 196.26
3	1	REAR TAILLAMP RH <i>can</i>		\$ 458.40
4	1	REAR FENDER RH <i>bt</i>		\$ 1,795.26
5	1	REAR FENDER GLASS RH <i>3 sec photo</i>		\$ 366.72
6	1	REAR FENDER GLASS MOULDING RH		W/GLASS
7	1	REAR TAILGATE SPOILER <i>X</i>		\$ 908.88
8	1	REAR TAILGATE TRIM RH <i>X</i>		\$ 83.22
9	1	FUEL FILLER FLAP <i>repair</i>		\$ 82.42
10	1	REAR DOOR RH <i>X</i>		\$ 1,391.70
11	1	REAR DOOR REAR WINDOW FRAME TRIM RH <i>X</i>		\$ 167.58
			SUB TOTAL	\$ 6,711.10
			LESS 5%	\$ 335.56
			TOTAL AMOUNT	\$ 6,375.55

Our Ref: SLT3986M

Your Ref: YQ5035G

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR BUMPER CLIPS <i>X</i>		\$ 50.00
1	1	REAR FENDER GLASS SEALANT <i>X</i>		\$ 60.00
			SUB TOTAL	\$ 110.00
			TOTAL PARTS COST	\$ 6,485.55

Our Ref: **SLT3986M**

Your Ref: **YQ5035G**

S/NO	DESCRIPTION	EST. BY WORKSHOP
<b><u>LABOUR &amp; PAINTWORK</u></b>		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ <del>800.00</del> 500
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ <del>100.00</del> 30
4	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ <del>800.00</del> 400
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ <del>50.00</del> 30
6	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ <del>50.00</del> 20
7	TO VACUUM, WAXING & CLEAN	\$ 60.00 X
8	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ <del>50.00</del> 30
TOTAL BEFORE GST		\$ 8,395.55
GST 7%		\$ 587.69
TOTAL (PARTS & LABOUR):		\$ <b>8,983.23</b>

#### Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$ 8,900.00** for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng  
Claims Director

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Jason*  
*Hp 900 100 68*  
*5 days*  
*4/8*  
*12/07/22 @ 1700*  
*Reg after repair*



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 04/06/2022 14:55 (SGT)  
Date of Accident ..... 04/06/2022 11:40 (SGT)  
Exact Location of Accident ..... Bukit Panjang Ring Rd, Singapore  
Additional Location Information ..... -  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLT3986M

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... MOHAMAD FAIDZAL BIN MUSLIM  
NRIC No ..... SXXXX456Z  
Email Address ..... FAIDZALMUSLIM@GMAIL.COM  
Mobile Phone No ..... (Phone) +65-82184973  
Alternative Phone No ..... +65-82184973

### VEHICLE PARTICULARS

Manufacturer ..... BMW  
Model ..... 216i  
Variant ..... GT LED  
Exact purpose for which vehicle was being used at time of accident ..... -  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1499

### INSURANCE COMPANY

Name of Insurance Company ..... China Taiping Insurance (Singapore) Pte. Ltd.  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... DMPCSNW00175592100  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... MOHAMAD FAIDZAL BIN MUSLIM  
NRIC No ..... SXXXX456Z

Date Of Birth	11/06/1988
Occupation	Indoor
Date Of Driving Pass	17/12/2008
Driving experience	13 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-82184973
Alt. Phone Number	+65-82184973
Email Address	FAIDZALMUSLIM@GMAIL.COM
Address	APT BLK 404 BUKIT BATOK WEST AVENUE 7 #07-12
Address complement	-
Postcode	650404
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

ON 4/6/2022, AT ABOUT 1140. I WAS DRIVING ALONG BUKIT PANJANG RING ROAD. AS I WAS DRIVING STRAIGHT, A LORRY BEARING NUMBER YQ5035G CHANGED LANE FROM THE RIGHT LANE TO LEFT LANE. AT THE POINT, THE FRONT PORTION OF THE LORRY WAS ALREADY IN BETWEEN DRIVER AND PASSANGER DOOR. THE LORRY DID NOT STOP AND HIT ONTO THE REAR RIGHT OF MY VEHICLE.

#### ATTACHMENT(S)


Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YQ5035G
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	BHUIYAN ANIS
Passport No/FIN	GXXXX823U



SKETCH PLAN



A: SLT3986M  
B: YQ 5035G

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


ON 4/6/2022, AT ABOUT 1140. I WAS DRIVING ALONG BUKIT PANGSANG RING ROAD. AS I WAS driving straight, a lorry bearing registration number YQ 5035G changed lane from the right to left lane. At that point, the front portion of the lorry was already at the ~~acc~~ in between driver and passenger door.

The lorry did not stop and hit onto the rear right of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	456Z

### Vehicle Details

Vehicle No.:	SLT3986M
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jul 2022
Vehicle Make:	B.M.W.
Vehicle Model:	216i GT LED
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	33935105B38A15A
Chassis No.:	WBA2D920405E91562
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$28,741.00
Original Registration Date:	27 Oct 2017
First Registration Date:	27 Oct 2017
Transfer Count:	1
Actual ARF Paid:	\$32,238.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Oct 2027
PARF Rebate Amount:	\$24,178.00

### Intended COE Rebate Details

COE Expiry Date:	26 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,617.00
COE Rebate Amount:	\$22,005.00
<b>Total Rebate Amount:</b>	<b>\$46,183.00</b>

The information contained herein is correct as at 12 Jul 2022

OK



# BMW 2 Series 216i Gran Tourer

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

PURE MOTORS PTE LTD



Price	\$94,800		
Depreciation	\$15,320 /yr <a href="#">View models with similar depre</a>	Reg Date	15-Sep-2017 (5yrs 2mths 1day COE left)
Mileage	98,000 km (20.3k /yr)	Manufactured	2017
Road Tax	\$684 /yr	Transmission	Auto
Dereg Value	\$41,907 as of today ( <a href="#">change</a> )	OMV	\$27,881
COE	\$36,001	ARF	\$31,034
Engine Cap	1,499 cc	Power	75.0 kW (100 bhp)
Curb Weight	1,480 kg	No. of Owners	2